

Product Change Notification

PCN #: 4B-2022

DATE: 04/07/2022

1 PRODUCTS AFFECTED – TOP LEVEL PART NUMBERS (KITS)

Laird Part Number	Old Rev	New Rev	Description
WH-SSD50NBT	1.0	2.0	2X2 802.11 a/b/g/n with BT4.0 dual mode module.
WH-MSD50NBT	1.0	2.0	2X2 802.11 a/b/g/n with BT4.0 dual mode module
WH-M2SD50NBT	1.0	2.0	2X2 802.11 a/b/g/n with BT4.0 dual mode module. WLAN run at SDIO bus. BT run at UART/PCM
WB50NBT Series			
WH-WB50NBT	1.0	2.0	802.11a/b/g/n - BT 4.0 Communications Subsystem
453-00107	1.0	2.0	802.11a/b/g/n - BT 4.0 Communications Subsystem
453-00019	1.0	2.0	Module, 50 Series, WB50NBT, Laird, wb50n-laird-3.5.4.20
453-00023	1.0	2.0	Module, WB50NBT, Custom Firmware
453-00033	1.0	2.0	Module, 50 Series, WB50NBT, Laird, wb50n-laird-3.5.4.46
453-00034	4.0	5.0	Module, WB50NBT, Custom Firmware
453-00112	1.0	2.0	Module, 50 Series, WB50NBT, Laird, wb50n-laird-3.5.3.11

2 DESCRIPTION OF CHANGES

Model	Rev	Rev	Description
SSD50NBT	1.0	2.0	- RF-Shield: change from NIPPON STEEL ECOTRIO to Toyo Kohan Silver Top - PCB (material): from Hitachi Chemical MCL-E-75G to Panasonic R-1566 - Add UKCA logo due to Brexit
M2SD50NBT	1.0	2.0	SSD50NBT RF and PCB raw material change
MSD50NBT	1.0	2.0	SSD50NBT RF and PCB raw material change
WB50NBT	1.0	2.0	- SSD50NBT RF and PCB raw material change - Microchip from part number ATSAMA5D31A-CU to ATSAMA5D31A-CUR21

The information in this document is subject to change without notice.

3 REASON FOR CHANGE

- For the end of material production due to the business reorganization of the material manufacturers (NIPPON STEEL and Hitachi Chemical)
- Microchip ATSAMA5D31A-CUR21 fixes a chip errata present in ATSAMA5D31A-CU which has no functional impact on the processor

4 ANTICIPATED IMPACT OF THE CHANGE

- None. There is no impact on form, fit, or function.

5 METHOD OF IDENTIFYING THE CHANGED PRODUCT


SSD50NBT

- Add hardware version code Rev 2 to product label
- Add UKCA logo to meet UK regulatory requirement after Brexit



MSD50NBT

- Change hardware version code to Rev 2 on product label due to SSD50NBT change to Rev 2.0



The information in this document is subject to change without notice.

M2SD50NBT

- Change hardware version code to Rev 2 on product label due to SSD50NBT change to Rev 2.0

Before**After****WB50NBT**

- Change hardware version code to Rev 2 on product label due to SSD50NBT change to Rev 2.0

Before**After**

6 FACTORY EFFECTIVITY DATE

- Implementation about the end of Q2 or the beginning of Q3 2022

7 CONTACT INFORMATION:

Headquarters

Laird Connectivity
50 S Main St., Suite 1100
Akron, OH 44308 USA
Tel: 1(330) 434-7929
Fax: 1(330) 434-7931

PCN Contact

pcn@lairdconnect.com

Website

www.lairdconnect.com

Technical Support

support@lairdconnect.com

Sales Contact

sales@lairdconnect.com

The information in this document is subject to change without notice.

Product Change Notices (PCNs) will be distributed at the discretion of Laird Connectivity. Occasionally, Laird Connectivity may adjust product revision levels for internal tracking purposes only, and customers may not receive formal notifications associated with those revision changes.

The information in this document is subject to change without notice.