



Product Change Notification: SYST-28BFYR538

Date:

02-Feb-2026

Product Category:

32-Bit Microcontrollers

Notification Subject:

PIC32CM6408PL10028/32/48/64 Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-28BFYR538_Affected_CPN_02022026.pdf](#)

[SYST-28BFYR538_Affected_CPN_02022026.csv](#)

Notification Text:

SYST-28BFYR538

Microchip has released a new Document for the PIC32CM6408PL10028/32/48/64 Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC32CM6408PL10028/32/48/64 Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change:

Added Erratum for silicon Rev. A1:

- SUPC: SUPC Events Not Generated in Standby Sleep Mode

Added Data Sheet Clarification:

- Analog-to-Digital Converter: ADC - Analog-to-Digital Converter
- Electrical Characteristics: Electrical Characteristics @125°C

Impacts to Data Sheet: None

Change Implementation Status: Complete

Date Document Changes Effective: 02 February 2026

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

PIC32CM6408PL10028/32/48/64 Silicon Errata and Data Sheet Clarifications

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from