



Product Change Notification - SYST-02WVZI795

Date:

03 Jul 2019

Product Category:

Interface- Controller Area Network (CAN)

Affected CPNs:**Notification subject:**

ERRATA - MCP2517FD Silicon Errata and Data Sheet Clarification

Notification text:

SYST-02WVZI795

Microchip has released a new DeviceDoc for the MCP2517FD Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [MCP2517FD Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Updated Section 1. Module: SPI Module. 2) Updated Figure 1. 3) Added Section 2. Module: SPI Module: Incorrect CRC for certain READ_CRC commands.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 03 July 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[MCP2517FD Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MCP2517FD-H/JHA
MCP2517FD-H/JHAVAO
MCP2517FD-H/SL
MCP2517FD-H/SLVAO
MCP2517FDT-H/JHA
MCP2517FDT-H/JHAV02
MCP2517FDT-H/JHAVAO
MCP2517FDT-H/SL
MCP2517FDT-H/SLV01
MCP2517FDT-H/SLVAO