



Product Change Notification - SYST-28OJFH276

Date:

30 Aug 2019

Product Category:

Memory

Affected CPNs:**Notification subject:**

Data Sheet - AT25080B/AT25160B - Complete Datasheet Document Revision

Notification text:

SYST-28OJFH276

Microchip has released a new Product Documents for the AT25080B/AT25160B - Complete Datasheet of devices. If you are using one of these devices please read the document located at [AT25080B/AT25160B - Complete Datasheet](#).

Notification Status: Final**Description of Change:**

- 1) Updated to the Microchip template. Microchip DS20006244 replaces Atmel document 5228.
- 2) Updated Part Marking Information. Added ESD rating.
- 3) Removed the 8ball WLCSP detail and ordering code.
- 4) Removed lead finish designation.
- 5) Added POR recommendations section.
- 6) Updated trace code format in package markings.
- 7) Updated section content throughout for clarification.
- 8) Updated the 8U31 VFBGA package drawing.
- 9) Updated the SOIC, TSSOP and UDFN package drawings to the Microchip equivalents.

Impacts to Data Sheet: None**Reason for Change:** To Improve Manufacturability**Change Implementation Status:** Complete**Date Document Changes Effective:** 30 Aug 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A**Attachment(s):**

[AT25080B/AT25160B - Complete Datasheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and



make the applicable selections.

Affected Catalog Part Numbers (CPN)

AT25080B-WWU11L
AT25080B-WWU11LER
AT25080B-SSHL-B
AT25080B-SSHL-B-899
AT25080B-XHL-B
AT25080B-XHL-B-899
AT25080B-SSHL-T
AT25080B-SSHL-T-899
AT25080B-XHL-T
AT25080B-XHL-T-899
AT25080B-MEHL-T
AT25080B-CUL-T
AT25080B-MAHL-T
AT25080B-MAHL-T-899
AT25080B-MAHL-E
AT25160B-WWU11L
AT25160B-WWU11LER
AT25160B-WWU27LER
AT25160B-SSHL-B
AT25160B-SSHL-B-899
AT25160B-XHL-B
AT25160B-XHL-B-899
AT25160B-SSHL-T
AT25160B-SSHL-T-899
AT25160B-XHL-T
AT25160B-XHL-T-899
AT25160B-XHLHX-T
AT25160B-MEHL-T
AT25160B-CUL-T
AT25160B-MAHL-T
AT25160B-MAHL-T-899
AT25160B-MAHL-E