



Product Change Notification - SYST-31JDLV556

Date:

03 Jun 2019

Product Category:

Development Tools; USB Hubs

Affected CPNs:**Notification subject:**

ERRATA - USB2422 Silicon Errata and Data Sheet Clarification Errata Document Revision

Notification text:

SYST-31JDLV556

Microchip has released a new DeviceDoc for the USB2422 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [USB2422 Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Module 9: Added new errata module "Detach detection failure”; 2) Updated layout to standard Microchip format

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 03 Jun 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[USB2422 Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

EVB-USB2422

USB2422-I/MJ

USB2422/MJ

USB2422T-I/MJ

USB2422T/MJ