



Product Change Notification (PCN)

PCN Number	503118	Date Issued	September 12, 2017
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	November 14, 2017		
Sample Availability Date (Changed Part)	November 14, 2017		
Planned Implementation Date	February 06, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RFI EASFD

Before Change

- There will be a replacement mold for the NSCC Hybrid 3circuit 98821103x connector.



After Change

Overview

- To support customers' demand, we are planning to build a replacement mold due to existing mold is in bad condition.
- Product Impact
 - No impact to fit, form or function
- Part Number Impact
 - The PN is 988211030, 988211031, 988211035 and 988211039 to be produced out of the replacement mold
- PPAP and samples available upon request after





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:503118**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com