



# Product Change Notification (PCN)

PCN Number	505676	Date Issued	June 05, 2018
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	September 28, 2018		
Sample Availability Date (Changed Part)	September 28, 2018		
Planned Implementation Date	December 03, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

## Before Change

- There will be a replacement mold for the NSCC Hybrid 3circuit 98821103x connector.



## After Change

### Overview

- To support customers' demand, we are planning to build a new mold.
- Product Impact
  - No impact to fit, form or function
- Part Number Impact
  - The PN is 988211030, 988211031, 988211035 and 988211039 to be produced out of the replacement mold
- PPAP and samples available upon request after September 28, 2018





## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505676**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

988211030

988211031

988211035