



Product Change Notification (PCN)

PCN Number	506197	Date Issued	November 26, 2018
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	January 24, 2019		
Sample Availability Date (Changed Part)	January 24, 2019		
Planned Implementation Date	April 19, 2019		
Method of Identifying Change	Date code		

RELEASED

Before Change

- Change metal shell add dimple to shell soldering tail



No dimples on shell soldering tail



Add dimples to each of shell soldering tails

After Change

Overview

- 1051330001/0002/0102/1001 add dimples to each of shell soldering tails for improvement hold PCB retention force after IR reflow.
 - Product Impact
 - No change to fit and function, no impact to fit PCB layout Part Number Impact
- | |
|------------|
| 1051330001 |
| 1051330002 |
| 1051330102 |
| 1051331001 |
- Qualification data and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:506197**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com