




Product Change Notification

Date Issued :	May 08, 2025	PCN Number :	516889
Reason for Change :	Product Design Change with Obsolescence		
Description of Change :	This notification is to inform you about changes that are being made to the part(s) as identified in the list.		
Reason for Short Notice :	Corrective Actions		
Assessment of Change :	Reliability Test Report/s		
Planned Implementation Date :	September 30, 2025		
Customer Sample Availability Date:	April 30, 2025		
Last date to request Samples by Customer :	May 31, 2025		
Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.			
Recommended replacement parts :	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts :	July 01, 2025		
Last Time Ship Date for Obsolete Parts :	August 30, 2025		
Traceability Code Markings / Date :	New part number		

Before Picture

■ HFM cavity update on 10+1+1 and 10+2 male connectors



After Picture

Overview

- HFM cavity updates on 10+1+1 and 10+2 male connectors. Changes needed to improve terminal forward stop performance during HFM assembly.

- Part number changes to male connectors (fit / form / function change)
- Part Number Impact: See attached impacted parts list
- Qualification reports and samples available upon request

- Refer Replacement parts list for more details about LTB and LTS with respect to each parts impacted
- PCN will be implemented once all required qualification / validation has been completed, and all necessary approvals have been obtained.

RELEASED

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:516889 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 516889** " in the e-mail Subject line for faster response.