



## Customer Information Notification

202012003I

**Issue Date:** 20-Dec-2020

**Effective Date:** 21-Jan-2021

Dear *Product Data*,

Here's your personalized quality information concerning products Mouser Electronics purchased from Nexperia. For detailed information we invite you to [view this notification online](#)



### Change Category

- |  |   |  |   |   |
|--|---|--|---|---|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process   | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                         |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input checked="" type="checkbox"/> Errata              |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location  | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |

## Correction of Fall Time in BUK6Y33-60P Datasheet

### Information Notification

This notification is to inform our customers about a correction of the fall time (tf) information in the datasheet of the type BUK6Y33-60P.

Adobe will no longer be supporting Flash Player after 31 December 2020 and Adobe will block Flash content from running in Flash Player beginning 12 January 2021. Therefore it is not possible to access the Nexperia ePCN-tool anymore. Please use the below links to access related documentation to this change notification.

Existing data sheet:

[https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P\\_Datasheet\\_Existing.pdf](https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P_Datasheet_Existing.pdf)

New data sheet:

[https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P\\_Datasheet\\_New.pdf](https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P_Datasheet_New.pdf)

### Why do we issue this Information Notification

To have the correct value in the datasheet. An error (missing number) for the fall time (tf) of the BUK6Y33-60P was detected which has been corrected.

### Identification of Affected Products

Product identification does not change

### Impact

no impact to the product's functionality anticipated.

**Data Sheet Revision**

A new datasheet will be issued

**Disposition of Old Products**

Not applicable

**Additional information**

Additional documents: [view online](#)

**Remarks**

Existing and New datasheet included in CIN attached files

**Contact and Support**

For all inquiries regarding the ePCN tool application or access issues, please [contact Nexperia "Global Quality Support Team"](#).

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

<b>Name</b>	Diane Leigh
<b>Position</b>	PCN Officer
<b>e-mail address</b>	<a href="mailto:gcc.bgmos@nexperia.com">gcc.bgmos@nexperia.com</a>

At Nexperia B.V. we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

**About Nexperia B.V.**

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

---

Nexperia B.V.  
Jonkerbosplein 52 6534 AB Nijmegen, The Netherlands  
© 2017 Nexperia. All rights reserved.