

Date: September 27, 2016

PCN- 27785

Product Change Notification

Change Title:**REMOVE HOLE IN TERMINALS FOR RA*PC10* SERIES HIGH AMP POWER JACKS****Product (s) Affected:**RAPC10, RAPC10P, RAPC10PS, RAPC10S
RASPC10, RASPC10P, RASPC10PS, RASPC10S**Reason for Change:**

DISCOURAGE USE FOR LEAD WIRE ATTACH. THE TERMINALS CAN FATIGUE AND CRACK IF OVERMANIPULATED DURING WIRE ATTACH OR DUE TO MANIPULATION OR VIBRATION OF UNSUPPORTED WIRING. PARTS ARE SUPPORTED FOR PCB ASSEMBLY.

Description of Change:

REMOVE THE HOLES IN THE TERMINALS (SHUNT AND SLEEVE). A SMALL HOLE WILL REMAIN IN THE TIP TERMINAL, THE SAME AS THE STANDARD POWER JACK.

Estimated Schedule of Change:

IMMEDIATE - OCTOBER 1, 2016

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature _____

(Electronic Signature is acceptable)

Print _____

Company: _____

Location: _____

Title: _____

Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

jpulliam@switchcraft.com

FAX: 773-792-2129