



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# 20131024000
Carrier Tape Change for Select products in 6L DSBGA package
Information Only

Date: 10/28/2013
To: MOUSER PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services
Phone: +1(214) 480-6037
Fax: +1(214) 480-6659

20131024000
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
CSD25211W1015	null
CSD25301W1015	null
CSD25303W1015	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20131024000			PCN Date:	10/28/2013																		
Title:	Carrier Tape Change for Select products in 6L DSBGA package																						
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037		Dept:	Quality Services																	
Proposed 1st Ship Date:	10/28/2013		Estimated Sample Availability:		10/28/2013																		
Change Type:	<input checked="" type="checkbox"/> Packing/Shipping/Labeling																						
PCN Details																							
Description of Change:																							
<p>A new deep pocket designed carrier tape will be used for the listed devices below. Comparison between new and old carrier tape is as follows:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">From</th> <th style="text-align: center;">To</th> </tr> </thead> <tbody> <tr> <td>Stock #</td> <td style="text-align: center;">4156725-0193</td> <td style="text-align: center;">4156725-0181</td> </tr> <tr> <td>A_o (mm)</td> <td style="text-align: center;">1.09</td> <td style="text-align: center;">1.18</td> </tr> <tr> <td>B_o (mm)</td> <td style="text-align: center;">1.56</td> <td style="text-align: center;">1.68</td> </tr> <tr> <td>K_o (mmm)</td> <td style="text-align: center;">0.65</td> <td style="text-align: center;">0.83</td> </tr> <tr> <td>Drawing</td> <td style="text-align: center;"> </td> <td style="text-align: center;"> </td> </tr> </tbody> </table>							From	To	Stock #	4156725-0193	4156725-0181	A_o (mm)	1.09	1.18	B_o (mm)	1.56	1.68	K_o (mmm)	0.65	0.83	Drawing		
	From	To																					
Stock #	4156725-0193	4156725-0181																					
A_o (mm)	1.09	1.18																					
B_o (mm)	1.56	1.68																					
K_o (mmm)	0.65	0.83																					
Drawing																							

Reason for Change:					
Quality improvement to address "sticky die"					
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):					
None					
Changes to product identification resulting from this PCN:					
Reel dimension changes as described above					
Product Affected:					
CSD25211W1015	CSD25303W1015	CSD75203W1015	HPA00738W1015		
CSD25301W1015	CSD58874W1015				

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com