



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

**PCN# 20150413000
Pin 1 Indicator marking change for 1x1mm X2SON
(DQN, DPF) package devices
Information Only**

Date: 5/4/2015
To: MOUSER PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

20150413000
Attachment: 1


Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
LP5907SNX-1.2/NOPB	null
LP5907SNX-1.8/NOPB	null
LP5907SNX-2.8/NOPB	null
LP5907SNX-2.85/NOPB	null
LP5907SNX-3.0/NOPB	null
LP5907SNX-3.1/NOPB	null
LP5907SNX-3.3/NOPB	null
TLV3691IDPFT	null
TLV70712PDQNR	null
TLV707185DQNR	null
TLV70718DQNR	null
TLV70718DQNT	null
TLV70718PDQNR	null
TLV70718PDQNT	null
TLV70725DQNR	null
TLV70725DQNT	null
TLV70725PDQNT	null
TLV707285PDQNR	null
TLV70728PDQNR	null
TLV70728PDQNT	null
TLV70730DQNT	null
TLV70730PDQNR	null
TLV70733DQNR	null
TLV70733DQNT	null
TLV70733PDQNR	null
TLV70733PDQNT	null
TLV70734DQNT	null
TLV70736PDQNR	null
TLV71310PDQNR	null
TLV71310PDQNT	null
TLV71312PDQNT	null
TLV71318PDQNR	null
TLV71318PDQNT	null
TLV71320DQNR	null
TLV71325PDQNR	null
TLV71325PDQNT	null
TLV71328PDQNR	null
TLV71330PDQNR	null
TLV71333PDQNR	null
TLV71712PDQNR	null
TLV71712PDQNT	null
TLV71713PDQNT	null
TLV71715PDQNT	null
TLV71718PDQNR	null
TLV71718PDQNT	null
TLV71721PDQNR	null
TLV71725PDQNR	null
TLV71725PDQNT	null
TLV71727PDQNR	null
TLV717285PDQNT	null

TLV71728PDQNR	null
TLV71728PDQNT	null
TLV71729PDQNR	null
TLV71730PDQNR	null
TLV71730PDQNT	null
TLV71733PDQNR	null
TLV71733PDQNT	null
TLV71736PDQNT	null
TLV73310PDQNT	null
TLV73311PDQNT	null
TLV73312PDQNT	null
TLV73315PDQNT	null
TLV73318PDQNT	null
TLV73325PDQNT	null
TLV73333PDQNT	null
TPD5E003DPFR	null
TPS3831G33DQNT	null
TPS3831K33DQNR	null
TPS3831K33DQNT	null
TPS3839A09DQNT	null
TPS3839E16DQNT	null
TPS3839G12DQNT	null
TPS3839G18DQNT	null
TPS3839G33DQNR	null
TPS3839K50DQNR	null
TPS3839L30DQNR	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20150413000		PCN Date:	05/04/2015
Title:	Pin 1 Indicator marking change for 1x1mm X2SON (DQN, DPF) package devices			
Customer Contact:	PCN_ww_admin_team@list.ti.com		Dept:	Quality Services
Change Type:	Device Marking			
☐	Assembly Site	☐	Design	☐
☒	Assembly Process	☐	Data Sheet	☐
☐	Assembly Materials	☐	Part number change	☐
☐	Mechanical Specification	☐	Test Site	☐
☐	Packing/Shipping/Labeling	☐	Test Process	☐
				☐
				Wafer Bump Site
				Wafer Bump Material
				Wafer Bump Process
				Wafer Fab Site
				Wafer Fab Materials
				Wafer Fab Process
PCN Details				
Description of Change:				
Informational notification to announce pin 1 indicator marking change for 1x1mm X2SON (DQN, DPF) package devices. Sample Device Marking: Change From: * * H C * * O 1st/2nd DIGIT = DEVICE CODE * * = BINARY DATECODE PER TI DRAWING O = Pin 1 Change To: * * H C * * X 1st/2nd DIGIT = DEVICE CODE * * = BINARY DATECODE PER TI DRAWING X = PIN 1 (MARKED) ┐ = 1st Quarter of the year └ = 2nd Quarter of the year ┌ = 3rd Quarter of the year └ = 4th Quarter of the year Sample Marking: 				
Reason for Change:				
Standardize pin 1 indicator marking format for 1x1mm X2SON (DQN, DPF) package devices				
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):				

None			
Changes to product identification resulting from this PCN:			
See reference picture above.			
Product Affected:			
LP5907SNX-1.2/NOPB	TLV70718DQNR	TLV71315PDQNT	TLV71733PDQNT
LP5907SNX-1.8/NOPB	TLV70718DQNT	TLV713185PDQNR	TLV71734PDQNR
LP5907SNX-2.2/NOPB	TLV70718PDQNR	TLV713185PDQNT	TLV71734PDQNT
LP5907SNX-2.5/NOPB	TLV70718PDQNT	TLV71318PDQNR	TLV71736PDQNR
LP5907SNX-2.7/NOPB	TLV70719DQNR	TLV71318PDQNT	TLV71736PDQNT
LP5907SNX-2.8/NOPB	TLV70719DQNT	TLV71320DQNR	TLV71750DQNR
LP5907SNX-2.85/NOPB	TLV70719PDQNR	TLV71320DQNT	TLV71750DQNT
LP5907SNX-2.9/NOPB	TLV70719PDQNT	TLV71325PDQNR	TLV71750PDQNR
LP5907SNX-3.0/NOPB	TLV70725DQNR	TLV71325PDQNT	TLV71750PDQNT
LP5907SNX-3.1/NOPB	TLV70725DQNT	TLV713285PDQNR	TLV73310PDQNR
LP5907SNX-3.2/NOPB	TLV70725PDQNR	TLV713285PDQNT	TLV73310PDQNT
LP5907SNX-3.3/NOPB	TLV70725PDQNT	TLV71328PDQNR	TLV73311PDQNR
LP5907SNX-4.0/NOPB	TLV70726DQNR	TLV71328PDQNT	TLV73311PDQNT
LP5907SNX-4.5/NOPB	TLV70726DQNT	TLV71330PDQNR	TLV73312PDQNR
P5907SNX-2.5	TLV70726PDQNR	TLV71330PDQNT	TLV73312PDQNT
P5907SNX29	TLV70726PDQNT	TLV71333PDQNR	TLV73315PDQNR
P5907SNX40	TLV707285DQNR	TLV71333PDQNT	TLV73315PDQNT
SN1112023PDQNR	TLV707285DQNT	TLV71712PDQNR	TLV73318PDQNR
SN1205002PDQNR	TLV707285PDQNR	TLV71712PDQNR1	TLV73318PDQNT
SN1205066PDQNR	TLV707285PDQNT	TLV71712PDQNR3	TLV73325PDQNR
SN1206013PDQNR	TLV70728PDQNR	TLV71712PDQNT	TLV73325PDQNT
SN1311021PDQNR	TLV70728PDQNT	TLV71713PDQNR	TLV73333PDQNR
SN1406032PDQNR	TLV70729DQNR	TLV71713PDQNT	TLV73333PDQNT
TLV3691IDPFR	TLV70729DQNT	TLV71715PDQNR	TPD5E003DPFR
TLV3691IDPFT	TLV70729PDQNR	TLV71715PDQNT	TPS3831A09DQNR
TLV707085DQNR	TLV70729PDQNT	TLV717185PDQNR	TPS3831A09DQNT
TLV707085DQNT	TLV70730DQNR	TLV717185PDQNT	TPS3831E16DQNR
TLV707085PDQNR	TLV70730DQNT	TLV71718PDQNR	TPS3831E16DQNT
TLV707085PDQNT	TLV70730PDQNR	TLV71718PDQNT	TPS3831G12DQNR
TLV70710DQNR	TLV70730PDQNT	TLV71719PDQNR	TPS3831G12DQNT
TLV70710DQNT	TLV70731DQNR	TLV71719PDQNT	TPS3831G18DQNR
TLV70710PDQNR	TLV70731DQNT	TLV71721PDQNR	TPS3831G18DQNT
TLV70710PDQNT	TLV70732DQNR	TLV71721PDQNT	TPS3831G33DQNR
TLV707115DQNR	TLV70732DQNT	TLV71725PDQNR	TPS3831G33DQNT
TLV707115DQNT	TLV707335DQNR	TLV71725PDQNT	TPS3831K33DQNR

TLV70711PDQNR	TLV707335DQNT	TLV71727PDQNR	TPS3831K33DQNT
TLV70711PDQNT	TLV707335PDQNR	TLV71727PDQNT	TPS3831K50DQNR
TLV70712DQNR	TLV707335PDQNT	TLV717285DQNR	TPS3831K50DQNT
TLV70712DQNT	TLV70733DQNR	TLV717285DQNT	TPS3831L30DQNR
TLV70712PDQNR	TLV70733DQNR1	TLV717285PDQNR	TPS3831L30DQNT
TLV70712PDQNT	TLV70733DQNT	TLV717285PDQNT	TPS3839A09DQNR
TLV70713DQNR	TLV70733PDQNR	TLV71728DQNR	TPS3839A09DQNT
TLV70713DQNT	TLV70733PDQNT	TLV71728DQNT	TPS3839E16DQNR
TLV70713PDQNR	TLV70734DQNR	TLV71728PDQNR	TPS3839E16DQNT
TLV70713PDQNT	TLV70734DQNT	TLV71728PDQNR1	TPS3839G12DQNR
TLV70715DQNR	TLV70734PDQNR	TLV71728PDQNR3	TPS3839G12DQNT
TLV70715DQNT	TLV70734PDQNT	TLV71728PDQNT	TPS3839G18DQNR
TLV70715PDQNR	TLV70736DQNR	TLV71729PDQNR	TPS3839G18DQNT
TLV70715PDQNT	TLV70736DQNT	TLV71729PDQNT	TPS3839G25DQNR
TLV70717DQNR	TLV70736PDQNR	TLV71730DQNR	TPS3839G25DQNT
TLV70717DQNT	TLV70736PDQNT	TLV71730DQNT	TPS3839G33DQNR
TLV70717PDQNR	TLV71310PDQNR	TLV71730PDQNR	TPS3839G33DQNT
TLV70717PDQNT	TLV71310PDQNT	TLV71730PDQNT	TPS3839K33DQNR
TLV707185DQNR	TLV71311PDQNR	TLV71731PDQNR	TPS3839K33DQNT
TLV707185DQNR1	TLV71311PDQNT	TLV71731PDQNT	TPS3839K50DQNR
TLV707185DQNT	TLV71312PDQNR	TLV71733DQNR	TPS3839K50DQNT
TLV707185PDQNR	TLV71312PDQNT	TLV71733DQNT	TPS3839L30DQNR
TLV707185PDQNT	TLV71315PDQNR	TLV71733PDQNR	TPS3839L30DQNT

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com