

9/5/2025

Mouser Electronics, Inc.

Re: Incorrect marking

Dear

This letter is in regards to TPS62966RPYR (the "Product"). The Product topside marking on shipments from batch #4418357CDA with lot trace code 3047568RFB are incorrect. Datasheet topside marking (T62966), marking on material in this shipment (T62964). This issue is not expected to have an adverse impact on the quality or reliability of the Product. TI's standard warranty and other applicable terms apply (see www.ti.com/termsofsale).

If you have any questions or concerns, please contact me at sr-mvb-mktg@list.ti.com.

Sincerely,

Switching Regulators Product Line
Texas Instruments Incorporated