



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20180110002
Datasheet for LP2950-N, LP2951-N
Information Only

Date: January 19, 2018
To: MOUSER PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services


Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
LP2951ACM	null
LP2951ACM-3.0/NOPB	null
LP2951ACM-3.3/NOPB	null
LP2951ACM/NOPB	null
LP2951ACMM-3.0/NOPB	null
LP2951ACMM-3.3/NOPB	null
LP2951ACMM/NOPB	null
LP2951ACMMX-3.0/NOPB	null
LP2951ACMMX-3.3/NOPB	null
LP2951ACMX-3.0/NOPB	null
LP2951ACMX-3.3/NOPB	null
LP2951ACMX/NOPB	null
LP2951ACN/NOPB	null
LP2951ACSD/NOPB	null
LP2951ACSDX-3.3/NOPB	null
LP2951ACSDX/NOPB	null
LP2951CM-3.0/NOPB	null
LP2951CM-3.3/NOPB	null
LP2951CM/NOPB	null
LP2951CMM-3.0/NOPB	null
LP2951CMM-3.3/NOPB	null
LP2951CMM/NOPB	null
LP2951CMMX-3.0/NOPB	null
LP2951CMMX-3.3/NOPB	null
LP2951CMMX/NOPB	null
LP2951CMX	null
LP2951CMX-3.0/NOPB	null
LP2951CMX-3.3/NOPB	null
LP2951CMX/NOPB	null
LP2951CN/NOPB	null
LP2951CSD-3.0/NOPB	null
LP2951CSD-3.3/NOPB	null
LP2951CSD/NOPB	null
LP2951CSDX-3.3/NOPB	null
LP2951CSDX/NOPB	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20180110002	PCN Date:	January 18, 2018
Title:	Datasheet for LP2950-N, LP2951-N		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.			
		LP2950-N, LP2951-N <small>SNVS764Q – JANUARY 2000 – REVISED DECEMBER 2017</small>	
Changes from Revision P (May 2016) to Revision Q			Page
<ul style="list-style-type: none"> Changed LP2951-N ESD parameter pin references and added SENSE pin row to LP2951-N ESD parameter in <i>ESD Ratings</i> table..... 			5
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
LP2950-N, LP2951-N	SNVS764P	SNVS764Q	
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/LP2950-N			
Reason for Change:			
To accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
LP2951ACM	LP2951ACMMX-3.3/NOPB	LP2951CM-3.3	LP2951CMX-3.0/NOPB
LP2951ACM-3.0/NOPB	LP2951ACMMX/NOPB	LP2951CM-3.3/NOPB	LP2951CMX-3.3
LP2951ACM-3.3	LP2951ACMX	LP2951CM/NOPB	LP2951CMX-3.3/NOPB
LP2951ACM-3.3/NOPB	LP2951ACMX-3.0/NOPB	LP2951CMM	LP2951CMX/NOPB
LP2951ACM/NOPB	LP2951ACMX-3.3/NOPB	LP2951CMM-3.0/NOPB	LP2951CN/NOPB
LP2951ACMM	LP2951ACMX/NOPB	LP2951CMM-3.3/NOPB	LP2951CSD-3.0/NOPB
LP2951ACMM-3.0	LP2951ACN/NOPB	LP2951CMM/NOPB	LP2951CSD-3.3/NOPB
LP2951ACMM-3.0/NOPB	LP2951ACSD	LP2951CMMX	LP2951CSD/NOPB
LP2951ACMM-3.3	LP2951ACSD/NOPB	LP2951CMMX-3.0/NOPB	LP2951CSDX-3.0/NOPB
LP2951ACMM-3.3/NOPB	LP2951ACSDX-3.3/NOPB	LP2951CMMX-3.3	LP2951CSDX-3.3/NOPB
LP2951ACMM/NOPB	LP2951ACSDX/NOPB	LP2951CMMX-3.3/NOPB	LP2951CSDX/NOPB
LP2951ACMMX-3.0	LP2951CM	LP2951CMMX/NOPB	
LP2951ACMMX-3.0/NOPB	LP2951CM-3.0/NOPB	LP2951CMX	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com