



**12500 TI Boulevard, MS 8640, Dallas, Texas 75243**

**PCN#20220930001.0**  
**SOT Symbolization update for select devices – 16 Additional Binary Codes**  
**Information Only**

**Date:** October 03, 2022  
**To:** MOUSER PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Team ([PCN\\_ww\\_admin\\_team@list.ti.com](mailto:PCN_ww_admin_team@list.ti.com)).

Sincerely,

PCN Team  
SC Business Services

**20220930001.0**  
**Attachment: 1**

**Products Affected:**

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months (60 months for automotive devices). The corresponding customer part number is also listed, if available.

| <b>DEVICE</b>      | <b>CUSTOMER PART NUMBER</b> |
|--------------------|-----------------------------|
| LM321MF/NOPB       | null                        |
| LM321MFX/NOPB      | null                        |
| LMC7101AIM5/NOPB   | null                        |
| LMC7101AIM5X/NOPB  | null                        |
| LMC7101BIM5/NOPB   | null                        |
| LMC7101BIM5X/NOPB  | null                        |
| LMV321IDBVR        | null                        |
| LMV321IDBVT        | null                        |
| LP2985IM5-5.0/NOPB | null                        |
| LP5907MFX-1.2/NOPB | null                        |
| LP5907MFX-1.5/NOPB | null                        |
| LP5907MFX-1.8/NOPB | null                        |
| LP5907MFX-2.5/NOPB | null                        |
| LP5907MFX-2.8/NOPB | null                        |
| LP5907MFX-2.9/NOPB | null                        |
| LP5907MFX-3.0/NOPB | null                        |
| LP5907MFX-3.1/NOPB | null                        |
| LP5907MFX-3.2/NOPB | null                        |
| LP5907MFX-3.3/NOPB | null                        |
| LP5907MFX-4.5/NOPB | null                        |
| SN74AVC1T45DRLR    | null                        |
| SN74LVC1G3157DBVR  | null                        |
| SN74LVC1T45DRLR    | null                        |
| TL331IDBVR         | null                        |
| TL331IDBVRG4       | null                        |
| TL331IDBVT         | null                        |
| TL331IDBVTG4       | null                        |
| TL331KDBVR         | null                        |
| TL331KDBVT         | null                        |
| TLV2241IDBVR       | null                        |
| TLV2241IDBVT       | null                        |
| TLV2401CDBVR       | null                        |
| TLV2401CDBVT       | null                        |
| TLV2401IDBVR       | null                        |
| TLV2401IDBVT       | null                        |
| TLV3401CDBVT       | null                        |
| TLV3401IDBVR       | null                        |
| TLV3401IDBVT       | null                        |
| TLV6001IDBVR       | null                        |
| TLV6001IDBVT       | null                        |
| TLV6001UIDBVR      | null                        |
| TLV6001UIDBVT      | null                        |
| TLV62565DBVR       | null                        |
| TLV62565DBVT       | null                        |
| TLV62566DBVR       | null                        |
| TLV62566DBVT       | null                        |
| TLV62568ADRLR      | null                        |
| TLV62568ADRLT      | null                        |
| TLV62568APDRLR     | null                        |
| TLV62568APDRLT     | null                        |
| TLV62568DBVR       | null                        |
| TLV62568DRLR       | null                        |
| TLV62568DRLT       | null                        |
| TLV62568PDDCR      | null                        |
| TLV62568PDDCT      | null                        |
| TLV62568PDRLR      | null                        |

|                  |      |
|------------------|------|
| TLV62568PDRLT    | null |
| TLV62569ADRLR    | null |
| TLV62569ADRLT    | null |
| TLV62569APDRLR   | null |
| TLV62569APDRLT   | null |
| TLV62569DBVR     | null |
| TLV62569DRLR     | null |
| TLV62569PDDCR    | null |
| TLV62569PDDCT    | null |
| TLV62569PDRLR    | null |
| TLV62569PDRLT    | null |
| TLV62585DRLR     | null |
| TLV62585DRLT     | null |
| TLV62585PDRLR    | null |
| TLV62585PDRLT    | null |
| TLV70212DBVR     | null |
| TLV70212DBVT     | null |
| TLV70215DBVR     | null |
| TLV70215DBVT     | null |
| TLV70218DBVR     | null |
| TLV70218DBVT     | null |
| TLV70225DBVR     | null |
| TLV70225DBVT     | null |
| TLV70228DBVR     | null |
| TLV70228DBVT     | null |
| TLV70233DBVR     | null |
| TLV70233DBVT     | null |
| TLV70433DBVR     | null |
| TLV70433DBVT     | null |
| TLV70436DBVR     | null |
| TLV75509PDBVR    | null |
| TLV75510PDBVR    | null |
| TLV75512PDBVR    | null |
| TLV75515PDBVR    | null |
| TLV75518PDBVR    | null |
| TLV75519PDBVR    | null |
| TLV75525PDBVR    | null |
| TLV75528PDBVR    | null |
| TLV75529PDBVR    | null |
| TLV75530PDBVR    | null |
| TLV75533PDBVR    | null |
| TLV75709PDBVR    | null |
| TLV75710PDBVR    | null |
| TLV75712PDBVR    | null |
| TLV75715PDBVR    | null |
| TLV75718PDBVR    | null |
| TLV75719PDBVR    | null |
| TLV75725PDBVR    | null |
| TLV75728PDBVR    | null |
| TLV75729PDBVR    | null |
| TLV75730PDBVR    | null |
| TLV75733PDBVR    | null |
| TLV803EA22DBZR   | null |
| TLV803EA26DBZR   | null |
| TLV803EA29DBZR   | null |
| TLV803EB29DBZR   | null |
| TLV803RDBZR      | null |
| TLV803SDBZR      | null |
| TLV803ZDBZR      | null |
| TLV809EA26DBZR   | null |
| TLV809EA29DBZR   | null |
| TLV840CADL11DBVR | null |
| TLV840CADL14DBVR | null |
| TLV840CADL28DBVR | null |
| TLV840CADL29DBVR | null |
| TLV840CADL40DBVR | null |
| TLV840MADL08DBVR | null |
| TLV840MADL10DBVR | null |
| TLV840MADL13DBVR | null |
| TLV840MADL29DBVR | null |

|                   |      |
|-------------------|------|
| TLV840MADL30DBVR  | null |
| TLV840MADL52DBVR  | null |
| TLV840NADH29DBVR  | null |
| TLV840NADL20DBVR  | null |
| TLV840NADL33DBVR  | null |
| TLV840NADL35DBVR  | null |
| TLV840NADL46DBVR  | null |
| TLV840NAPL50DBVR  | null |
| TLV9352IDDFR      | null |
| TMP102AIDRLR      | null |
| TMP102AIDRLT      | null |
| TMP112AIDRLR      | null |
| TMP112AIDRLT      | null |
| TMP302ADRLR       | null |
| TMP302ADRLT       | null |
| TMP302BDRLR       | null |
| TMP302BDRLT       | null |
| TMP302CDRLR       | null |
| TMP302CDRLT       | null |
| TMP302DDRLR       | null |
| TMP302DDRLT       | null |
| TMUX1308DYYR      | null |
| TPS2041CDBVR      | null |
| TPS2041CDBVT      | null |
| TPS2051BDBVR      | null |
| TPS2051BDBVT      | null |
| TPS2051CDBVR      | null |
| TPS2051CDBVT      | null |
| TPS2061CDBVR      | null |
| TPS2061CDBVT      | null |
| TPS2065CDBVR      | null |
| TPS2065CDBVR-2    | null |
| TPS2065CDBVT      | null |
| TPS2065CDBVT-2    | null |
| TPS2069CDBVR      | null |
| TPS2069CDBVT      | null |
| TPS22918DBVR      | null |
| TPS22918DBVT      | null |
| TPS2513DBVR       | null |
| TPS2513DBVT       | null |
| TPS2514DBVR       | null |
| TPS25221DBVR      | null |
| TPS25221DBVT      | null |
| TPS2552DBVR       | null |
| TPS2552DBVT       | null |
| TPS2553DBVR       | null |
| TPS2553DBVR-1     | null |
| TPS2553DBVT       | null |
| TPS2553DBVT-1     | null |
| TPS3808G01DBVR    | null |
| TPS3808G01DBVT    | null |
| TPS3808G09DBVR    | null |
| TPS3808G09DBVT    | null |
| TPS3808G18DBVR    | null |
| TPS3808G18DBVT    | null |
| TPS3808G30DBVR    | null |
| TPS3808G30DBVT    | null |
| TPS3813I50QDBVRQ1 | null |
| TPS3813K33QDBVRQ1 | null |
| TPS3840DL16DBVR   | null |
| TPS3840DL17DBVR   | null |
| TPS3840DL18DBVR   | null |
| TPS3840DL19DBVR   | null |
| TPS3840DL20DBVR   | null |
| TPS3840DL22DBVR   | null |
| TPS3840DL24DBVR   | null |
| TPS3840DL25DBVR   | null |
| TPS3840DL27DBVR   | null |
| TPS3840DL28DBVR   | null |
| TPS3840DL29DBVR   | null |

|                 |      |
|-----------------|------|
| TPS3840DL30DBVR | null |
| TPS3840DL31DBVR | null |
| TPS3840DL35DBVR | null |
| TPS3840DL40DBVR | null |
| TPS3840DL42DBVR | null |
| TPS3840DL44DBVR | null |
| TPS3840DL45DBVR | null |
| TPS3840DL46DBVR | null |
| TPS3840DL49DBVR | null |
| TPS3840PH18DBVR | null |
| TPS3840PH19DBVR | null |
| TPS3840PH27DBVR | null |
| TPS3840PH30DBVR | null |
| TPS3840PH40DBVR | null |
| TPS3840PH45DBVR | null |
| TPS3840PH49DBVR | null |
| TPS3840PL16DBVR | null |
| TPS3840PL18DBVR | null |
| TPS3840PL20DBVR | null |
| TPS3840PL25DBVR | null |
| TPS3840PL26DBVR | null |
| TPS3840PL27DBVR | null |
| TPS3840PL28DBVR | null |
| TPS3840PL29DBVR | null |
| TPS3840PL30DBVR | null |
| TPS3840PL34DBVR | null |
| TPS3840PL42DBVR | null |
| TPS3840PL43DBVR | null |
| TPS3840PL45DBVR | null |
| TPS3840PL48DBVR | null |
| TPS562201DDCR   | null |
| TPS562201DDCT   | null |
| TPS562202DRLR   | null |
| TPS562207DRLR   | null |
| TPS562208DDCR   | null |
| TPS562208DDCT   | null |
| TPS562231DRLR   | null |
| TPS562231DRLT   | null |
| TPS563201DDCR   | null |
| TPS563201DDCT   | null |
| TPS563202DRLR   | null |
| TPS563207DRLR   | null |
| TPS563208DDCR   | null |
| TPS563208DDCT   | null |
| TPS563231DRLR   | null |
| TPS563231DRLT   | null |
| TPS563249DDCR   | null |
| TPS563249DDCT   | null |
| TPS76138DBVR    | null |
| TPS76150DBVR    | null |
| TPS76150DBVT    | null |
| TPS76333DBVR    | null |
| TPS76433DBVR    | null |
| TPS76912DBVR    | null |
| TPS76933DBVR    | null |
| TPS76933DBVT    | null |
| TPS77025DBVR    | null |
| TPS77025DBVT    | null |
| TPS78833DBVR    | null |
| TPS78833DBVT    | null |
| TPS79333DBVR    | null |
| TPS7A0212PDBVR  | null |
| TPS7A0215PDBVR  | null |
| TPS7A0218PDBVR  | null |
| TPS7A0220PDBVR  | null |
| TPS7A0222PDBVR  | null |
| TPS7A0223PDBVR  | null |
| TPS7A0225PDBVR  | null |
| TPS7A0228PDBVR  | null |
| TPS7A0230PDBVR  | null |

|                  |      |
|------------------|------|
| TPS7A0233PDBVR   | null |
| TPS7A0236PDBVR   | null |
| TPS7A0312PDBVR   | null |
| TPS7A0315PDBVR   | null |
| TPS7A0318PDBVR   | null |
| TPS7A0320PDBVR   | null |
| TPS7A0322PDBVR   | null |
| TPS7A0323PDBVR   | null |
| TPS7A0325PDBVR   | null |
| TPS7A0328PDBVR   | null |
| TPS7A0330PDBVR   | null |
| TPS7A0331PDBVR   | null |
| TPS7A0333PDBVR   | null |
| TPS7A0336PDBVR   | null |
| TPS7A2009PDBVR   | null |
| TPS7A2012PDBVR   | null |
| TPS7A2015PDBVR   | null |
| TPS7A20185PDBVR  | null |
| TPS7A2018PDBVR   | null |
| TPS7A2024PDBVR   | null |
| TPS7A2025PDBVR   | null |
| TPS7A20285PDBVR  | null |
| TPS7A2028PDBVR   | null |
| TPS7A2030PDBVR   | null |
| TPS7A2031PDBVR   | null |
| TPS7A2032PDBVR   | null |
| TPS7A2033PDBVR   | null |
| TPS7A2036PDBVR   | null |
| TPS7A2042PDBVR   | null |
| TPS7A2045PDBVR   | null |
| TPS7A2050PDBVR   | null |
| TPS7A2055PDBVR   | null |
| TPS7A2401DBVR    | null |
| TPS7A24125DBVR   | null |
| TPS7A2418DBVR    | null |
| TPS7A2425DBVR    | null |
| TPS7A2430DBVR    | null |
| TPS7A2433DBVR    | null |
| TPS7A2436DBVR    | null |
| TPS7A2450DBVR    | null |
| TS5A3159DBVR     | null |
| UCC27517ADBVR    | null |
| UCC27517ADBVT    | null |
| UCC27517AQDBVRQ1 | null |
| UCC27517DBVR     | null |
| UCC27517DBVT     | null |

Technical details of this Product Change follow on the next page(s).

|                                          |                                                                          |                                                   |                  |
|------------------------------------------|--------------------------------------------------------------------------|---------------------------------------------------|------------------|
| <b>PCN Number:</b>                       | 20220930001.0                                                            | <b>PCN Date:</b>                                  | October 03, 2022 |
| <b>Title:</b>                            | SOT Symbolization update for select devices – 16 Additional Binary Codes |                                                   |                  |
| <b>Customer Contact:</b>                 | <a href="#">PCN Manager</a>                                              | <b>Dept:</b>                                      | Quality Services |
| <b>Change Type:</b>                      |                                                                          |                                                   |                  |
| <input type="checkbox"/> Assembly Site   | <input type="checkbox"/> Assembly Process                                | <input type="checkbox"/> Assembly Materials       |                  |
| <input type="checkbox"/> Design          | <input type="checkbox"/> Datasheet                                       | <input type="checkbox"/> Mechanical Specification |                  |
| <input type="checkbox"/> Test Site       | <input checked="" type="checkbox"/> Packing/Shipping/Labeling            | <input type="checkbox"/> Test Process             |                  |
| <input type="checkbox"/> Wafer Bump Site | <input type="checkbox"/> Wafer Bump Material                             | <input type="checkbox"/> Wafer Bump Process       |                  |
| <input type="checkbox"/> Wafer Fab Site  | <input type="checkbox"/> Wafer Fab Materials                             | <input type="checkbox"/> Wafer Fab Process        |                  |
|                                          | <input type="checkbox"/> Part number change                              |                                                   |                  |

## PCN Details

### Description of Change:

This letter is to inform customers of a device symbolization change for select devices in the SOT package that will enable enhanced device level traceability. The symbolization will maintain current Year/Month binary codes and add 4 additional binary codes (i.e. X1, X2, X3, and X4) for enhanced lot traceability as follows:

| What                | Current                                                                                                                                                                                     | New                                                                                                                                                                                                                                                                                         |
|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Binary Codes</b> | 8                                                                                                                                                                                           | 24                                                                                                                                                                                                                                                                                          |
| <b>Illustration</b> | <p>The diagram shows a 4x4 grid of squares. The top row is labeled 'YEAR BINARY CODE' and the bottom row is labeled 'MONTH BINARY CODE'. The middle two rows each contain four squares.</p> | <p>The diagram shows a 4x4 grid of squares. The top row is labeled 'X1' and 'X2'. The bottom row is labeled 'X3' and 'X4'. The middle two rows each contain four squares. The rightmost square in the top row is labeled 'Y' and the rightmost square in the bottom row is labeled 'M'.</p> |

### Reason for Change:

Improved Device traceability

### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

### Changes to product identification resulting from this PCN:

Added device symbolization row

### Product Affected:

|                   |              |              |               |  |
|-------------------|--------------|--------------|---------------|--|
| LM321MF/NOPB      | TLV70212DBVT | TPS2051BDBVR | TPS562208DDCT |  |
| LM321MFX/NOPB     | TLV70215DBVR | TPS2051BDBVT | TPS562231DRLR |  |
| LMC7101AIM5/NOPB  | TLV70215DBVT | TPS2051CDBVR | TPS562231DRLT |  |
| LMC7101AIM5X/NOPB | TLV70218DBVR | TPS2051CDBVT | TPS563201DDCR |  |
| LMC7101BIM5/NOPB  | TLV70218DBVT | TPS2061CDBVR | TPS563201DDCT |  |
| LMC7101BIM5X/NOPB | TLV70225DBVR | TPS2061CDBVT | TPS563202DRLR |  |
| LMV321IDBVR       | TLV70225DBVT | TPS2065CDBVR | TPS563207DRLR |  |

|                    |                  |                   |                |  |
|--------------------|------------------|-------------------|----------------|--|
| LMV321IDBVT        | TLV70228DBVR     | TPS2065CDBVR-2    | TPS563208DDCR  |  |
| LP2985IM5-5.0/NOPB | TLV70228DBVT     | TPS2065CDBVT      | TPS563208DDCT  |  |
| LP5907MFX-1.2/NOPB | TLV70233DBVR     | TPS2065CDBVT-2    | TPS563231DRLR  |  |
| LP5907MFX-1.5/NOPB | TLV70233DBVT     | TPS2069CDBVR      | TPS563231DRLT  |  |
| LP5907MFX-1.8/NOPB | TLV70433DBVR     | TPS2069CDBVT      | TPS563249DDCR  |  |
| LP5907MFX-2.5/NOPB | TLV70433DBVT     | TPS22918DBVR      | TPS563249DDCT  |  |
| LP5907MFX-2.8/NOPB | TLV70436DBVR     | TPS22918DBVT      | TPS76138DBVR   |  |
| LP5907MFX-2.9/NOPB | TLV75506PDBVR    | TPS2513DBVR       | TPS76138DBVT   |  |
| LP5907MFX-3.0/NOPB | TLV75509PDBVR    | TPS2513DBVT       | TPS76150DBVR   |  |
| LP5907MFX-3.1/NOPB | TLV75510PDBVR    | TPS2514DBVR       | TPS76150DBVT   |  |
| LP5907MFX-3.2/NOPB | TLV75512PDBVR    | TPS25221DBVR      | TPS76333DBVR   |  |
| LP5907MFX-3.3/NOPB | TLV75515PDBVR    | TPS25221DBVT      | TPS76433DBVR   |  |
| LP5907MFX-4.5/NOPB | TLV75518PDBVR    | TPS2552DBVR       | TPS76912DBVR   |  |
| SN1608035DRLR      | TLV75519PDBVR    | TPS2552DBVT       | TPS76933DBVR   |  |
| SN1710027DRLR      | TLV75525PDBVR    | TPS2553DBVR       | TPS76933DBVT   |  |
| SN1710027DRLT      | TLV75528PDBVR    | TPS2553DBVR-1     | TPS77025DBVR   |  |
| SN562231DRLR       | TLV75529PDBVR    | TPS2553DBVT       | TPS77025DBVT   |  |
| SN562231DRLT       | TLV75530PDBVR    | TPS2553DBVT-1     | TPS78833DBVR   |  |
| SN562249DDCR       | TLV75533PDBVR    | TPS3808G01DBVR    | TPS78833DBVT   |  |
| SN562249DDCT       | TLV75550PDBVR    | TPS3808G01DBVT    | TPS79333DBVR   |  |
| SN563249DDCR       | TLV75706PDBVR    | TPS3808G09DBVR    | TPS7A0212PDBVR |  |
| SN563249DDCT       | TLV75709PDBVR    | TPS3808G09DBVT    | TPS7A0215PDBVR |  |
| SN74AVC1T45DRLR    | TLV75710PDBVR    | TPS3808G18DBVR    | TPS7A0218PDBVR |  |
| SN74LVC1G3157DBVR  | TLV75712PDBVR    | TPS3808G18DBVT    | TPS7A0220PDBVR |  |
| SN74LVC1T45DRLR    | TLV75715PDBVR    | TPS3808G30DBVR    | TPS7A0222PDBVR |  |
| TL331IDBVR         | TLV75718PDBVR    | TPS3808G30DBVT    | TPS7A0223PDBVR |  |
| TL331IDBVRG4       | TLV75719PDBVR    | TPS3813I50QDBVRQ1 | TPS7A0225PDBVR |  |
| TL331IDBVT         | TLV75725PDBVR    | TPS3813K33QDBVRAL | TPS7A0228PDBVR |  |
| TL331IDBVTG4       | TLV75728PDBVR    | TPS3813K33QDBVRQ1 | TPS7A0230PDBVR |  |
| TL331KDBVR         | TLV75729PDBVR    | TPS3840DL16DBVR   | TPS7A0233PDBVR |  |
| TL331KDBVT         | TLV75730PDBVR    | TPS3840DL17DBVR   | TPS7A0236PDBVR |  |
| TLV2241IDBVR       | TLV75733PDBVR    | TPS3840DL18DBVR   | TPS7A0312PDBVR |  |
| TLV2241IDBVT       | TLV75750PDBVR    | TPS3840DL19DBVR   | TPS7A0315PDBVR |  |
| TLV2401CDBVR       | TLV803EA22DBZR   | TPS3840DL20DBVR   | TPS7A0318PDBVR |  |
| TLV2401CDBVT       | TLV803EA26DBZR   | TPS3840DL22DBVR   | TPS7A0320PDBVR |  |
| TLV2401IDBVR       | TLV803EA29DBZR   | TPS3840DL24DBVR   | TPS7A0322PDBVR |  |
| TLV2401IDBVT       | TLV803EB29DBZR   | TPS3840DL25DBVR   | TPS7A0323PDBVR |  |
| TLV3401CDBVR       | TLV803RDBZR      | TPS3840DL27DBVR   | TPS7A0325PDBVR |  |
| TLV3401CDBVT       | TLV803SDBZR      | TPS3840DL28DBVR   | TPS7A0328PDBVR |  |
| TLV3401IDBVR       | TLV803ZDBZR      | TPS3840DL29DBVR   | TPS7A0330PDBVR |  |
| TLV3401IDBVT       | TLV809EA26DBZR   | TPS3840DL30DBVR   | TPS7A0331PDBVR |  |
| TLV6001IDBVR       | TLV809EA29DBZR   | TPS3840DL31DBVR   | TPS7A0333PDBVR |  |
| TLV6001IDBVT       | TLV840CADL11DBVR | TPS3840DL35DBVR   | TPS7A0336PDBVR |  |
| TLV6001UIDBVR      | TLV840CADL14DBVR | TPS3840DL40DBVR   | TPS7A2009PDBVR |  |
| TLV6001UIDBVT      | TLV840CADL28DBVR | TPS3840DL42DBVR   | TPS7A2012PDBVR |  |

|                |                  |                 |                  |  |
|----------------|------------------|-----------------|------------------|--|
| TLV62565DBVR   | TLV840CADL29DBVR | TPS3840DL44DBVR | TPS7A2015PDBVR   |  |
| TLV62565DBVT   | TLV840CADL40DBVR | TPS3840DL45DBVR | TPS7A20185PDBVR  |  |
| TLV62566DBVR   | TLV840MADL08DBVR | TPS3840DL46DBVR | TPS7A2018PDBVR   |  |
| TLV62566DBVT   | TLV840MADL10DBVR | TPS3840DL49DBVR | TPS7A2024PDBVR   |  |
| TLV62568ADRLR  | TLV840MADL13DBVR | TPS3840PH18DBVR | TPS7A2025PDBVR   |  |
| TLV62568ADRLT  | TLV840MADL29DBVR | TPS3840PH19DBVR | TPS7A20285PDBVR  |  |
| TLV62568APDRLR | TLV840MADL30DBVR | TPS3840PH27DBVR | TPS7A2028PDBVR   |  |
| TLV62568APDRLT | TLV840MADL52DBVR | TPS3840PH30DBVR | TPS7A2030PDBVR   |  |
| TLV62568DBVR   | TLV840NADH29DBVR | TPS3840PH40DBVR | TPS7A2031PDBVR   |  |
| TLV62568DRLR   | TLV840NADL20DBVR | TPS3840PH45DBVR | TPS7A2032PDBVR   |  |
| TLV62568DRLT   | TLV840NADL33DBVR | TPS3840PH49DBVR | TPS7A2033PDBVR   |  |
| TLV62568PDDCR  | TLV840NADL35DBVR | TPS3840PL16DBVR | TPS7A2036PDBVR   |  |
| TLV62568PDDCT  | TLV840NADL46DBVR | TPS3840PL18DBVR | TPS7A2042PDBVR   |  |
| TLV62568PDRLR  | TLV840NAPL50DBVR | TPS3840PL20DBVR | TPS7A2045PDBVR   |  |
| TLV62568PDRLT  | TLV9352IDDFR     | TPS3840PL25DBVR | TPS7A2050PDBVR   |  |
| TLV62569ADRLR  | TMP102AIDRLR     | TPS3840PL26DBVR | TPS7A2055PDBVR   |  |
| TLV62569ADRLT  | TMP102AIDRLT     | TPS3840PL27DBVR | TPS7A2401DBVR    |  |
| TLV62569APDRLR | TMP112AIDRLR     | TPS3840PL28DBVR | TPS7A24125DBVR   |  |
| TLV62569APDRLT | TMP112AIDRLT     | TPS3840PL29DBVR | TPS7A2418DBVR    |  |
| TLV62569DBVR   | TMP302ADRLR      | TPS3840PL30DBVR | TPS7A2425DBVR    |  |
| TLV62569DRLR   | TMP302ADRLT      | TPS3840PL34DBVR | TPS7A2430DBVR    |  |
| TLV62569DRLT   | TMP302BDRLR      | TPS3840PL42DBVR | TPS7A2433DBVR    |  |
| TLV62569PDDCR  | TMP302BDRLT      | TPS3840PL43DBVR | TPS7A2436DBVR    |  |
| TLV62569PDDCT  | TMP302CDRLR      | TPS3840PL45DBVR | TPS7A2450DBVR    |  |
| TLV62569PDRLR  | TMP302CDRLT      | TPS3840PL48DBVR | TS5A3159DBVR     |  |
| TLV62569PDRLT  | TMP302DDRLR      | TPS562201DDCR   | UCC27517ADBVR    |  |
| TLV62585DRLR   | TMP302DDRLT      | TPS562201DDCT   | UCC27517ADBVT    |  |
| TLV62585DRLT   | TMUX1308DYR      | TPS562202DRLR   | UCC27517AQDBVRQ1 |  |
| TLV62585PDRLR  | TPS2041CDBVR     | TPS562207DRLR   | UCC27517DBVR     |  |
| TLV62585PDRLT  | TPS2041CDBVT     | TPS562208DDCR   | UCC27517DBVT     |  |
| TLV70212DBVR   |                  |                 |                  |  |

For questions regarding this notice, e-mails can be sent to the contacts shown below or your local Field Sales Representative.

| Location                  | E-Mail                                                                           |
|---------------------------|----------------------------------------------------------------------------------|
| WW Change Management Team | <a href="mailto:PCN_ww_admin_team@list.ti.com">PCN_ww_admin_team@list.ti.com</a> |

## **IMPORTANT NOTICE AND DISCLAIMER**

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale ([www.ti.com/legal/termsofsale.html](http://www.ti.com/legal/termsofsale.html)) or other applicable terms available either on [ti.com](http://ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.