

Title of Change:	FUSB251UCX New Carrier Tape Design Qualification
Effective date:	24 Oct 2022
Contact information:	Contact your local onsemi Sales Office or Michelle.Lyn.Alaba@onsemi.com
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
Change Category:	Assembly Change
Change Sub-Category(s):	Material Change

Sites Affected:

onsemi Sites	External Foundry/Subcon Sites
onsemi Cebu, Philippines	None

Description and Purpose:

Qualification of New Carrier Tape Design for FUSB251UCX WLSCP Device

There are no product material changes as a result of this change.

There is no product marking change as a result of this change.

New carrier tape design with Corner relief for FUSB251UCX WLCSP Device with changes comparison as below:

FROM: No Corner Relief



TO: With Corner Relief



Carrier Tape	Details	Chipping All Side Inspection	Remarks	Result
New Carrier Tape with Corner Relief	Reel Form; 1 meter	0/100	No chipping anomaly found	Passed
	Reel Form; 1.5 meter	0/100	No chipping anomaly found	Passed
	Reel Form; 2 meters	0/100	No chipping anomaly found	Passed
	Intermediate Box; 1 meter	0/100	No chipping anomaly found	Passed
	Intermediate Box; 1.5 meter	0/100	No chipping anomaly found	Passed
	Intermediate Box; 2 meters	0/100	No chipping anomaly found	Passed
	Shipping Box; 1 meter	0/100	No chipping anomaly found	Passed
	Shipping Box; 1.5 meter	0/100	No chipping anomaly found	Passed
	Shipping Box; 2 meters	0/100	No chipping anomaly found	Passed

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

FUSB251UCX		
------------	--	--