

Title of Change:	Correct the front side marking in datasheet of OPN FGHL40T120SWD
Effective date:	27 Dec 2024
Contact information:	Contact your local onsemi Sales Office
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
Change Category:	Datasheet/Product Document change
Change Sub-Category(s):	Datasheet/Product Document change


Sites Affected:

onsemi Sites	External Foundry/Subcon Sites
None	None

Description and Purpose:

onsemi is updating the datasheet for FGHL40T120SWD to correct the part marking to align with actual part marking on the device. Part marking on the device itself will not change. This is a datasheet update only.

There is no change of the front side marking on physical unit.

	Before Change	After Change
Physical marking	No change	No change
Marking diagram in Datasheet	MARKING DIAGRAM  \$Y = onsemi Logo &Z = Assembly Plant Code &3 = 3-Digit Date Code &K = 2-Digit Lot Traceability Code FGHL40T120SWD = Specific Device Code	MARKING DIAGRAM  \$Y = onsemi Logo &Z = Assembly Plant Code &3 = 3-Digit Date Code &K = 2-Digit Lot Traceability Code FGHL40T120SWD = Specific Device Code

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

FGHL40T120SWD		
---------------	--	--