



Product Change Notification / SYST-23VXCC518

Date:

24-Nov-2020

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16(L)F15325/45 Family Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-23VXCC518_Affected_CPN_11242020.pdf](#)

[SYST-23VXCC518_Affected_CPN_11242020.csv](#)

Notification Text:

SYST-23VXCC518

Microchip has released a new Product Documents for the PIC16(L)F15325/45 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC16\(L\)F15325/45 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Updated Table 2 and Section 5.3 Minimum VDD Specification for LF Devices 2) Added Table 37-1 and Section 5.4 ADC Offset Error.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 24 Nov 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC16\(L\)F15325/45 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.