

## Product Change Notification - SYST-21FEWW605

---

**Date:**

22 Apr 2020

**Product Category:**

32-bit Microcontrollers

**Affected CPNs:****Notification subject:**

ERRATA - PIC32MX1XX/2XX 28/44-pin XLP Family Errata

**Notification text:**

SYST-21FEWW605

Microchip has released a new Product Documents for the PIC32MX1XX/2XX 28/44-pin XLP Family Errata of devices. If you are using one of these devices please read the document located at [PIC32MX1XX/2XX 28/44-pin XLP Family Errata](#).

**Notification Status:** Final

**Description of Change:** Added Silicon Issue 53. USB Low-Speed Mode.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 22 Apr 2020

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):**

[PIC32MX1XX/2XX 28/44-pin XLP Family Errata](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.