



Product Change Notification / SYST-20SPBK308

Date:

22-Jun-2023

Product Category:

Ethernet PHYs

PCN Type:

Document Change

Notification Subject:

ERRATA - LAN8670/2 10BASE-T1S Ethernet PHY Transceiver Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-20SPBK308_Affected_CPN_06222023.pdf](#)

[SYST-20SPBK308_Affected_CPN_06222023.csv](#)

Notification Text:

SYST-20SPBK308

Microchip has released a new Errata for the LAN8670/2 10BASE-T1S Ethernet PHY Transceiver Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [LAN8670/2 10BASE-T1S Ethernet PHY Transceiver Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change:

Updated for Rev C1 Silicon
Data Sheet Clarifications resolved

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 21 Jun 2023

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices::N/A

Attachments:

[LAN8670/2 10BASE-T1S Ethernet PHY Transceiver Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.