



Product Change Notification / SYST-22KOVA405

Date:

23-Sep-2022

Product Category:

32-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-22KOVA405_Affected_CPN_09232022.pdf](#)
[SYST-22KOVA405_Affected_CPN_09232022.csv](#)

Notification Text:

SYST-22KOVA405

Microchip has released a new Errata for the PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change:

Added the following new errata: • EVSYS: 2.6.3 Synchronous/Resynchronized Modes • TCC: 2.16.6 DMA One-Shot Trigger Mode Updated Table 3. PIC32CM LS60 Family Silicon Device Identification

Impacts to Data Sheet: None

Change Implementation Status: Complete

Date Document Changes Effective: 23 Sep 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC32CM LE00/LS00/LS60 Family Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.