

10/31/2024

Re: Incorrect Symbolization of the Product

Dear Mouser:

This letter is in regards to TPD1E10B06DPYR (the "Product"). The Product may have symbolization as A5, B1, BI, B2, or B6. Furthermore, the device may have pin one indicator as a line or a dot. Shipping boxes and shipping labels were not affected by this issue.. This issue is not expected to have an adverse impact on the quality or reliability of the Product. TI's standard warranty and other applicable terms apply (see www.ti.com/termsofsale).

If you have any questions or concerns, please contact me at m-eaker1@ti.com.

Sincerely,

McKenzie Eaker
Applications Engineer
Texas Instruments Incorporated