

Product Change Notice

Date:	September 5, 2019
Overview:	Ordering part number change for select 6" AC fans and accessories
Reason for Change:	Part number consolidation
Affected Part No(s):	Listed on page 2 of this PCN
Design Change Detail:	• Select 6" AC fans and their corresponding accessories were manufactured by both <i>ebm</i> and <i>Papst</i> (when the two were separate companies / competitors) under different part numbers (PNs); when <i>ebm</i> acquired <i>Papst</i>, these fans therefore overlapped • Over time, the location of manufacture was consolidated by the newly created <i>ebm-papst</i>; however, product could still be ordered under both PNs and both PNs appeared on the labels • To eliminate redundancy, we have deactivated the <i>Papst</i> PNs so all product can only be ordered under the <i>ebm</i> PNs • Both PNs still appear on the label for traceability
Effective Date	Immediately
Last Time Buy Deadline:	N/A
Pricing:	No change to <i>ebm</i> PN pricing / <i>Papst</i> PNs no longer orderable
ebm-papst employee:	Jeannine Zenobi
Attachments:	N/A
Comments:	N/A

Current Ordering PN ("ebm" PN)	Equivalent "Papst" PN – Deactivated*
W2E142-BB01-01	7056 ES
W2S130-BM03-01	7450 ES
W2S130-AA03-97	7855 ES
W2E143-AB09-01	6078 ES
W2S130AA03C4	7856 ES-012
W2S130-AA03-97	7856 ES
W2S130-AA25-97	7806 ES
W2E142-BB05-01	7006 ES
09576-2-4013	LZ1000-175
W2S130-BM15-01	7400 ES
W2S130-AA25-01	7805 ES
09569-2-4013	LZ1000-160
W2E143-AA15-01	6008 ES
W2E143-AA09-01	6058 ES
W2E143-AB15-01	6028 ES
09566-2-4013	LZ1000-133
22550-2-2929	LZ 48-1
22050-2-2929	LZ 47-1
96358-2-4013	LZ1000-225
96120-2-4013	LZ1000-120
09563-2-4013	LZ1000-097

* No longer used for ordering, still referenced on product label

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing