

SYMBOL DEFINITION		
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL □ DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	27
	LAST NO. USED	24

DATE				REVISED				REVISION HISTORY				AUTH		DR		APPROVED	
02AP02				R				01				223146		FR0		AK	
16AP02				R				01				223929		RAB		RAB	
25JN10				R				01				411214		LHT		LHT	
07JL10				R				01				411317		JEB		EFJ	

