

SYMBOL DEFINITION										MISSING SYMBOLS										ZONE										REVISION HISTORY										AUTH		DR		AP/OP/D		1		2																											
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.										TOTAL NO OF INSPECTIONS REQUIRED										23										NO MISSING SYMBOL NUMBER										DATE										STG		REV		N/P		CHG		AUTH										DR		AP/OP/D		1		2	
																																								31MR06										R		A3		-		-		REDRAWN TO PD										278855							
										06JUN06										R		A4		-		-		ADDED DIM NUMBER 17 AND PROCESS SENSITIVE DIM WAS 1										281239										MM		JAS																									
										26JUL06										R		A5		-		-		66.21 +0.34/-0.15 WAS 66.21 +/-0.15										283079										MDH		AUG		EST																							
LAST NO. USED										17																																																																	

