

Double-Data-Rate Octal SPI PSRAM

Specifications

- Single Supply Voltage
 - o VDD=1.62 to 1.98V
 - VDDQ=1.62 to 1.98V
- Interface: Octal SPI with DDR Xccela mode, two bytes transfers per one clock cycle
- Performance: Clock rate up to 200MHz, 400MB/s read/write throughput
- Organization: 64Mb, 8M x 8bits with 1024 bytes page size
 - o Column address: AYO to AY9
 - o Row address: AX0 to AX12
- Refresh: Self-managed
- Operating Temperature Range
 - o Tc = -40°C to +85°C(standard range)
 - Tc= -40°C to +105°C (extended range)
- Maximum Standby Current
 - o 300μA @ 105°C
 - o 200μA @ 85°C
 - o 100μA @ 25°C
 - \circ 30μA @ 25°C (Half Sleep Mode with data retained)

Features

- Low Power Features
 - o Partial Array Self-Refresh (PASR)
 - Auto Temperature Compensated Self-Refresh (ATCSR) by built-in temperature sensor
 - o User configurable refresh rate
 - Ultra Low Power (ULP) Half Sleep mode with data retained
- Software Reset
- Reset Pin Available
- Output driver LVCMOS with programmable drive strength
- Data Mask (DM) for write data
- Data Strobe (DQS) enabled highspeed read operation
- Register Configurable write and read initial latencies
- Write Burst Length, maximum 1024 bytes, minimum 2 bytes.
- Wrap & Hybrid Burst in 16/32/64/1K lengths.
- Linear Burst Command
- Row Boundary Crossing (RBX)
 - read operations can be enabled via Mode Register.
 - o RBX Write is NOT supported.



Table of Contents

1 Table of Contents


1	Tab	le of Contents	2
2	Pac	kage Information	3
3	Pac	kage Outline Drawing	4
4	Ord	lering Information	5
5	Sign	nal Table	6
6	Pow	ver-Up Initialization	7
	6.1	Power-Up Initialization Method 1 (via. RESET# pin)	7
	6.2	Power-Up Initialization Method 2 (via. Global Reset)	8
7	Inte	erface Description	9
	7.1	Address Space	9
	7.2	Burst Type & Length	9
	7.3	Command/Address Latching	9 <u>3</u>
	7.4	Command Truth Table	9
	7.5	Read Operation	10
	7.6	Write Operation	13
	7.7	Control Registers	14
	7.8	Half Sleep Mode	20
	7.9	Deep Power Down Mode	21
8	Elec	ctrical Specifications:	22
	8.1	Absolute Maximum Ratings	22
	8.2	Pin Capacitance	22
	8.3	Decoupling Capacitor Requirement	23
	8.4	Operating Conditions	23
	8.5	DC Characteristics	24
	8.6	ISB Partial Array Refresh Current	25
	8.7	AC Characteristics	26
۵	Cha	nga log	28



2 Package Information

The APS6408L-OBMx is available in miniBGA 24L package $6 \times 8 \times 1.2$ mm, ball pitch 1.0mm,ball size 0.4mm, package code "BA".

Ball Assignment for MINIBGA 24L




(6x8x1.2mm)(P1.0)(B0.4)


Note:

- 1. Part Number APS6408L-OBM-BA for 64Mb.
- 2. RFU: Reserved for future use, which is reserved for 2nd CE#.
- 3. NC: No internal connection.



3 Package Outline Drawing








SYM.	DIMENSION (mm)				
SYM.	MIN.	NOM.	MAX.		
Α	-	-	1.20		
A1	0.25	0.30	0.35		
A2	1	-			
b	0.35 0.40		0.45		
D	7.90	8.00	8.10		
D1	4.00 BSC				
E	5.90 6.00 6.10				
E1	4.00 BSC				
SE	1.	.00 TYP			
SD	1.00 TYP				
e	1.00 BSC				

NOTE:

- 1. CONTROLLING DIMENSION : MILLIMETER.
- 2. REFERENCE DOCUMENT : JEDEC MO-207.
- 3. THE DIAMETER OF PRE-REFLOW SOLDER BALL IS Ø0.40mm.(0.35mm SMO)










4 Ordering Information

Table 1: Ordering Information

Part Number	Temperature Range	Max Frequency	Note
APS6408L-OBM	Tj= -40°C to +85°C	200 MHz	Bare die, SIP
APS6408L-OBMX	Tj= -40°C to +105°C	200 MHz	Bare die, SIP
APS6408L-OBM-BA	Tc= -40°C to +85°C	200 MHz	24b Package
APS6408L-OBMX-BA	Tc= -40°C to +105°C	200 MHz	24b Package

Note

• OBM is standard part to support RBX read operation only.





5 Signal Table

All signals are listed in Table 2.

Table 2: Signals Table

Symbol	Туре	Description	Comments
V _{DD}	Power	Core supply 1.8V	
V_{DDQ}	Power	IO supply 1.8V	
V _{SS}	Ground	Core supply ground	
V _{SSQ}	Ground	IO supply ground	
A/DQ[7:0]	Ю	Address/DQ bus [7:0]	
DQS/DM	Ю	DQ strobe clock during reads, Data mask during writes. DM is	
		active high. DM=1 means "do not write".	
CE#	Input	Chip select, active low. When CE#=1, chip is in standby state.	
CLK	Input	Clock signal	
RESET#	Input	Reset signal, active low. Optional, as the pad is internally tied	
		to a weak pull-up and can be left floating.	



6 Power-Up Initialization

Octal DDR products include an on-chip voltage sensor used to start the self-initialization process. V_{DD} and V_{DDQ} must be applied simultaneously. When they reach a stable level at or above minimum V_{DD} , the device is in Phase 1 and will require 150 μ s to complete its self-initialization process. The user can then proceed to Phase 2 of the initialization described in this section.

During Phase 1 CE# should remain HIGH (track V_{DD} within 200mV); CLK should remain LOW.

After Phase 2 is complete the device is ready for operation, however Half Sleep entry and Deep Power Down (DPD) entry are not available until Half Sleep Power Up (tHSPU) or DPD Power Up (tDPDp) duration is observed.

6.1 Power-Up Initialization Method 1 (via. RESET# pin)

The RESET# pin can be used to initialize the device during Phase 2 as follows:




Figure 1. Power-Up Initialization Method 1 RESET#

The RESET# pin can also be used at any time after the device is initialized to reset all register contents. Memory content is not guaranteed. Timing requirements for RESET# usage are shown below.




Figure 2. RESET# Timing



6.2 Power-Up Initialization Method 2 (via. Global Reset)

As an alternate power-up initialization method, After the Phase 1 150 μ s period the Global Reset command is used to reset the device in Phase 2 as follows:




Figure 3. Power-Up Initialization Method 2 Timing with Global Reset

The Global Reset command resets all register contents. Memory content is not guaranteed. The command frame is made of 4 clocked CE# lows. Clocking is optional during tRST. The Global Reset command sequence is shown below. Note that Global Reset command can be used ONLY as Power-up initialization.




Figure 4: Global Reset



7 Interface Description

7.1 Address Space

Octal DDR PSRAM device is byte-addressable. Memory accesses are required to start on even addresses (A[0]='0). Mode Register accesses allow both even and odd addresses.

7.2 Burst Type & Length

Read and write operations are default Hybrid Wrap 32 mode. Other burst lengths of 16, 32, 64 or 1K bytes in standard or Hybrid wrap modes are register configurable(see Table 20). The device also includes command for Linear Bursting. Bursts can start on any even address. Write burst length has a minimum of 2 bytes. Read has no minimum length. Both write and read have no restriction on maximum burst length as long as tCEM is met.

7.3 Command/Address Latching

After CE# goes LOW, instruction code is latched on 1st CLK rising edge. Access address is latched on the 3rd, 4th, 5th & 6th CLK edges (2nd CLK rising edge, 2nd CLK falling edge, 3rd CLK rising edge, 3rd CLK falling edge).

7.4 Command Truth Table

The Octal DDR PSRAM recognizes the following commands specified on the INST (Instruction) cycle defined by the Address/DQ pins.

	1st CLK		2nd	CLK	3rd	CLK
Command					4	_
Sync Read	00h		A3	A2	A1	A0
Sync Write	80h		А3	A2	A1	A0
Sync Read (Linear Burst)	20h		А3	A2	A1	A0
Sync Write (Linear Burst)	A0h		А3	A2	A1	A0
Mode Register Read	4()h		×		MA
Mode Register Write	C0h ×			MA		
Global Reset	FI	Fh		,	×	_

Remarks:

 \times = don't care (V_{IH}/V_{IL})

A3 = unused address bits are reserved

A2 = 1'bx, RA[12:6], unused address bit is reserved

A1 = RA[5:0], CA[9:8]

A0 = CA[7:0]

MA = Mode Register Address



7.5 Read Operation

After address latching, the device initializes DQS/DM to '0 from **next** CLK rising edge of the 3rd clock cycle (A1). See Figure 5 below.

Output data is available after LC latency cycles, as shown in Figure 7 & Figure 8, LC is defined in Table 5 and Table 6. When data is valid, A/DQ[7:0] and DQS/DM follow the timing specified in Figure 9. Synchronous timing parameters are shown in Table 30 & Table 31.

In case of internal refresh insertion, variable latency output data may be delayed by up to (LC*2) latency cycles as shown in Figure 7. True variable refresh pushout latency can be anywhere **between** LC to LCx2. The 1st DQS/DM rising edge after read pre-amble indicates the beginning of valid data.




Figure 5: Synchronous Read

If RBX has been enabled (MR8[3] written to 1) and a Linear Burst Command issued, then Wrap settings (MR8[2:0] are ignored and Read operations are allowed to cross row boundaries as shown in Figure 6.




Figure 6: Synchronous Read with RBX (Starting address '3FE)




Figure 7: Variable Read Latency Refresh Pushout




Figure 8: Read Latency & tDQSCK




Figure 9: Read DQS/DM & DQ timing



7.6 Write Operation

A minimum of 2 bytes of data must be input in a write operation. In the case of consecutive short burst writes, tRC must be met by issuing additional CE# high time between operations. Single-byte write operations can be performed by masking the un-written byte with DQS/DM as shown in Figure 10.




Figure 10: Synchronous Write followed by any Operation




Figure 11: Write DQS/DM & DQ Timing



7.7 Control Registers

Register Read is shown below. Mode Address in command determines which Mode Register is read from as Data0 (see chart in the Figure below).




Figure 12: Register Read




Figure 13: Register Write

Register Writes are Latency 1, whereas Register Reads use the same MR0[4:2] settings as burst reads (see Table 5). Registers 0, 4 & 8 are read and writable, and Registers 1, 2 and 3 are read-only. Register mapping is shown in Table 3. Note that MR0[6], MR0[7], MR4[4] and MR8[7] must be written to b'0.



Table 3: Mode Register Table

MR No.	MA[7:0]	Access	OP7	OP6	OP5	OP4	OP3	OP2	OP1	OP0
0	`h00	R/W	'00')'	LT	Read Latency Code Drive St		e Str.		
1	`h01	R	ULP	rsvd.		Vendor ID				
2	`h02	R	GB	rsv	vd.	Dev ID Density				
3	`h03	R	RBXen	VCC	SRF	rsvd.				
4	`h04	R/W	Write I	Latency	Code	'0' RF PASR				
6	`h06	W	На	Half Sleep & DPD rsvd.						
8	`h08	R/W	'0'	'0' rsvd. RBX BT		В	L			

Table 4: Read Latency Type (MR0[5])

Latency Type					
MR0[5]	LT				
0	Variable (default)				
1	Fixed				

Table 5: Read Latency Codes MR0[5:2]

	VL Codes (MR0[5]=0)		FL Codes (MR0[5]=1)	Max Input CL	K Freq (MHz)
MR0[4:2]	Latency (LC)	Max push out (LCx2)	Latency (LCx2)	Standard	Extended
000	3	6	6	66	66
001	4	8	8	109	109
010	5 (default)	10	10	133	133
011	6	12	12	166	166
100	7	14	14	200	200
others	reserved				-

Table 6: Operation Latency Code Table

Туре	Operation	VL (de	FL	
		No Refresh	Refresh	
Memory	Read	LC	Up to LCx2	LCx2
	Write	Write WLC		WLC
Register	Read	LC		LC
	Write	2 1		1

^{*}Note: see Table 16 for WLC settings.



Table 7: Drive Strength Codes MR0[1:0]

Codes	Drive Strength
'00	Full (25Ω)
'01	Half (50Ω default)
'10	1/4 (100Ω)
'11	1/8 (200Ω)

Table 8: Ultra Low Power Device mapping MR1[7]

ULP					
΄0	Non-ULP (no Half Sleep)				
'1	ULP (Half Sleep supported)				

Table 9: Vendor ID mapping MR1[4:0]

Vendor ID
01101: APM

Table 10: Good-Die Bit MR2[7]*

Codes	Good Die ID
'1	PASS
΄0	FAIL

^{*}Note: Default is FAIL die, and only mark PASS after all tests passed.

Table 11: Device ID MR2[4:3]

Codes	Device ID
'00	Generation 1
'01	Generation 2
'10	Generation 3 (default)
others	reserved

Table 12: Device Density mapping MR2[2:0]

MR2[2:0]	Density
'001	32Mb
'011	64Mb
'101	128Mb
'111	256Mb
others	reserved



Table 13: Row Boundary Crossing Enable (MR3[7])

MR3[7] (read-only) RBXen	
0	RBX not supported
1	RBX supported via MR8[3]=1

Table 14: Operating Voltage Range (MR3[6])

MR3[6] VCC	
0	1.8V (default)
1	3V

Table 15: Self Refresh Flag (MR3[5])

MR3[5] (read-only)	Self Refresh Flag	
0	0 Slow Refresh (allowed via MR4[3]=1, otherwise Fast Refresh	
1 Fast Refresh		

MR3[5] is a refresh indicator that corresponds to device internal temperature. This bit will indicate 0 when the temperature is low enough to allow a slow frequency refresh rate.

Table 16: Write Latency MR4[7:5]

Default powered up behavior is WL 5

MR4[7:5]	Write Latency	Fmax (MHz)
000	3	66
100	4	104
010	5 (default)	133
110	6	166
001	7	200
others	reserved	-

Table 17: Refresh Frequency MR4[3]

MR4[3]	Refresh Frequency	
0	Fast Refresh (default)	
1	Enables Slow Refresh when temperature allows	



Table 18: PASR MR4[2:0]

The PASR bits restrict refresh operation to a portion of the total memory array. This feature allows the device to reduce standby current by refreshing only that part of the memory array required by the host system. The refresh options are full array, one-half array, one-quarter array, one-eighth array, or none of the array. The mapping of these partitions can start at either the beginning or the end of the address map.

		64Mb		
Codes	Refresh Coverage	Address Space	Size	Density
'000	Full array (default)	000000h-7FFFFFh	8M x8	64Mb
'001	Bottom 1/2 array	000000h-3FFFFFh	4M x8	32Mb
'010	Bottom 1/4 array	000000h-1FFFFFh	2M x8	16Mb
'011	Bottom 1/8 array	000000h-0FFFFh	1M x8	8Mb
'100	None	0	OM	0Mb
'101	Top 1/2 array	400000h-7FFFFFh	4M x8	32Mb
'110	Top 1/4 array	600000h-7FFFFFh	2M x8	16Mb
'111	Top 1/8 array	700000h-7FFFFh	1M x8	8Mb



Table 19: ULP Modes MR6[7:0]

MR6[7:0]	ULP Modes	
'hF0	Half Sleep	
'hC0	Deep Power Down	
others	reserved	

Note: see 7.8 Half Sleep Mode; 7.9 Deep Power Down Mode for more information.

Table 20: Burst Type MR8[2], Burst Length MR8[1:0]

By default the device powers up in 32 Byte Hybrid Wrap. In non-Hybrid burst (MR8[2]=0), MR8[1:0] sets the burst address space in which the device will continually wrap within. If Hybrid burst wrap is selected (MR8[2]=1), the device will burst through the initial wrapped burst length once, then continue to burst incrementally up to maximum column address (1K) before wrapping around within the entire column address space. Burst length (MR8[1:0]) can be set to 16,32,64 & 1K lengths.

MR8[2]	MR8[1:0]	Burst Length	Example of	Sequence of Bytes During Wrap
	,		Starting Address	Byte Sequence
΄0	'00	16 Byte Wrap	4	[4,5,6,15,0,1,2,]
΄0	'01	32 Byte Wrap	4	[4,5,6,31,0,1,2,]
΄0	'10	64 Byte Wrap	4	[4,5,6,63,0,1,2,]
΄0	'11	1K Byte Wrap	4	[4,5,6,1023,0,1,2,]
'1	'00	16 Byte Hybrid Wrap	2	[2,3,4,15,0,1],16,17,18,1023,0,1,
'1	'01	32 Byte Hybrid Wrap (default)	2	[2,3,4,31,0,1],32,33,34,1023,0,1,
'1	'10	64 Byte Hybrid Wrap	2	[2,3,4,63,0,1],64,65,66,1023,0,1,
'1	'11	1K Byte Wrap	2	[2,3,4,1023,0,1,2,]

The Linear Burst Commands (INST[5:0]=6'b100000) override MR8[2:0] settings and forces the current array read or write command to do 1K Byte Wrap (equivalent to having MR8[1:0] set to 2'b11). The burst continues linearly from the starting address and at the end of the page, then wraps back to the beginning of the page. This special burst instruction can be used on both array write and read.

Table 21: Row Boundary Crossing Read Enable MR8[3]

This register setting applies to Linear Burst reads only on RBX enabled devices (MR3[7]=1). Default write and read burst behavior is limited within the 1K (CA='h000 -> 'h3FF) column address space. Setting this bit high will allow Linear Burst reads to cross over into the next Row (RA+1).

MR8[3]	RBX Read	
0	Reads stay within the 1K column address space	
1	Reads cross row at 1K boundaries	



7.8 Half Sleep Mode

Half Sleep Mode is a feature which puts the device in an ultra-low power state, while the stored data is retained. Half Sleep Mode Entry is entered by writing 8'hF0 into MR6. CE# going high initiates the Half Sleep mode and must be maintained for the minimum duration of tHS. The Half Sleep Entry command sequence is shown below.




Figure 14: Half Sleep Entry Write (default WL0)

Half Sleep Exit is initiated by a low pulsed CE#. Afterwards, CE# can be held high with or without clock toggling until the first operation begins (observing minimum tXHS).




Figure 15: Half Sleep Exit (Read Operation shown as example)



7.9 Deep Power Down Mode

Deep Power Down Mode (DPD) is a feature which puts the device into power down state. DPD Mode Entry is entered by writing 8'hC0 into MR6. CE# going high initiates the DPD Mode and must be maintained for the minimum duration of tDPD. The Deep Power Down Entry command sequence is shown below.




Figure 16: Deep Power Down Entry

Deep Power Down Exit is initiated by a low pulsed CE#. After a CE# DPD Exit, CE# must be held high with or without clock toggling until the first operation begins (observing minimum tXDPD).




Figure 17: Deep Power Down Exit (Read Operation shown as example)

Register values and memory content are not retained in DPD Mode. After DPD mode register values will reset to defaults. tDPDp is minimum period between two DPD Modes (measured from DPD exit to the next DPD entry) as well as from the initial powerup to the first DPD entry.



8 Electrical Specifications:

8.1 Absolute Maximum Ratings

Table 22: Absolute Maximum Ratings

Parameter	Symbol	Rating	Unit	Notes
Voltage to any ball except V _{DD} , V _{DDQ} relative to V _{SS}	VT	-0.4 to V _{DD} /V _{DDQ} +0.4	V	
Voltage on V _{DD} supply relative to V _{SS}	V _{DD}	-0.4 to +2.45	V	
Voltage on V _{DDQ} supply relative to V _{SS}	V_{DDQ}	-0.4 to +2.45	V	
Storage Temperature	T _{STG}	-55 to +150	°C	1

Notes 1: Storage temperature refers to the case surface temperature on the center/top side of the PSRAM.

Caution:

Exposing the device to stress above those listed in Absolute Maximum Ratings could cause permanent damage. The device is not meant to be operated under conditions outside the limits described in the operational section of this specification. Exposure to Absolute Maximum Rating conditions for extended periods may affect device reliability.

8.2 Pin Capacitance

Table 23: Bare Die Pin Capacitance

Parameter	Symbol	Min	Max	Unit	Notes
Input Pin Capacitance	CIN		2	pF	VIN=0V
Output Pin Capacitance	COUT		3	pF	VOUT=0V

Note 1: spec'd at 25°C.

Table 24: Package Pin Capacitance

Parameter	Symbol	Min	Max	Unit	Notes
Input Pin Capacitance	CIN		6	pF	VIN=0V
Output Pin Capacitance	COUT		8	pF	VOUT=0V

Note 1: spec'd at 25°C.

Table 25: Load Capacitance


Parameter	Symbol	Min	Max	Unit	Notes
Load Capacitance	C_L		15	pF	

Note 1: System C_L for the use of package



8.3 Decoupling Capacitor Requirement

System designers need to take care of power integrity considering voltage regulator response and the memory peak currents/usage modes.



8.3.1 <u>Low ESR cap C1:</u>

It is recommended to place a low ESR decoupling capacitor of $<=1\mu F$ close to the device to absorb transient peaks.

8.3.2 Large cap C2:

During Half-sleep modes even though half-sleep average currents are very small (less than $100\mu A$), device will internally have low duty cycle burst refresh for an extended period of time of a few tens of microseconds. These refresh current peaks are large. During this period if the system regulator cannot supply large peaks for several microseconds, it is important to place a $4.7\mu F-10\mu F$ cap to take care of burst refresh currents and replenish the charge before next burst of refreshes.

If required please contact AP Memory for further current peak details.

8.4 Operating Conditions

Table 26: Operating Characteristics

Parameter	Min	Max	Unit	Notes
Operating Temperature (extended)	-40	105	°C	1
Operating Temperature (standard)	-40	85	°C	

Note 1: Extended temp range of -40 to 105°C is only characterized; test condition is -32 to 105°C.



8.5 DC Characteristics

Table 27: DC Characteristics

Symbol	Parameter	Min	Max	Unit	Notes
V_{DD}	Supply Voltage	1.62	1.98	V	
V_{DDQ}	I/O Supply Voltage	1.62	1.98	V	
V _{IH}	Input high voltage	V _{DDQ} -0.4	V _{DDQ} +0.2	V	
V _{IL}	Input low voltage	-0.2	0.4	V	
V _{OH}	Output high voltage (I _{OH} =-0.2mA)	0.8 V _{DDQ}		V	
V _{OL}	Output low voltage (I _{OL} =+0.2mA)		0.2 V _{DDQ}	V	
ILI	Input leakage current		1	μΑ	
I _{LO}	Output leakage current		1	μΑ	
	Read/Write @13MHz		4	mA	2
ICC	Read/Write @133MHz		16	mA	2
	Read/Write @166MHz		19	mA	2
	Read/Write @200MHz		22	mA	2
ISB _{EXT}	Standby current (extended temp)		300	μΑ	1,3
ISB _{STD}	Standby current (standard temp)		200	μΑ	3
ISB _{STDroom}	Standby current (room temp)		100	μΑ	3, 4, 5
ISB _{STDHS}	Standby current (half sleep 25°C)		30	μΑ	3,4,6,7
ISB _{STDDPD}	Standby current (Deep Power Down -40°C to 85°C)		15	μА	8

Note 1: Spec'd up to 105°C.

Note 2: Current is only characterized.

Note 3: Without CLK toggling. ISB will be higher if CLK is toggling.

Note 4: Slow Refresh.

Note 5: **Typical ISB**stdroom **66uA**.

Note 6: Current is only guaranteed after 150ms into Half Sleep mode.

Note 7: Typical ISBsTDHs 20uA

Note 8: Typical mean ISBstddpd 7uA at 25°C



8.6 ISB Partial Array Refresh Current

Table 28: Typical PASR Current @ 25°C

Standby Co	Standby Current @ 25°C							
PASR	ISB –typical mean	Unit	Notes					
Full	66	μΑ	1,2					
1/2	65	μΑ	1,2					
1/4	64	μΑ	1,2					
1/8	60	μΑ	1,2					
Half Sleep	Current @ 25°C							
PASR	I Half Sleep-typical mean	Unit	Notes					
Full	20	μΑ	1,2,3					
1/2	14	μΑ	1,2,3					
1/4	11	μΑ	1,2,3					
1/8	10	μΑ	1,2,3					

Table 29: Typical PASR Current @ 85°C

Standby Co	Standby Current @ 85°C							
PASR	ISB –typical mean	Unit	Notes					
Full	190	μΑ	2					
1/2	150	μΑ	2					
1/4	125	μΑ	2					
1/8	110	μΑ	2					
Half Sleep	Current @ 85°C							
PASR	I Half Sleep-typical mean	Unit	Notes					
Full	120	μΑ	2,3					
1/2	72	μΑ	2,3					
1/4	48	μΑ	2,3					
1/8	24	μΑ	2,3					

Note 1: Slow Refresh current is only attainable by enabling Slow Refresh Frequency (see Table 17)

Note 2: PASR Current is only characterized based on 64M density without CLK toggling.

Note 3: Spec'd Half Sleep current is only guaranteed after 150ms into Half Sleep mode.



8.7 AC Characteristics

Table 30: READ/WRITE Timing

BGA 1.8V Only									
		-7(133	-7(133MHz) -6(166MHz) -5(200MHz)						
Symbol	Parameter	Min	Max	Min	Max	Min	Max	Unit	Notes
tCLK	CLK period	7.5		6		5		ns	
tCH/tCL	Clock high/low width	0.45	0.55	0.45	0.55	0.45	0.55	tCLK	
tKHKL	CLK rise or fall time		1.2		1		0.8	ns	
tCPH	CE# HIGH between subsequent burst	4.5		40		20			
	operations	15		18		20		ns	
tCEM	CE# low pulse width		4		4		4	μs	Standard temp
CCLIVI	(excluding Half Sleep exit)		1		1		1	μs	Extended temp
tCEM	CE# low pulse width	3		3		3		tCLK	Minimum 3 clocks
tCSP	CE# setup time to CLK rising edge	2		2		2		ns	
tCHD	CE# hold time from CLK falling edge	2		2		2		ns	
tSP	Setup time to active CLK edge	0.8		0.8		0.8		ns	
tHD	Hold time from active CLK edge	0.8		0.8		0.8		ns	Max 0.75*tCLK
tHZ	Chip disable to DQ/DQS output high-Z		6		6		6	ns	
tRBXwait	Row Boundary Crossing Wait Time	30	65	30	65	30	65	ns	
tRC	Write Cycle	60		60		60		ns	
tRC	Read Cycle	60		60		60		ns	
tHS	Minimum Half Sleep duration	150		150		150		μs	
tXHS	Half Sleep Exit CE# low to CLK setup time	150		150		150		μs	
17/21/10		60		60		60		ns	
tXPHS	Half Sleep Exit CE# low pulsewidth		4		4		4	μs	Standard temp
			1		1		1	μs	Extended temp
tDPD	Minimum DPD duration	500		500		500		μs	
tDPDp	Minimum period between DPD Modes	500		500		500		μs	
tXDPD	DPD CE# low to CLK setup time	150		150		150		μs	
tXPDPD	DPD Exit CE# low pulsewidth	60		60		60		ns	
tPU	Device Initialization	150		150		150		μs	
tRP	RESET# low pulse width	1		1		1		μs	
tRST	Reset to CMD valid	2		2		2		μs	



Table 31: DDR timing parameters

			BGA 1.8V Only						
		-7(13	3МНz)	-6(16	6MHz)	-5(20	OMHz)		
Symbol	Parameter	Min	Max	Min	Max	Min	Max	Unit	Notes
tCQLZ	Clock rising edge to DQS low	1	6	1	6	1	6	ns	
tDQSCK	DQS output access time from CLK	2	5.5	2	5.5	2	5.5	ns	
tDQSQ	DQS – DQ skew		0.6		0.5		0.4	ns	
tDS	DQ and DM input setup time	0.8		0.8		0.8		ns	
tDH	DQ and DM input hold time	0.8		0.8		0.8		ns	
tHP	Half Period	= min (tCH, tCL)				ns			
tQHS	Datahold skew factor	0.75 0.6 0.5				ns			
tQH	DQ output hold time from DQS			= tHP	- tQHS			ns	



9 Change Log

1.0 Mar 02, 2017 Initial Version 1.1 Mar 03, 2017 Changed register usage for Refresh Frequency 1.2 Mar 27, 2017 Temperature range correction; reformatted PASR current 1.3 July 18, 2017 Tables, reworded burst table for clarity; added pin cap tables 1.4 Aug 01, 2017 Corrected tCQLZ reference edge 1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated XHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated Max. Frequency of ordering information 3.0 Aug 08, 2019 Revised to Power-up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typical Page 1; added b'0 notes for Table3; revised Table 11; corrected C ₁ in Table 27; happed and table and picture; added notes for Table3; revised Table 11; corrected C ₂ in Table 27; pudated RBA Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C ₃ in Table 27; pudated RBA Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C ₄ in Table 20; updated Figure 1; 3.2 Sep 28,	Version	Date	Description
1.1 Mar 03, 2017 Changed register usage for Refresh Frequency 1.2 Mar 27, 2017 Temperature range correction; reformatted PASR current 1.3 July 18, 2017 Tables, reworded burst table for clarity; added pin cap tables 1.4 Aug 01, 2017 Corrected tCQLZ reference edge 1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 1.8 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 1.1 Nov 13, 2017 Revised ICC and ISB 1.2 Nov 27, 2017 Revised tCHD, WLC table 1.3 Dec 21, 2017 Revised tCHD, WLC table 1.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 1.5 Apr 13, 2018 Added DPD 1.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 1.8 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 1.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 1.8 Jan 22, 2019 Updated Max. Frequency of ordering information 1.8 May 31, 2019 Removed the NOTE for STM32L4+ family 1.9 Aug 06, 2019 Rewised cross-reference of Table 17: revised bection 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 1.0 Aug 08, 2019 Revised section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for Table 3; revised Table 11; corrected C ₁ in Table 25; Added tRBXwait in Table 30 1.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 1.1 Aug 21, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29			·
1.2 Mar 27, 2017 Temperature range correction; reformatted PASR current 1.3 July 18, 2017 Tables, reworded burst table for clarity; added pin cap tables 1.4 Aug 01, 2017 Corrected tCQLZ reference edge 1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 1.8 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 1.1 Nov 13, 2017 Revised ICC and ISB 1.2 Nov 27, 2017 Revised tCHD, WILC table 1.3 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 1.5 Apr 13, 2018 Added DPD 1.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 1.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 1.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STIM32L4+ family 1.8 Jan 22, 2019 Updated Max. Frequency of ordering information 1.8 Aug 06, 2019 Rewoved the NOTE for STM32L4+ family 1.9 Aug 06, 2019 Rewoved the NOTE for STM32L4+ family 1.9 Aug 06, 2019 Rewised typo in Page 1; added notes for 24B BGA 1.0 Aug 08, 2019 Revised section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 1.0 Aug 08, 2019 Revised section 8.6, Table 15, Table 28, Table 29; added section 8.3 1.1 Aug 21, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29		-	
1.3 July 18, 2017 Tables, reworded burst table for clarity; added pin cap tables 1.4 Aug 01, 2017 Corrected tCQLZ reference edge 1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 2.0 Oct 31, 2017 Rewised Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.8 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Revised section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'O notes for Table 3; revised Table 11; corrected C _L in Table 25, Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29			
1.4 Aug 01, 2017 Corrected tCQLZ reference edge 1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 2.0 Oct 31, 2017 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.8 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Padded Section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 248 BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'O notes for Table 3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1 Aug 21, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29			
1.5 Aug 03, 2017 Corrected tCHD reference edge in table; add don't care data to Register Write drawing 1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 2.0 Oct 31, 2017 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 08, 2019 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table 3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Table 28 and Table 29		-	
1.6 Sep 11, 2017 Corrected extended temperature range; updated ordering information; added system CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 2.0 Oct 31, 2017 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'O notes for Table 3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	1.4	Aug 01, 2017	7
1.6 Sep 11, 2017 CL for max frequency 1.7 Sep 25, 2017 Added Typical ISBSTDHS & note for latency count of register read 2.0 Oct 31, 2017 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 08, 2019 Revised cyton in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	1.5	Aug 03, 2017	
2.0 Oct 31, 2017 Removed Hybrid 64, modified Write 4 bytes & absolute voltage, VIL/VIH, added typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Rovised part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Prevised section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	1.6	Sep 11, 2017	
typical ISB & PASR@25C 2.1 Nov 13, 2017 Revised ICC and ISB 2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Removed the NOTE for STM32L4+ family 3.0 Aug 08, 2019 Revised typo in Page 1; added b'O notes for Table 3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	1.7	Sep 25, 2017	Added Typical ISBSTDHS & note for latency count of register read
2.2 Nov 27, 2017 Revised typical ISB, HS ISB spec 2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected Ct in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.0	Oct 31, 2017	· · · · · · · · · · · · · · · · · · ·
2.3 Dec 21, 2017 Revised tCHD, WLC table 2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.1	Nov 13, 2017	Revised ICC and ISB
2.4 Jan 28, 2018 Restored timing of Half Sleep mode, corrected typo of Half Sleep mode 2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.2	Nov 27, 2017	Revised typical ISB, HS ISB spec
2.5 Apr 13, 2018 Added DPD 2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.3	Dec 21, 2017	Revised tCHD, WLC table
2.6 Apr 26, 2018 Revised cross-reference of Table 17 in table 27 and 28 2.7 Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.4	Jan 28, 2018	Restored timing of Half Sleep mode, corrected typo of Half Sleep mode
Nov 30, 2018 Note for special part of OBM, updated some latency wording and added operation latency table Unified part number to OBM for RBX read & special parts of STM32L4+ family Updated Max. Frequency of ordering information Added ISBSTDDPD, updated tXHS spec Removed the NOTE for STM32L4+ family Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.5	Apr 13, 2018	Added DPD
2.7 Nov 30, 2018 latency table 2.8 Jan 09, 2019 Unified part number to OBM for RBX read & special parts of STM32L4+ family 2.81 Jan 22, 2019 Updated Max. Frequency of ordering information 2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.6	Apr 26, 2018	Revised cross-reference of Table 17 in table 27 and 28
 Jan 22, 2019 Updated Max. Frequency of ordering information May 30, 2019 Added ISBSTDDPD, updated tXHS spec May 31, 2019 Removed the NOTE for STM32L4+ family Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C_L in Table 25; Added tRBXwait in Table 30 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29 	2.7	Nov 30, 2018	
2.82 May 30, 2019 Added ISBSTDDPD, updated tXHS spec 2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.8	Jan 09, 2019	Unified part number to OBM for RBX read & special parts of STM32L4+ family
2.83 May 31, 2019 Removed the NOTE for STM32L4+ family 2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.81	Jan 22, 2019	Updated Max. Frequency of ordering information
2.9 Aug 06, 2019 Updated section 6 Power-Up Initialization; added table for change log; revised Page 1; revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.82	May 30, 2019	Added ISBSTDDPD, updated tXHS spec
Aug 06, 2019 revised section 4 table and picture; added notes for 24B BGA 3.0 Aug 08, 2019 Revised typo in Page 1; added b'0 notes for Table3; revised Table 11; corrected C _L in Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.83	May 31, 2019	Removed the NOTE for STM32L4+ family
Table 25; Added tRBXwait in Table 30 3.1 Aug 16, 2019 Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3 3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	2.9	Aug 06, 2019	
3.1a Aug 21, 2019 Updated notes of section 2 and Table 20; Updated Figure 1; 3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	3.0	Aug 08, 2019	
3.2 Sep 28, 2019 Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29	3.1	Aug 16, 2019	Revised section 8.6, Table 15, Table 28 & Table 29; added section 8.3
	3.1a	Aug 21, 2019	Updated notes of section 2 and Table 20; Updated Figure 1;
3.3 Oct 30, 2019 Updated notes for Table 3, Table 15, Table 20 and section 7.5	3.2	Sep 28, 2019	Updated header and page 1; updated ICC in Table 27; updated Table 28 and Table 29
	3.3	Oct 30, 2019	Updated notes for Table 3, Table 15, Table 20 and section 7.5



3.4	Nov 14, 2019	Updated notes in section 7.5, Table 16, Table 18 and Table 30
3.4a	Nov 20, 2019	Updated typo in section 7.7
3.5a	Dec 11, 2019	Updated tHS _{min} in Table 30, Figure 15 and Figure 17
3.5b	Dec 13, 2019	Updated the notes for Table 27

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

APS6408L-OBM-BA APS6408L-OBMX-BA