
## UNCONTROLLED DOCUMENT



IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR NANY YEARS OF EXPERIENCE DATA ACCUNULATION INDICATE THAT

SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.

PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

DRAWN BY:

BC

CHECKED BY:

TW WEB: www.lumex.com.tw

DATE:

PAGE:

SCALE:

4.9.96

1 OF 1

N/A

APPROVED BY:

T-3mm (T-1) 430nm SUPER BLUE LED,

BLUE DIFFUSED LENS.

## **Mouser Electronics**

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Lumex: SSL-LX3044SBD/A