

Preliminary Specification of COAXIAL CONNECTORWritten by:T.KuriyamaPreliminary SPEC No.: NMM04-PW0001CChecked byT. OhtaniPart Number: MM8130-2600B/RA2/RB8Date:13/Jun./2006

SPECIFICATION

Revised A: 4/Apr./'07 ER Revised B: 07/Mar./'08 KY Revised C: 9/Jun./'08 KY

1. PART NUMBER

Part Number	Packaging	Quantity
MM8130-2600B	Bulk Package	
MM8130-2600RA2	178 mm dia. reel	2000 pcs/reel
MM8130-2600RB8	330 mm dia. reel	8000 pcs/reel

2. MECHANICAL

C> B>




FIGURE1. Construction


3. RATING:

Item	Specification	
Voltage Rating	250V r.m.s. maximum	
Nominal Frequency Range	DC to 6GHz	
Nominal Impedance	50Ω	
Temperature Rating	-40°C to +85°C	
Insulation Resistance	500 MΩ minimum	
Withstanding Voltage	AC 300V±20V	
B> Initial Contact Resistance	Center contact 70.0mΩmax.	
(without conductor resistance)		
Voltage Standing Wave Ratio (V.S.W.R.)	Meet the requirements of following spec.	
	1.2 max. (DC to 3GHz)	
	1.3 max. (3GHz to 6GHz)	
Insertion Loss	0.1dBmax. (DC~3GHz)	
	0.2dBmax.(3GHz ~6GHz)	
Isolation	20dBmin.(DC~3GHz)	
	15dBmin.(3GHz ~6GHz)	
Durability	100 cycles	



Preliminary Specification of	f COAXIAL CONNECTOR	Written by: <u>T.Kuriyama</u>
Preliminary SPEC No.	: NMM04-PW0001C	Checked by <u>T. Ohtani</u>
Part Number	: MM8130-2600B/RA2/RB8	Date: 13/Jun./2006

4. STANDARD PATTERN DIMENSION




(Note) ·I/O pattern should be designed to be the impedance match 50 ohm.

- •The material of PCB is the epoxy resin of glass fabric base. (εr=4.8). Thickness is 1.0mm.
- •The solder resist should be printed except for the land pattern on the PCB FIGURE2. Standard pattern dimensions

5. STANDARD STENCIL MASK PATTERN

The standard stencil mask pattern is as FIGURE 3.(Thickness is 0.12mm)

There is the possibility to have the contact failure by solder shifting into contact point, if the excess solder is used by non standard stencil mask pattern



Unit: mm

The standard solder cream metal stencil mask drawing (Thickness: 0.12mm)

Note) There is the possibility to have the contact failure by solder shifting into contact point, if the excess solder is used by non standard stencil mask pattern.

FIGURE3. Standard stencil mask pattern

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Murata:

MM8130-2600RA2