Product availability: Non-Stock - Not normally stocked in distribution facility



Main Range of product Altivar Bus type Modbus Accessory / separate part category Accessory / separate Line terminator

part type

Accessory / separate RJ45 connector part destination

Quantity per set Set of 2

Complementary

| Range compatibility | Altivar Machine ATV340 except Sercos drives | | |
|-----------------------------|---|--------------|------------|
| | Altivar 71Q | | |
| | Altivar 71 | | |
| | Altivar 61Q Altivar 61 | | |
| | | | Altivar 31 |
| | Preventa XPS MF | | |
| | Altistart 48 | | |
| | Altivar 12 | | |
| | | Altistart 22 | |
| | Lexium SD3 | | |
| | Altivar 31C | | |
| | Altivar Easy 310 | | |
| | Altivar 312 | | |
| Communication port protocol | Modbus | | |
| Terminator resistance | 150 Ohm | | |
| Product weight | 0.44 lb(US) (0.2 kg) | | |

Ordering and shipping details

| Category | 22490 - SENSORS-ULTRASONIC (XX5,6) | |
|-----------------------|------------------------------------|--|
| Discount Schedule | DS2 | |
| GTIN | 00785901437451 | |
| Nbr. of units in pkg. | 2 | |
| Package weight(Lbs) | 8.9999999999997E-2 | |
| Returnability | N | |
| Country of origin | CN | |

Offer Sustainability

| California proposition 65 | WARNING: This product can expose you to chemicals including: | |
|---------------------------|--|--|
| Substance 1 | Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. | |
| Substance 2 | Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm. | |
| More information | For more information go to www.p65warnings.ca.gov | |

Contractual warranty

| Warranty period | 18 months |
|-----------------|-----------|
| | |

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Schneider Electric: VW3A8306R