


Exploded view diagram of a mechanical assembly. The diagram shows various components and their assembly sequence, indicated by numbered callouts (1 through 67). Key components include a central motor unit, a terminal support structure, and various mounting brackets and fasteners. A detail view at the top right shows the terminal support location with dimensions 0.51 ± 0.5 and $[.020 \pm .020]$, and reference points 8 and 34.

- * WARNING
ON INSTALLATION, SET WIRE
DISC TO LARGEST WIRE SIZE
SETTING. USE OF SETTINGS
BELOW MIN. REQUIRED CRIMP
HEIGHT SETTING WILL CAUSE
DAMAGE TO CRIMP TOOLING.



Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[TE Connectivity:](#)

[1528688-1](#)