

The information given here is subject to change without notice. Design changes may be in order to improve the product .

Connect to the future

TECHNICAL	DATA Page 2/2
	R162.017.000 ISSUE 9813D01 SERIES N 75
CLAMP NUT <u>'V'GROOVE GASKET</u> CLAMP BRAID SLEEVE	<u>CENTRE CONTACT</u>
Strip the cable .	
-	Strippingabcdeinch0.1970.335000.059mm58.51.5
Slide the clamp nut and the 'V' groove gasket onto the cable . Slide clamp braid sleeve over braid . Fold back braid and trim off surplus braid . Trim back dielectric as shown . -	
3 Solder the cable inner conductor into centre contact . - - - -	
Screw sub-assembly into the connector body . ( recommended coupling torque 70.87 in.1b ) - - The information given here is subject to change without noti	Hex. : 0.63/flats

## **Mouser Electronics**

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Radiall: R162017000W