




## Terminal Winding Options For Wire Harness Manufacturers



STANDARD FCI WINDING IS "B."

TO ORDER WINDING "A" USE THE FOLLOWING  
SUFFIX: 5400xxxxRWA

TO ORDER WINDING "C" USE THE FOLLOWING  
SUFFIX: 5400xxxxRWC

TO ORDER WINDING "D" USE THE FOLLOWING  
SUFFIX: 5400xxxxRWD