



Product/Process Change Notice - PCN 14_0258 Rev. C

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

Note: Revised fields are indicated by a red field name. See Appendix B for revision history.

PCN Title: Assembly Transfer of Selected 14x14 LQFP, 14x14 LQFP_EP and 7x7, 10x10, 12x12, 14x14 TQFP_EP Products to Amkor Philippines
Publication Date: 19-Oct-2015
Effectivity Date: 17-Jan-2016 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Add AD80100ASVZ-80 and AD6645ASVZ-80 to the affected parts list

Description Of Change

ADI is transferring to qualified subcontractor Amkor Philippines for the assembly of 14x14 LQFP, 14x14 LQFP_EP and 7x7, 10x10, 12x12, 14x14 TQFP_EP products.
ADI will be qualifying Amkor's standard bill of materials (BOM). The mold compound material for 14x14 body packages will change from Sumitomo G700L to Sumitomo G631HQ. The mold gate position will change as a result of the mold compound change. The package outline dimensions and wire sizes of each product will be maintained. Please see attachments.

History of Effectivity Dates:

Rev – : Effectivity date was 1-Apr-2015 with Qualification Plans provided.

Rev A : Effectivity date was 22-Jun-2015 for products covered by Qualification Results Summaries provided:
7x7 10x10 12x12 TQFP_EP Using G700L_3230, 10x10 12x12 TQFP_EP Using G700L_8361J and 14x14 TQFP_EP Using G631HQ_3230.

Rev B : Effectivity date will be 31-Jan-2016 for products covered by remaining Qualification Plans:
14x14 LQFP Using G631HQ_3230
14x14 LQFP_EP Using G631HQ_3230

Effectivity date will be immediate for products covered by Qualification Results Summaries provided:
14x14 LQFP Using G631HQ_3230_QM1536

Rev C : Add AD80100ASVZ-80 and AD6645ASVZ-80 to the affected parts list

Reason For Change

ADI is transferring to Amkor Philippines due to the closure of Amkor Korea factory line on February of 2015 for 12x12 TQFP_EP and mid-year 2016 for 7x7, 10x10 TQFP_EP, 14x14 LQFP, 14x14 LQFP_EP, respectively.

ADI's assembly subcontractors manufacture products using Analog Devices specified manufacturing flows, materials, process controls and monitors, ensuring the same level of quality and reliability.

Impact of the change (positive or negative) on fit, form, function & reliability

The transfer will have no impact on the form, fit, function and reliability of the devices.

Product Identification *(this section will describe how to identify the changed material)*

The parts that will be assembled after the transfer will be identified by assembly lot number and the country of origin.

Summary of Supporting Information

Qualification will be performed per ADI0012, Procedure for Qualification of New or Revised Processes. See attached Qualification Plans.

Supporting Documents

Attachment 1: Type: Detailed Parts List

ADI_PCN_14_0258_Rev_C_LQFP_LQFP_EP_TQFP_EP_PART_LIST.xlsx

Attachment 2: Type: Detailed Change Description

ADI_PCN_14_0258_Rev_C_14x14 Mold Compound and Mold Gate Position Change.pptx

Attachment 3: Type: Qualification Results Summary

ADI_PCN_14_0258_Rev_C_7x7 10x10 12x12 TQFP_EP Using G700L_3230 at AP-Qualification Results Summary.docx

Attachment 4: Type: Qualification Results Summary

ADI_PCN_14_0258_Rev_C_10x10 12x12 TQFP_EP Using G700L_8361J at AP-Qualification Results Summary.docx

Attachment 5: Type: Qualification Results Summary

ADI_PCN_14_0258_Rev_C_14x14 TQFP_EP Using G631HQ_3230 at AP.docx

Attachment 6: Type: Qualification Plan

ADI_PCN_14_0258_Rev_C_14x14 LQFP Using G631HQ_3230 at AP.docx

Attachment 7: Type: Qualification Results Summary

ADI_PCN_14_0258_Rev_C_14x14 LQFP Using G631HQ_3230_QM1536 at AP.docx

Attachment 8: Type: Qualification Plan

ADI_PCN_14_0258_Rev_C_14x14 LQFP_EP Using G631HQ_3230 at AP.docx

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Existing Parts - Product Family / Model Number (78)

AD53509G / AD53509JSWZ	AD53564 / AD53564JSWZ	AD5522 / AD5522JSVDZ	AD5522 / AD5522JSVUZ	AD5522 / AD5522JSVUZ-RL
AD5560 / AD11/2059Z-2	AD5560 / AD5560JSVUZ	AD5560 / AD5560JSVUZ-REEL	AD6645 / AD6645ASVZ-105	AD7760 / AD7760BSVZ
AD7760 / AD7760BSVZ-REEL	AD8116 / AD8116JSTZ	AD8387 / AD8387JSVZ	AD9271 / AD9271BSVZ-25	AD9271 / AD9271BSVZ-40
AD9271 / AD9271BSVZ-50	AD9271 / AD9271BSVZRL-40	AD9272 / AD9272BSVZ-40	AD9272 / AD9272BSVZ-65	AD9272 / AD9272BSVZ-80
AD9272 / AD9272BSVZRL-40	AD9272 / AD9272BSVZRL-65	AD9272 / AD9272BSVZRL-80	AD9273 / AD9273BSVZ-25	AD9273 / AD9273BSVZ-40
AD9273 / AD9273BSVZ-50	AD9273 / AD9273BSVZRL-25	AD9273 / AD9273BSVZRL-40	AD9273 / AD9273BSVZRL-50	AD9276 / AD9276BSVZ
AD9277 / AD9277BSVZ	AD9389B / AD9389BBSTZ-165	AD9389B / AD9389BBSTZ-80	AD9410 / AD9410BSVZ	AD9430 / AD80107Z
AD9430 / AD80142BSVZ-200	AD9430 / AD80205BSVZ-200	AD9430 / AD80215BSVZ-185	AD9430 / AD9430BSVZ-170	AD9430 / AD9430BSVZ-210
AD9433 / AD9433BSVZ-125	AD9444 / AD9444BSVZ-80	AD9445 / AD9445BSVZ-105	AD9445 / AD9445BSVZ-125	AD9446 / AD9446BSVZ-100
AD9446 / AD9446BSVZ-80	AD9460 / AD9460BSVZ-105	AD9460 / AD9460BSVZ-80	AD9461 / AD9461BSVZ	AD9726 / AD9726BSVZ
AD9726 / AD9726BSVZRL	AD9775 / AD9775BSVZ	AD9775 / AD9775BSVZRL	AD9777 / AD9777BSVZ	AD9777 / AD9777BSVZRL
AD9786 / AD9786BSVZ	AD9786 / AD9786BSVZRL	AD9852 / AD9852ASVZ	AD9854 / AD9854ASVZ	AD9858 / AD9858BSVZ
AD9910 / AD9910BSVZ	AD9910 / AD9910BSVZ-REEL	AD9951 / AD9951YSVZ	AD9951 / AD9951YSVZ-REEL7	AD9952 / AD9952YSVZ
AD9952 / AD9952YSVZ-REEL7	AD9954 / AD9954YSVZ	AD9954 / AD9954YSVZ-REEL7	AD9957 / AD9957BSVZ	AD9957 / AD9957BSVZ-REEL
ADATE302-02 / ADATE302-02BSVZ	ADATE305 / ADATE305BSVZ	ADAU1442 / ADAU1442YSVZ-3A-RL	ADAU1445 / ADAU1445YSVZ-3A	ADAU1445 / ADAU1445YSVZ-3A-RL
ADN4604 / ADN4604ASVZ	ADN4604 / ADN4604ASVZ-RL	GAD53063 / AD53063-03Z		

Added Parts On This Revision - Product Family / Model Number (2)

AD6645 / AD6645ASVZ-80	AD6645 / AD80100ASVZ-80			
------------------------	-------------------------	--	--	--

Appendix B - Revision History			
Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	10-Dec-2014	01-Apr-2015	Initial Release
Rev. A	22-Jun-2015	22-Jun-2015	Including qualification result summaries for 7x7 10x10 12x12 TQFP_EP Using G700L_3230, 10x10 12x12 TQFP_EP Using G700L_8361J and 14x14 TQFP_EP Using G631HQ_3230. Remaining Qualification Plans updated to reflect new expected completion dates.
Rev. B	03-Aug-2015	31-Jan-2016	Reason for Change: Revised the estimated AK1 factory line shutdown date for 7x7, 10x10, and 14x14 body packages from Oct. and Nov. of 2015 to mid-year 2016. Update Attachment 7 to Qualification Results Summary for 14x14 LQFP Using G631HQ_3230_QMI536 at AP. Revised attachment 6 and 8: Expected qualification completion date by December 2015.
Rev. C	19-Oct-2015	17-Jan-2016	Add AD80100ASVZ-80 and AD6645ASVZ-80 to the affected parts list

Analog Devices, Inc.

DocId:3432 Parent DocId:None Layout Rev:7