



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001098I

DATE: 25-Sep-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1087LU-447+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1087LU-447+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1842AN+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1842AN+T&R	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1848B-050+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1848B-050+T&R	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1865T+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS1865T+T&R	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS2460S-W0B+1T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS2711ZB+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS2711ZB+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS28EL15X+U	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS28EL15X-04D-00+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS28EL15X-04D-00+U	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS8023-RRX+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	DS8023-RRX+T&R	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	IH5045CPE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1177AEUP+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX139EQH+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX139EQH+D	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14528ETA+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14528ETA+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14566EETA+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14566EETA+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14676DEWO+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14676DEWO+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Oct-2023

Discontinuance	MAX14681EWC+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14681EWC+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14690CEWX+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14690CEWX+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14704EWC+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14704EWC+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14745KEWX+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX14745KEWX+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX15025BATB+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX15025BATB+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX156BCNG+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1595ETC33+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1595ETC33+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16086US30E+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16086US30E+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16086US30E/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16086US30E/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16125WTDB29+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16125WTDB29+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16135HRR/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16135HRR/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16904RAUE18/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16904RAUE18/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16904RAUE50+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPA/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPA/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPJ/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPJ/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPK/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16922ATPK/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16930ATLS/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16930ATLS/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16932ATIS/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16932ATIS/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16932CATIR/VY+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16932CATIR/VY+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Oct-2023

Discontinuance	MAX16935CAUERB/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16935CAUERB/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJG+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJG/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJI+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJI+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJI/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX16993ATJI/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17041X+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17083ETG+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17083ETG+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17113ETL+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17113ETL+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17500AAUB+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX17500AAUB+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1864TEEE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1864TEEE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX1993ETG+TG40	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX199BCAI+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX199BCAI+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20012ATJB/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20012ATJB/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20019ATBJ/V+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20019ATBJ/V+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX2070GTM+CDZ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX2070GTM+TCDZ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20802TPBB+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX20802TPBB+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX274BC/D	MAX274AEWI+	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX28200EWC+TC01	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX28200EWC+UC01	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX32515/WDS+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX32565-LNJ+	N/A	25-Sep-2023	25-Sep-2023	The part was not released
Discontinuance	MAX32565-LNS+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX32565-LNS+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX32626ITK+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Oct-2023

Discontinuance	MAX32626ITK+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX32626ITK+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX3454EETE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX3454EETE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX3643ETG+G1N	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX3643ETG+TG1N	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX40016ATE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX40016ATE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4461HETT+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4461HETT+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4548EAX+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4548EAX+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4623CPE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4653ESE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4837ETT33BD3+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX4837ETT33BD3+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5068CAUE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5068CAUE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5110GTJ+TG074	MAX5113GTJ+TG074	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5201ACUB+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5201ACUB+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5434MEZT+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5434MEZT+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5774UTK+TG074	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5872EXE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5874EGK+	N/A	25-Sep-2023	25-Sep-2023	The part was not released
Discontinuance	MAX5874EGK+D	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5874EGK+TD	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5942BCSE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX5942BCSE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6129AEUK33+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6129AEUK33+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6337US22D3+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6337US22D3+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6348XR35+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6348XR35+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Oct-2023

Discontinuance	MAX6365HKA23+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6365HKA23+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6381XR27D3+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6381XR27D3+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6387XS28D2+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6387XS28D2+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6467XS33D3+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6467XS33D3+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6501UKP105+CBZ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6501UKP105+TCBZ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6719UTMSD1+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6719UTMSD1+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6752KA31/V+	N/A	25-Sep-2023	25-Sep-2023	The part was not released
Discontinuance	MAX6752KA31/V+T	N/A	25-Sep-2023	25-Sep-2023	The part was not released
Discontinuance	MAX6822WUK+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX6822WUK+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX691AEUE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX691AEUE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX7037EGL+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX7037EGL+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX7405EPA+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX77825AEWP+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX77825AEWP+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX77836EWZ+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX77836EWZ+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8212MTY	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8214ACPE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX822MUS+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX822MUS+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX825ZEXK+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX825ZEXK+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8596XETA+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8596XETA+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8791BGTA+	MAX17491GTA+	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8791BGTA+T	MAX17491GTA+	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8840ELT40+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Oct-2023

Discontinuance	MAX8840ELT40+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8841ELT29+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8841ELT29+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8896EREE+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8896EREE+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8968EWL+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX8968EWL+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9668ETP+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9668ETP+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+G45	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9986ETP+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9986ETP+D	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9986ETP+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9995ETX+	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	MAX9995ETX+T	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-BR	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-RR	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-BR	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-RR	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	VT241WFCX-ADJ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	VT261ABWFQX-ADJ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured
Discontinuance	VT267AWFQX-ADJ	N/A	25-Sep-2023	26-Mar-2025	Part can no longer be manufactured