

Production Change Note

Code: TS0201D-202103-00

page : 1/1

Customer :	All customers	Date	2021/Mar/22
Change Items :	AMPHENOL marking will be added on shell instead of housing surface.		
Change Reason :	Since both PBT and PA9T plastic mold with Amphenol logo were worn out, the shared tooling without logo is to step in as replacement instead. The only different of molding tools is with or without Amphenol logo.		
Change Range :	L17HTNXXXXXX, *SD*A4*, Right Angle, Military Footprint, Male and Female		

Before Change:

"AMPHENOL" marking on housing surface.

**After Change:**

AMPHENOL marking will be added on shell instead of housing surface



AMPHENOL marking
will be added on shell

Approved by : Tony

Prepared by : Bella

Date: 2021/Mar/12

Reply by Customer:

Approved by:

Date:

Remarks: Please confirm within three days in order to offer you the better products.

Amphenol will do the change after your approval.