



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1060

Issue Date: 8/21/2024

Parts Affected	SMFLP	Old Rev.	F	New Rev.	G
	SMFLP3		C		D
	SMFLP2		C		D

Change Will Affect:

This change will affect the product specifications.

Description of Change:

The recommended mounting hole nominal value and tolerances in the drawing have been adjusted to better fit the post dimension. (see old and new values below).

- Post dimension: .100"
- Old Mounting Hole dimension: .101" +.003/-0.002
- New Mounting Hole dimension: .100" +0/-0.005

Effective Date of Change: August 21, 2024

Reason for Change: Typographical error in the datasheet.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122