



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-020	Old Rev.	U	New Rev.	V
	939-030		U		V
	939-035		U		V
	939-040		U		V
	939-045		U		V
	939-050		U		V
	939-055		U		V
	939-060		U		V
	939-065		U		V
	939-070		U		V
	939-075		U		V
	939-080		U		V
	939-085		U		V
	939-090		U		V
	939-095		U		V
	939-1.000		U		V
	939-1.100		U		V
	939-1.125		U		V
	939-1.180		U		V
	939-1.250		U		V
	939-100		U		V
	939-105		U		V
	939-10MM		U		V
	939-110		U		V
	939-115		U		V
	939-11MM		U		V
	939-120		U		V
	939-125		U		V
	939-12MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-130	Old Rev.	U	New Rev.	V
	939-135		U		V
	939-13MM		U		V
	939-140		U		V
	939-145		U		V
	939-14MM		U		V
	939-150		U		V
	939-155		U		V
	939-15MM		U		V
	939-160		U		V
	939-165		U		V
	939-16MM		U		V
	939-170		U		V
	939-175		U		V
	939-180		U		V
	939-185		U		V
	939-190		U		V
	939-195		U		V
	939-1MM		U		V
	939-200		U		V
	939-205		U		V
	939-210		U		V
	939-215		U		V
	939-21MM		U		V
	939-220		U		V
	939-225		U		V
	939-22MM		U		V
	939-230		U		V
	939-235		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-240	Old Rev.	U	New Rev.	V
	939-245		U		V
	939-250		U		V
	939-255		U		V
	939-260		U		V
	939-265		U		V
	939-270		U		V
	939-275		U		V
	939-280		U		V
	939-285		U		V
	939-290		U		V
	939-295		U		V
	939-2MM		U		V
	939-300		U		V
	939-305		U		V
	939-310		U		V
	939-315		U		V
	939-31MM		U		V
	939-320		U		V
	939-325		U		V
	939-32MM		U		V
	939-330		U		V
	939-335		U		V
	939-340		U		V
	939-345		U		V
	939-350		U		V
	939-355		U		V
	939-360		U		V
	939-365		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-370	Old Rev.	U	New Rev.	V
	939-375		U		V
	939-380		U		V
	939-385		U		V
	939-390		U		V
	939-395		U		V
	939-3MM		U		V
	939-400		U		V
	939-405		U		V
	939-410		U		V
	939-415		U		V
	939-420		U		V
	939-425		U		V
	939-430		U		V
	939-435		U		V
	939-437		U		V
	939-440		U		V
	939-445		U		V
	939-450		U		V
	939-455		U		V
	939-460		U		V
	939-465		U		V
	939-470		U		V
	939-475		U		V
	939-480		U		V
	939-485		U		V
	939-490		U		V
	939-495		U		V
	939-4MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-500	Old Rev.	U	New Rev.	V
	939-505		U		V
	939-510		U		V
	939-515		U		V
	939-520		U		V
	939-525		U		V
	939-530		U		V
	939-535		U		V
	939-540		U		V
	939-545		U		V
	939-550		U		V
	939-555		U		V
	939-560		U		V
	939-565		U		V
	939-570		U		V
	939-575		U		V
	939-580		U		V
	939-585		U		V
	939-590		U		V
	939-595		U		V
	939-5MM		U		V
	939-600		U		V
	939-605		U		V
	939-610		U		V
	939-615		U		V
	939-620		U		V
	939-625		U		V
	939-630		U		V
	939-635		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-640	Old Rev.	U	New Rev.	V
	939-645		U		V
	939-650		U		V
	939-655		U		V
	939-660		U		V
	939-665		U		V
	939-670		U		V
	939-675		U		V
	939-680		U		V
	939-685		U		V
	939-690		U		V
	939-695		U		V
	939-6MM		U		V
	939-700		U		V
	939-705		U		V
	939-710		U		V
	939-715		U		V
	939-720		U		V
	939-725		U		V
	939-730		U		V
	939-735		U		V
	939-740		U		V
	939-745		U		V
	939-750		U		V
	939-755		U		V
	939-760		U		V
	939-765		U		V
	939-770		U		V
	939-775		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-780	Old Rev.	U	New Rev.	V
	939-785		U		V
	939-790		U		V
	939-795		U		V
	939-7MM		U		V
	939-800		U		V
	939-805		U		V
	939-810		U		V
	939-815		U		V
	939-820		U		V
	939-825		U		V
	939-830		U		V
	939-835		U		V
	939-840		U		V
	939-845		U		V
	939-850		U		V
	939-855		U		V
	939-860		U		V
	939-865		U		V
	939-870		U		V
	939-875		U		V
	939-880		U		V
	939-885		U		V
	939-890		U		V
	939-895		U		V
	939-8MM		U		V
	939-900		U		V
	939-905		U		V
	939-910		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	939-915	Old Rev.	U	New Rev.	V
	939-920		U		V
	939-925		U		V
	939-930		U		V
	939-935		U		V
	939-940		U		V
	939-945		U		V
	939-950		U		V
	939-9MM		U		V
	901-020		U		V
	901-030		U		V
	901-035		U		V
	901-040		U		V
	901-045		U		V
	901-050		U		V
	901-055		U		V
	901-060		U		V
	901-065		U		V
	901-070		U		V
	901-075		U		V
	901-080		U		V
	901-085		U		V
	901-090		U		V
	901-095		U		V
	901-1.000		U		V
	901-1.065		U		V
	901-1.125		U		V
	901-1.180		U		V
	901-1.250		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-100	Old Rev.	U	New Rev.	V
	901-105		U		V
	901-10MM		U		V
	901-110		U		V
	901-115		U		V
	901-11MM		U		V
	901-120		U		V
	901-120 GN		U		V
	901-125		U		V
	901-12MM		U		V
	901-130		U		V
	901-135		U		V
	901-13MM		U		V
	901-140		U		V
	901-145		U		V
	901-150		U		V
	901-155		U		V
	901-15MM		U		V
	901-160		U		V
	901-165		U		V
	901-16MM		U		V
	901-170		U		V
	901-175		U		V
	901-177		U		V
	901-17MM		U		V
	901-180		U		V
	901-185		U		V
	901-187		U		V
	901-18MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-190	Old Rev.	U	New Rev.	V
	901-195		U		V
	901-19MM		U		V
	901-1MM		U		V
	901-200		U		V
	901-205		U		V
	901-20MM		U		V
	901-210		U		V
	901-215		U		V
	901-21MM		U		V
	901-220		U		V
	901-225		U		V
	901-22MM		U		V
	901-230		U		V
	901-235		U		V
	901-240		U		V
	901-245		U		V
	901-250		U		V
	901-255		U		V
	901-260		U		V
	901-265		U		V
	901-270		U		V
	901-270 BE		U		V
	901-275		U		V
	901-280		U		V
	901-285		U		V
	901-290		U		V
	901-295		U		V
	901-295 BK		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-2MM	Old Rev.	U	New Rev.	V
	901-300		U		V
	901-305		U		V
	901-310		U		V
	901-315		U		V
	901-320		U		V
	901-325		U		V
	901-32MM		U		V
	901-330		U		V
	901-335		U		V
	901-340		U		V
	901-345		U		V
	901-350		U		V
	901-355		U		V
	901-360		U		V
	901-365		U		V
	901-370		U		V
	901-375		U		V
	901-380		U		V
	901-385		U		V
	901-390		U		V
	901-395		U		V
	901-3MM		U		V
	901-400		U		V
	901-405		U		V
	901-410		U		V
	901-415		U		V
	901-420		U		V
	901-425		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-430	Old Rev.	U	New Rev.	V
	901-435		U		V
	901-437		U		V
	901-440		U		V
	901-445		U		V
	901-450		U		V
	901-455		U		V
	901-460		U		V
	901-465		U		V
	901-470		U		V
	901-475		U		V
	901-480		U		V
	901-485		U		V
	901-490		U		V
	901-495		U		V
	901-4MM		U		V
	901-500		U		V
	901-505		U		V
	901-510		U		V
	901-515		U		V
	901-520		U		V
	901-525		U		V
	901-530		U		V
	901-535		U		V
	901-540		U		V
	901-545		U		V
	901-550		U		V
	901-555		U		V
	901-560		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-562	Old Rev.	U	New Rev.	V
	901-565		U		V
	901-570		U		V
	901-575		U		V
	901-580		U		V
	901-585		U		V
	901-590		U		V
	901-595		U		V
	901-5MM		U		V
	901-600		U		V
	901-605		U		V
	901-610		U		V
	901-615		U		V
	901-620		U		V
	901-625		U		V
	901-630		U		V
	901-635		U		V
	901-640		U		V
	901-645		U		V
	901-650		U		V
	901-655		U		V
	901-660		U		V
	901-665		U		V
	901-670		U		V
	901-675		U		V
	901-680		U		V
	901-685		U		V
	901-690		U		V
	901-695		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-6MM	Old Rev.	U	New Rev.	V
	901-700		U		V
	901-705		U		V
	901-710		U		V
	901-715		U		V
	901-720		U		V
	901-725		U		V
	901-730		U		V
	901-735		U		V
	901-740		U		V
	901-745		U		V
	901-750		U		V
	901-755		U		V
	901-760		U		V
	901-765		U		V
	901-770		U		V
	901-775		U		V
	901-780		U		V
	901-785		U		V
	901-790		U		V
	901-795		U		V
	901-7MM		U		V
	901-800		U		V
	901-805		U		V
	901-810		U		V
	901-815		U		V
	901-820		U		V
	901-825		U		V
	901-830		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-835	Old Rev.	U	New Rev.	V
	901-840		U		V
	901-845		U		V
	901-850		U		V
	901-855		U		V
	901-860		U		V
	901-865		U		V
	901-870		U		V
	901-875		U		V
	901-880		U		V
	901-885		U		V
	901-890		U		V
	901-895		U		V
	901-8MM		U		V
	901-900		U		V
	901-905		U		V
	901-910		U		V
	901-915		U		V
	901-920		U		V
	901-925		U		V
	901-930		U		V
	901-935		U		V
	901-940		U		V
	901-945		U		V
	901-950		U		V
	901-955		U		V
	901-960		U		V
	901-965		U		V
	901-970		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	901-975	Old Rev.	U	New Rev.	V
	901-980		U		V
	901-985		U		V
	901-990		U		V
	901-995		U		V
	901-9MM		U		V
	902-020		U		V
	902-030		U		V
	902-035		U		V
	902-040		U		V
	902-045		U		V
	902-050		U		V
	902-055		U		V
	902-060		U		V
	902-065		U		V
	902-070		U		V
	902-075		U		V
	902-080		U		V
	902-085		U		V
	902-090		U		V
	902-095		U		V
	902-1.000		U		V
	902-1.100		U		V
	902-1.125		U		V
	902-1.250		U		V
	902-100		U		V
	902-105		U		V
	902-10MM		U		V
	902-110		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-115	Old Rev.	U	New Rev.	V
	902-11MM		U		V
	902-120		U		V
	902-125		U		V
	902-12MM		U		V
	902-130		U		V
	902-135		U		V
	902-13MM		U		V
	902-140		U		V
	902-145		U		V
	902-150		U		V
	902-155		U		V
	902-15MM		U		V
	902-160		U		V
	902-165		U		V
	902-16MM		U		V
	902-170		U		V
	902-175		U		V
	902-17MM		U		V
	902-180		U		V
	902-185		U		V
	902-18MM		U		V
	902-190		U		V
	902-190-032		U		V
	902-195		U		V
	902-19MM		U		V
	902-1MM		U		V
	902-200		U		V
	902-205		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-20MM	Old Rev.	U	New Rev.	V
	902-210		U		V
	902-215		U		V
	902-220		U		V
	902-225		U		V
	902-230		U		V
	902-235		U		V
	902-240		U		V
	902-245		U		V
	902-250		U		V
	902-255		U		V
	902-260		U		V
	902-265		U		V
	902-270		U		V
	902-275		U		V
	902-280		U		V
	902-285		U		V
	902-290		U		V
	902-295		U		V
	902-2MM		U		V
	902-300		U		V
	902-305		U		V
	902-310		U		V
	902-312		U		V
	902-315		U		V
	902-320		U		V
	902-325		U		V
	902-32MM		U		V
	902-330		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-335	Old Rev.	U	New Rev.	V
	902-340		U		V
	902-345		U		V
	902-350		U		V
	902-355		U		V
	902-360		U		V
	902-365		U		V
	902-370		U		V
	902-375		U		V
	902-380		U		V
	902-385		U		V
	902-390		U		V
	902-395		U		V
	902-3MM		U		V
	902-400		U		V
	902-405		U		V
	902-410		U		V
	902-415		U		V
	902-420		U		V
	902-425		U		V
	902-430		U		V
	902-435		U		V
	902-437		U		V
	902-440		U		V
	902-445		U		V
	902-450		U		V
	902-455		U		V
	902-460		U		V
	902-465		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-470	Old Rev.	U	New Rev.	V
	902-475		U		V
	902-480		U		V
	902-485		U		V
	902-490		U		V
	902-495		U		V
	902-4MM		U		V
	902-500		U		V
	902-505		U		V
	902-510		U		V
	902-515		U		V
	902-520		U		V
	902-525		U		V
	902-530		U		V
	902-535		U		V
	902-540		U		V
	902-545		U		V
	902-550		U		V
	902-555		U		V
	902-560		U		V
	902-565		U		V
	902-570		U		V
	902-575		U		V
	902-580		U		V
	902-585		U		V
	902-590		U		V
	902-595		U		V
	902-5MM		U		V
	902-600		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-605	Old Rev.	U	New Rev.	V
	902-610		U		V
	902-615		U		V
	902-620		U		V
	902-625		U		V
	902-630		U		V
	902-635		U		V
	902-640		U		V
	902-645		U		V
	902-650		U		V
	902-655		U		V
	902-660		U		V
	902-665		U		V
	902-670		U		V
	902-675		U		V
	902-680		U		V
	902-685		U		V
	902-690		U		V
	902-695		U		V
	902-6MM		U		V
	902-700		U		V
	902-705		U		V
	902-710		U		V
	902-715		U		V
	902-720		U		V
	902-725		U		V
	902-730		U		V
	902-735		U		V
	902-740		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-745	Old Rev.	U	New Rev.	V
	902-750		U		V
	902-755		U		V
	902-760		U		V
	902-765		U		V
	902-770		U		V
	902-775		U		V
	902-780		U		V
	902-785		U		V
	902-790		U		V
	902-795		U		V
	902-7MM		U		V
	902-800		U		V
	902-805		U		V
	902-810		U		V
	902-815		U		V
	902-820		U		V
	902-825		U		V
	902-830		U		V
	902-835		U		V
	902-840		U		V
	902-845		U		V
	902-850		U		V
	902-855		U		V
	902-860		U		V
	902-865		U		V
	902-870		U		V
	902-875		U		V
	902-880		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	902-885	Old Rev.	U	New Rev.	V
	902-890		U		V
	902-8MM		U		V
	902-900		U		V
	902-905		U		V
	902-910		U		V
	902-915		U		V
	902-920		U		V
	902-925		U		V
	902-930		U		V
	902-935		U		V
	902-940		U		V
	902-945		U		V
	902-950		U		V
	902-955		U		V
	902-960		U		V
	902-965		U		V
	902-970		U		V
	902-975		U		V
	902-980		U		V
	902-985		U		V
	902-990		U		V
	902-995		U		V
	902-9MM		U		V
	903-030		U		V
	903-035		U		V
	903-040		U		V
	903-045		U		V
	903-050		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-055	Old Rev.	U	New Rev.	V
	903-060		U		V
	903-065		U		V
	903-065 BK		U		V
	903-070		U		V
	903-075		U		V
	903-080		U		V
	903-085		U		V
	903-090		U		V
	903-095		U		V
	903-1.000		U		V
	903-1.060		U		V
	903-1.065		U		V
	903-1.125		U		V
	903-1.250		U		V
	903-100		U		V
	903-100 BK		U		V
	903-105		U		V
	903-10MM		U		V
	903-110		U		V
	903-115		U		V
	903-11MM		U		V
	903-120		U		V
	903-125		U		V
	903-12MM		U		V
	903-130		U		V
	903-135		U		V
	903-140		U		V
	903-145		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-14MM	Old Rev.	U	New Rev.	V
	903-150		U		V
	903-155		U		V
	903-15MM		U		V
	903-160		U		V
	903-165		U		V
	903-16MM		U		V
	903-170		U		V
	903-175		U		V
	903-180		U		V
	903-185		U		V
	903-187		U		V
	903-18MM		U		V
	903-190		U		V
	903-195		U		V
	903-1MM		U		V
	903-200		U		V
	903-205		U		V
	903-20MM		U		V
	903-210		U		V
	903-215		U		V
	903-220		U		V
	903-225		U		V
	903-230		U		V
	903-235		U		V
	903-240		U		V
	903-245		U		V
	903-24MM		U		V
	903-250		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-255	Old Rev.	U	New Rev.	V
	903-260		U		V
	903-265		U		V
	903-270		U		V
	903-275		U		V
	903-280		U		V
	903-285		U		V
	903-290		U		V
	903-295		U		V
	903-2MM		U		V
	903-300		U		V
	903-305		U		V
	903-310		U		V
	903-315		U		V
	903-320		U		V
	903-325		U		V
	903-330		U		V
	903-335		U		V
	903-340		U		V
	903-345		U		V
	903-350		U		V
	903-355		U		V
	903-360		U		V
	903-365		U		V
	903-370		U		V
	903-375		U		V
	903-380		U		V
	903-385		U		V
	903-390		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-395	Old Rev.	U	New Rev.	V
	903-3MM		U		V
	903-400		U		V
	903-405		U		V
	903-410		U		V
	903-415		U		V
	903-420		U		V
	903-425		U		V
	903-430		U		V
	903-435		U		V
	903-440		U		V
	903-445		U		V
	903-450		U		V
	903-455		U		V
	903-460		U		V
	903-465		U		V
	903-470		U		V
	903-475		U		V
	903-480		U		V
	903-485		U		V
	903-490		U		V
	903-495		U		V
	903-4MM		U		V
	903-500		U		V
	903-505		U		V
	903-510		U		V
	903-515		U		V
	903-520		U		V
	903-525		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-530	Old Rev.	U	New Rev.	V
	903-535		U		V
	903-540		U		V
	903-545		U		V
	903-550		U		V
	903-555		U		V
	903-560		U		V
	903-565		U		V
	903-570		U		V
	903-575		U		V
	903-580		U		V
	903-585		U		V
	903-590		U		V
	903-595		U		V
	903-5MM		U		V
	903-600		U		V
	903-605		U		V
	903-610		U		V
	903-615		U		V
	903-620		U		V
	903-625		U		V
	903-630		U		V
	903-635		U		V
	903-640		U		V
	903-645		U		V
	903-650		U		V
	903-655		U		V
	903-660		U		V
	903-665		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-670	Old Rev.	U	New Rev.	V
	903-675		U		V
	903-680		U		V
	903-685		U		V
	903-690		U		V
	903-695		U		V
	903-6MM		U		V
	903-700		U		V
	903-705		U		V
	903-710		U		V
	903-715		U		V
	903-720		U		V
	903-725		U		V
	903-730		U		V
	903-735		U		V
	903-740		U		V
	903-745		U		V
	903-750		U		V
	903-755		U		V
	903-760		U		V
	903-765		U		V
	903-770		U		V
	903-775		U		V
	903-780		U		V
	903-785		U		V
	903-790		U		V
	903-795		U		V
	903-7MM		U		V
	903-800		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	903-805	Old Rev.	U	New Rev.	V
	903-810		U		V
	903-815		U		V
	903-820		U		V
	903-825		U		V
	903-830		U		V
	903-835		U		V
	903-840		U		V
	903-845		U		V
	903-850		U		V
	903-855		U		V
	903-860		U		V
	903-865		U		V
	903-870		U		V
	903-875		U		V
	903-880		U		V
	903-885		U		V
	903-890		U		V
	903-895		U		V
	903-8MM		U		V
	903-900		U		V
	903-935		U		V
	903-940		U		V
	903-995		U		V
	903-9MM		U		V
	904-020		U		V
	904-030		U		V
	904-035		U		V
	904-040		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	904-045	Old Rev.	U	New Rev.	V
	904-050		U		V
	904-055		U		V
	904-060		U		V
	904-065		U		V
	904-070		U		V
	904-075		U		V
	904-080		U		V
	904-085		U		V
	904-090		U		V
	904-095		U		V
	904-1.000		U		V
	904-1.065		U		V
	904-1.125		U		V
	904-1.250		U		V
	904-100		U		V
	904-105		U		V
	904-10MM		U		V
	904-110		U		V
	904-115		U		V
	904-11MM		U		V
	904-120		U		V
	904-125		U		V
	904-12MM		U		V
	904-130		U		V
	904-135		U		V
	904-13MM		U		V
	904-140		U		V
	904-150		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	904-155	Old Rev.	U	New Rev.	V
	904-15MM		U		V
	904-160		U		V
	904-165		U		V
	904-170		U		V
	904-175		U		V
	904-180		U		V
	904-185		U		V
	904-187		U		V
	904-190		U		V
	904-195		U		V
	904-1MM		U		V
	904-200		U		V
	904-205		U		V
	904-20MM		U		V
	904-210		U		V
	904-220		U		V
	904-225		U		V
	904-22MM		U		V
	904-230		U		V
	904-235		U		V
	904-240		U		V
	904-245		U		V
	904-250		U		V
	904-255		U		V
	904-260		U		V
	904-270		U		V
	904-275		U		V
	904-280		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	904-290	Old Rev.	U	New Rev.	V
	904-295		U		V
	904-2MM		U		V
	904-300		U		V
	904-310		U		V
	904-315		U		V
	904-320		U		V
	904-325		U		V
	904-330		U		V
	904-335		U		V
	904-340		U		V
	904-345		U		V
	904-350		U		V
	904-355		U		V
	904-360		U		V
	904-370		U		V
	904-375		U		V
	904-375 BK		U		V
	904-380		U		V
	904-385		U		V
	904-390		U		V
	904-395		U		V
	904-3MM		U		V
	904-400		U		V
	904-410		U		V
	904-415		U		V
	904-425		U		V
	904-435		U		V
	904-440		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	904-450	Old Rev.	U	New Rev.	V
	904-460		U		V
	904-470		U		V
	904-495		U		V
	904-4MM		U		V
	904-500		U		V
	904-510		U		V
	904-550		U		V
	904-560		U		V
	904-565		U		V
	904-570		U		V
	904-5MM		U		V
	904-600		U		V
	904-620		U		V
	904-625		U		V
	904-640		U		V
	904-645		U		V
	904-650		U		V
	904-680		U		V
	904-685		U		V
	904-690		U		V
	904-6MM		U		V
	904-710		U		V
	904-750		U		V
	904-755		U		V
	904-780		U		V
	904-7MM		U		V
	904-800		U		V
	904-810		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	904-815	Old Rev.	U	New Rev.	V
	904-845		U		V
	904-850		U		V
	904-875		U		V
	904-8MM		U		V
	904-940		U		V
	904-975		U		V
	904-9MM		U		V
	905-030		U		V
	905-035		U		V
	905-040		U		V
	905-045		U		V
	905-050		U		V
	905-050 BK		U		V
	905-055		U		V
	905-060		U		V
	905-065		U		V
	905-070		U		V
	905-070 BE		U		V
	905-070 RD		U		V
	905-075		U		V
	905-080		U		V
	905-085		U		V
	905-090		U		V
	905-095		U		V
	905-1.000		U		V
	905-1.015		U		V
	905-1.030		U		V
	905-1.050		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-1.060	Old Rev.	U	New Rev.	V
	905-1.065		U		V
	905-1.070		U		V
	905-1.075		U		V
	905-1.100		U		V
	905-1.120		U		V
	905-1.125		U		V
	905-1.130		U		V
	905-1.150		U		V
	905-1.150 BK		U		V
	905-1.160		U		V
	905-1.170		U		V
	905-1.175		U		V
	905-1.180		U		V
	905-1.185		U		V
	905-1.190		U		V
	905-1.210		U		V
	905-1.250		U		V
	905-1.310		U		V
	905-1.310-test		U		V
	905-1.335		U		V
	905-1.375		U		V
	905-1.500		U		V
	905-1.560		U		V
	905-100		U		V
	905-105		U		V
	905-10MM		U		V
	905-110		U		V
	905-115		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-11MM	Old Rev.	U	New Rev.	V
	905-120		U		V
	905-125		U		V
	905-125-test		U		V
	905-12MM		U		V
	905-130		U		V
	905-135		U		V
	905-140		U		V
	905-140 BE		U		V
	905-140 RD		U		V
	905-145		U		V
	905-14MM		U		V
	905-150		U		V
	905-155		U		V
	905-15MM		U		V
	905-160		U		V
	905-165		U		V
	905-16MM		U		V
	905-170		U		V
	905-175		U		V
	905-175 BK		U		V
	905-17MM		U		V
	905-180		U		V
	905-185		U		V
	905-190		U		V
	905-195		U		V
	905-19MM		U		V
	905-1MM		U		V
	905-200		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-205	Old Rev.	U	New Rev.	V
	905-20MM		U		V
	905-210		U		V
	905-215		U		V
	905-21MM		U		V
	905-220		U		V
	905-225		U		V
	905-22MM		U		V
	905-230		U		V
	905-235		U		V
	905-240		U		V
	905-245		U		V
	905-250		U		V
	905-250 BK		U		V
	905-255		U		V
	905-260		U		V
	905-265		U		V
	905-270		U		V
	905-275		U		V
	905-280		U		V
	905-285		U		V
	905-28MM		U		V
	905-290		U		V
	905-295		U		V
	905-2MM		U		V
	905-300		U		V
	905-300 BK		U		V
	905-305		U		V
	905-310		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-315	Old Rev.	U	New Rev.	V
	905-320		U		V
	905-325		U		V
	905-330		U		V
	905-335		U		V
	905-340		U		V
	905-345		U		V
	905-350		U		V
	905-355		U		V
	905-360		U		V
	905-365		U		V
	905-370		U		V
	905-375		U		V
	905-380		U		V
	905-385		U		V
	905-390		U		V
	905-395		U		V
	905-3MM		U		V
	905-400		U		V
	905-405		U		V
	905-410		U		V
	905-415		U		V
	905-420		U		V
	905-425		U		V
	905-430		U		V
	905-435		U		V
	905-440		U		V
	905-445		U		V
	905-450		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-455	Old Rev.	U	New Rev.	V
	905-460		U		V
	905-465		U		V
	905-470		U		V
	905-475		U		V
	905-480		U		V
	905-485		U		V
	905-490		U		V
	905-495		U		V
	905-4MM		U		V
	905-500		U		V
	905-505		U		V
	905-510		U		V
	905-515		U		V
	905-520		U		V
	905-525		U		V
	905-530		U		V
	905-535		U		V
	905-540		U		V
	905-545		U		V
	905-550		U		V
	905-555		U		V
	905-560		U		V
	905-565		U		V
	905-570		U		V
	905-575		U		V
	905-580		U		V
	905-585		U		V
	905-590		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-595	Old Rev.	U	New Rev.	V
	905-5MM		U		V
	905-600		U		V
	905-605		U		V
	905-610		U		V
	905-615		U		V
	905-620		U		V
	905-625		U		V
	905-630		U		V
	905-635		U		V
	905-640		U		V
	905-645		U		V
	905-650		U		V
	905-655		U		V
	905-660		U		V
	905-665		U		V
	905-670		U		V
	905-675		U		V
	905-680		U		V
	905-685		U		V
	905-690		U		V
	905-695		U		V
	905-6MM		U		V
	905-700		U		V
	905-705		U		V
	905-710		U		V
	905-715		U		V
	905-720		U		V
	905-725		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-730	Old Rev.	U	New Rev.	V
	905-735		U		V
	905-740		U		V
	905-745		U		V
	905-750		U		V
	905-755		U		V
	905-760		U		V
	905-765		U		V
	905-770		U		V
	905-775		U		V
	905-780		U		V
	905-785		U		V
	905-790		U		V
	905-795		U		V
	905-7MM		U		V
	905-800		U		V
	905-805		U		V
	905-810		U		V
	905-815		U		V
	905-820		U		V
	905-825		U		V
	905-830		U		V
	905-835		U		V
	905-840		U		V
	905-845		U		V
	905-850		U		V
	905-855		U		V
	905-860		U		V
	905-865		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	905-870	Old Rev.	U	New Rev.	V
	905-875		U		V
	905-880		U		V
	905-885		U		V
	905-890		U		V
	905-895		U		V
	905-8MM		U		V
	905-900		U		V
	905-905		U		V
	905-910		U		V
	905-915		U		V
	905-920		U		V
	905-925		U		V
	905-930		U		V
	905-935		U		V
	905-940		U		V
	905-945		U		V
	905-950		U		V
	905-955		U		V
	905-960		U		V
	905-965		U		V
	905-970		U		V
	905-975		U		V
	905-980		U		V
	905-985		U		V
	905-990		U		V
	905-995		U		V
	905-9MM		U		V
	906-030		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-035	Old Rev.	U	New Rev.	V
	906-040		U		V
	906-045		U		V
	906-050		U		V
	906-055		U		V
	906-060		U		V
	906-065		U		V
	906-070		U		V
	906-075		U		V
	906-080		U		V
	906-085		U		V
	906-090		U		V
	906-095		U		V
	906-1.000		U		V
	906-1.125		U		V
	906-1.200		U		V
	906-1.250		U		V
	906-100		U		V
	906-105		U		V
	906-10MM		U		V
	906-110		U		V
	906-115		U		V
	906-11MM		U		V
	906-120		U		V
	906-125		U		V
	906-12MM		U		V
	906-130		U		V
	906-135		U		V
	906-140		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-145	Old Rev.	U	New Rev.	V
	906-14MM		U		V
	906-150		U		V
	906-155		U		V
	906-160		U		V
	906-165		U		V
	906-16MM		U		V
	906-170		U		V
	906-175		U		V
	906-180		U		V
	906-185		U		V
	906-189		U		V
	906-190		U		V
	906-195		U		V
	906-1MM		U		V
	906-200		U		V
	906-205		U		V
	906-20MM		U		V
	906-210		U		V
	906-215		U		V
	906-220		U		V
	906-225		U		V
	906-22MM		U		V
	906-230		U		V
	906-235		U		V
	906-240		U		V
	906-245		U		V
	906-250		U		V
	906-255		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-260	Old Rev.	U	New Rev.	V
	906-265		U		V
	906-270		U		V
	906-275		U		V
	906-275 BK		U		V
	906-280		U		V
	906-285		U		V
	906-290		U		V
	906-295		U		V
	906-2MM		U		V
	906-300		U		V
	906-305		U		V
	906-30MM		U		V
	906-310		U		V
	906-315		U		V
	906-320		U		V
	906-325		U		V
	906-330		U		V
	906-335		U		V
	906-340		U		V
	906-345		U		V
	906-350		U		V
	906-355		U		V
	906-360		U		V
	906-365		U		V
	906-370		U		V
	906-375		U		V
	906-375 BK		U		V
	906-380		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-385	Old Rev.	U	New Rev.	V
	906-390		U		V
	906-395		U		V
	906-3MM		U		V
	906-400		U		V
	906-405		U		V
	906-410		U		V
	906-415		U		V
	906-420		U		V
	906-425		U		V
	906-430		U		V
	906-435		U		V
	906-440		U		V
	906-445		U		V
	906-450		U		V
	906-455		U		V
	906-460		U		V
	906-465		U		V
	906-470		U		V
	906-475		U		V
	906-480		U		V
	906-485		U		V
	906-490		U		V
	906-495		U		V
	906-4MM		U		V
	906-500		U		V
	906-505		U		V
	906-510		U		V
	906-515		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-520	Old Rev.	U	New Rev.	V
	906-525		U		V
	906-530		U		V
	906-535		U		V
	906-540		U		V
	906-545		U		V
	906-550		U		V
	906-555		U		V
	906-560		U		V
	906-565		U		V
	906-570		U		V
	906-575		U		V
	906-580		U		V
	906-585		U		V
	906-590		U		V
	906-595		U		V
	906-5MM		U		V
	906-600		U		V
	906-605		U		V
	906-610		U		V
	906-615		U		V
	906-620		U		V
	906-625		U		V
	906-630		U		V
	906-635		U		V
	906-640		U		V
	906-645		U		V
	906-650		U		V
	906-655		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-660	Old Rev.	U	New Rev.	V
	906-665		U		V
	906-670		U		V
	906-675		U		V
	906-680		U		V
	906-685		U		V
	906-690		U		V
	906-695		U		V
	906-6MM		U		V
	906-700		U		V
	906-705		U		V
	906-710		U		V
	906-715		U		V
	906-720		U		V
	906-725		U		V
	906-730		U		V
	906-735		U		V
	906-740		U		V
	906-745		U		V
	906-750		U		V
	906-755		U		V
	906-760		U		V
	906-765		U		V
	906-770		U		V
	906-775		U		V
	906-780		U		V
	906-785		U		V
	906-790		U		V
	906-795		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-7MM	Old Rev.	U	New Rev.	V
	906-800		U		V
	906-805		U		V
	906-810		U		V
	906-815		U		V
	906-820		U		V
	906-825		U		V
	906-830		U		V
	906-835		U		V
	906-840		U		V
	906-845		U		V
	906-850		U		V
	906-855		U		V
	906-860		U		V
	906-865		U		V
	906-870		U		V
	906-875		U		V
	906-880		U		V
	906-885		U		V
	906-890		U		V
	906-895		U		V
	906-8MM		U		V
	906-900		U		V
	906-905		U		V
	906-910		U		V
	906-915		U		V
	906-920		U		V
	906-925		U		V
	906-930		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	906-935	Old Rev.	U	New Rev.	V
	906-940		U		V
	906-945		U		V
	906-950		U		V
	906-955		U		V
	906-960		U		V
	906-965		U		V
	906-970		U		V
	906-975		U		V
	906-980		U		V
	906-985		U		V
	906-990		U		V
	906-995		U		V
	906-9MM		U		V
	907-030		U		V
	907-035		U		V
	907-040		U		V
	907-045		U		V
	907-050		U		V
	907-055		U		V
	907-060		U		V
	907-063		U		V
	907-065		U		V
	907-070		U		V
	907-075		U		V
	907-080		U		V
	907-085		U		V
	907-090		U		V
	907-095		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-1.000	Old Rev.	U	New Rev.	V
	907-1.115		U		V
	907-1.125		U		V
	907-1.150		U		V
	907-1.155		U		V
	907-1.200		U		V
	907-1.250		U		V
	907-1.6MM		U		V
	907-100		U		V
	907-105		U		V
	907-10MM		U		V
	907-110		U		V
	907-115		U		V
	907-11MM		U		V
	907-120		U		V
	907-125		U		V
	907-12MM		U		V
	907-130		U		V
	907-135		U		V
	907-13MM		U		V
	907-140		U		V
	907-145		U		V
	907-14MM		U		V
	907-150		U		V
	907-155		U		V
	907-15MM		U		V
	907-160		U		V
	907-165		U		V
	907-16MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-170	Old Rev.	U	New Rev.	V
	907-175		U		V
	907-17MM		U		V
	907-180		U		V
	907-185		U		V
	907-18MM		U		V
	907-190		U		V
	907-195		U		V
	907-19MM		U		V
	907-1MM		U		V
	907-2.5MM		U		V
	907-200		U		V
	907-205		U		V
	907-20MM		U		V
	907-210		U		V
	907-215		U		V
	907-220		U		V
	907-225		U		V
	907-230		U		V
	907-235		U		V
	907-240		U		V
	907-245		U		V
	907-250		U		V
	907-255		U		V
	907-260		U		V
	907-265		U		V
	907-270		U		V
	907-275		U		V
	907-280		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-285	Old Rev.	U	New Rev.	V
	907-290		U		V
	907-295		U		V
	907-2MM		U		V
	907-300		U		V
	907-305		U		V
	907-310		U		V
	907-315		U		V
	907-320		U		V
	907-325		U		V
	907-330		U		V
	907-335		U		V
	907-340		U		V
	907-345		U		V
	907-350		U		V
	907-355		U		V
	907-360		U		V
	907-365		U		V
	907-370		U		V
	907-375		U		V
	907-380		U		V
	907-385		U		V
	907-390		U		V
	907-395		U		V
	907-3MM		U		V
	907-400		U		V
	907-405		U		V
	907-410		U		V
	907-415		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-420	Old Rev.	U	New Rev.	V
	907-425		U		V
	907-430		U		V
	907-435		U		V
	907-437		U		V
	907-440		U		V
	907-445		U		V
	907-450		U		V
	907-455		U		V
	907-460		U		V
	907-465		U		V
	907-470		U		V
	907-475		U		V
	907-480		U		V
	907-485		U		V
	907-490		U		V
	907-495		U		V
	907-4MM		U		V
	907-500		U		V
	907-505		U		V
	907-510		U		V
	907-515		U		V
	907-520		U		V
	907-525		U		V
	907-530		U		V
	907-535		U		V
	907-540		U		V
	907-545		U		V
	907-550		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-555	Old Rev.	U	New Rev.	V
	907-560		U		V
	907-565		U		V
	907-570		U		V
	907-575		U		V
	907-580		U		V
	907-585		U		V
	907-590		U		V
	907-595		U		V
	907-5MM		U		V
	907-600		U		V
	907-605		U		V
	907-610		U		V
	907-615		U		V
	907-620		U		V
	907-625		U		V
	907-630		U		V
	907-635		U		V
	907-640		U		V
	907-645		U		V
	907-650		U		V
	907-655		U		V
	907-660		U		V
	907-665		U		V
	907-670		U		V
	907-675		U		V
	907-680		U		V
	907-685		U		V
	907-690		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-695	Old Rev.	U	New Rev.	V
	907-6MM		U		V
	907-700		U		V
	907-705		U		V
	907-710		U		V
	907-715		U		V
	907-720		U		V
	907-725		U		V
	907-730		U		V
	907-735		U		V
	907-740		U		V
	907-745		U		V
	907-750		U		V
	907-755		U		V
	907-760		U		V
	907-765		U		V
	907-770		U		V
	907-775		U		V
	907-780		U		V
	907-785		U		V
	907-790		U		V
	907-795		U		V
	907-7MM		U		V
	907-800		U		V
	907-805		U		V
	907-810		U		V
	907-815		U		V
	907-820		U		V
	907-825		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-830	Old Rev.	U	New Rev.	V
	907-835		U		V
	907-840		U		V
	907-845		U		V
	907-850		U		V
	907-855		U		V
	907-860		U		V
	907-865		U		V
	907-870		U		V
	907-875		U		V
	907-880		U		V
	907-885		U		V
	907-890		U		V
	907-895		U		V
	907-8MM		U		V
	907-900		U		V
	907-905		U		V
	907-910		U		V
	907-915		U		V
	907-920		U		V
	907-925		U		V
	907-930		U		V
	907-935		U		V
	907-940		U		V
	907-945		U		V
	907-950		U		V
	907-955		U		V
	907-960		U		V
	907-965		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	907-970	Old Rev.	U	New Rev.	V
	907-975		U		V
	907-980		U		V
	907-985		U		V
	907-990		U		V
	907-995		U		V
	907-9MM		U		V
	908-030		U		V
	908-035		U		V
	908-040		U		V
	908-045		U		V
	908-050		U		V
	908-055		U		V
	908-060		U		V
	908-065		U		V
	908-070		U		V
	908-075		U		V
	908-080		U		V
	908-085		U		V
	908-090		U		V
	908-095		U		V
	908-1.000		U		V
	908-1.080		U		V
	908-1.120		U		V
	908-1.125		U		V
	908-1.155		U		V
	908-1.160		U		V
	908-1.180		U		V
	908-1.200		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-1.250	Old Rev.	U	New Rev.	V
	908-100		U		V
	908-105		U		V
	908-10MM		U		V
	908-110		U		V
	908-115		U		V
	908-11MM		U		V
	908-120		U		V
	908-120 BK		U		V
	908-125		U		V
	908-12MM		U		V
	908-130		U		V
	908-135		U		V
	908-13MM		U		V
	908-140		U		V
	908-145		U		V
	908-14MM		U		V
	908-150		U		V
	908-155		U		V
	908-15MM		U		V
	908-160		U		V
	908-165		U		V
	908-170		U		V
	908-175		U		V
	908-17MM		U		V
	908-180		U		V
	908-180 BK		U		V
	908-185		U		V
	908-18MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-190	Old Rev.	U	New Rev.	V
	908-195		U		V
	908-19MM		U		V
	908-1MM		U		V
	908-2.5MM		U		V
	908-200		U		V
	908-200 OE		U		V
	908-205		U		V
	908-20MM		U		V
	908-210		U		V
	908-215		U		V
	908-21MM		U		V
	908-220		U		V
	908-225		U		V
	908-22MM		U		V
	908-230		U		V
	908-235		U		V
	908-23MM		U		V
	908-240		U		V
	908-245		U		V
	908-24MM		U		V
	908-250		U		V
	908-255		U		V
	908-25MM		U		V
	908-260		U		V
	908-265		U		V
	908-26MM		U		V
	908-270		U		V
	908-275		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-280	Old Rev.	U	New Rev.	V
	908-285		U		V
	908-290		U		V
	908-295		U		V
	908-2MM		U		V
	908-300		U		V
	908-305		U		V
	908-310		U		V
	908-315		U		V
	908-315 BE		U		V
	908-315 BK		U		V
	908-320		U		V
	908-325		U		V
	908-32MM		U		V
	908-330		U		V
	908-335		U		V
	908-335 BE		U		V
	908-340		U		V
	908-345		U		V
	908-350		U		V
	908-355		U		V
	908-360		U		V
	908-365		U		V
	908-370		U		V
	908-375		U		V
	908-380		U		V
	908-385		U		V
	908-390		U		V
	908-395		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-3MM	Old Rev.	U	New Rev.	V
	908-400		U		V
	908-405		U		V
	908-410		U		V
	908-415		U		V
	908-415 RD		U		V
	908-420		U		V
	908-425		U		V
	908-430		U		V
	908-435		U		V
	908-440		U		V
	908-445		U		V
	908-450		U		V
	908-455		U		V
	908-460		U		V
	908-460 BK		U		V
	908-465		U		V
	908-470		U		V
	908-470 BK		U		V
	908-475		U		V
	908-480		U		V
	908-485		U		V
	908-490		U		V
	908-495		U		V
	908-4MM		U		V
	908-500		U		V
	908-505		U		V
	908-510		U		V
	908-515		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-520	Old Rev.	U	New Rev.	V
	908-520 BK		U		V
	908-525		U		V
	908-530		U		V
	908-535		U		V
	908-540		U		V
	908-545		U		V
	908-550		U		V
	908-555		U		V
	908-560		U		V
	908-565		U		V
	908-570		U		V
	908-575		U		V
	908-580		U		V
	908-585		U		V
	908-590		U		V
	908-595		U		V
	908-5MM		U		V
	908-600		U		V
	908-605		U		V
	908-610		U		V
	908-615		U		V
	908-620		U		V
	908-625		U		V
	908-630		U		V
	908-635		U		V
	908-640		U		V
	908-645		U		V
	908-650		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-655	Old Rev.	U	New Rev.	V
	908-660		U		V
	908-665		U		V
	908-670		U		V
	908-675		U		V
	908-680		U		V
	908-685		U		V
	908-690		U		V
	908-695		U		V
	908-6MM		U		V
	908-700		U		V
	908-705		U		V
	908-710		U		V
	908-715		U		V
	908-720		U		V
	908-725		U		V
	908-730		U		V
	908-735		U		V
	908-740		U		V
	908-745		U		V
	908-750		U		V
	908-755		U		V
	908-760		U		V
	908-765		U		V
	908-770		U		V
	908-775		U		V
	908-780		U		V
	908-785		U		V
	908-790		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-795	Old Rev.	U	New Rev.	V
	908-7MM		U		V
	908-800		U		V
	908-805		U		V
	908-810		U		V
	908-815		U		V
	908-820		U		V
	908-825		U		V
	908-830		U		V
	908-835		U		V
	908-840		U		V
	908-845		U		V
	908-850		U		V
	908-855		U		V
	908-860		U		V
	908-865		U		V
	908-870		U		V
	908-875		U		V
	908-880		U		V
	908-885		U		V
	908-890		U		V
	908-895		U		V
	908-8MM		U		V
	908-900		U		V
	908-905		U		V
	908-910		U		V
	908-915		U		V
	908-920		U		V
	908-925		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	908-930	Old Rev.	U	New Rev.	V
	908-935		U		V
	908-940		U		V
	908-945		U		V
	908-950		U		V
	908-955		U		V
	908-960		U		V
	908-965		U		V
	908-970		U		V
	908-975		U		V
	908-980		U		V
	908-985		U		V
	908-990		U		V
	908-995		U		V
	908-9MM		U		V
	911-030		U		V
	911-035		U		V
	911-040		U		V
	911-045		U		V
	911-050		U		V
	911-055		U		V
	911-060		U		V
	911-065		U		V
	911-070		U		V
	911-075		U		V
	911-080		U		V
	911-085		U		V
	911-090		U		V
	911-095		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-1.000	Old Rev.	U	New Rev.	V
	911-1.065		U		V
	911-1.105		U		V
	911-1.125		U		V
	911-1.130		U		V
	911-1.170		U		V
	911-1.185		U		V
	911-1.190		U		V
	911-1.200		U		V
	911-1.250		U		V
	911-100		U		V
	911-105		U		V
	911-10MM		U		V
	911-10MM-test		U		V
	911-110		U		V
	911-115		U		V
	911-120		U		V
	911-125		U		V
	911-12MM		U		V
	911-130		U		V
	911-135		U		V
	911-13MM		U		V
	911-140		U		V
	911-145		U		V
	911-14MM		U		V
	911-150		U		V
	911-155		U		V
	911-15MM		U		V
	911-160		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-165	Old Rev.	U	New Rev.	V
	911-16MM		U		V
	911-170		U		V
	911-175		U		V
	911-17MM		U		V
	911-180		U		V
	911-185		U		V
	911-18MM		U		V
	911-190		U		V
	911-195		U		V
	911-1MM		U		V
	911-200		U		V
	911-205		U		V
	911-210		U		V
	911-215		U		V
	911-220		U		V
	911-225		U		V
	911-230		U		V
	911-235		U		V
	911-240		U		V
	911-245		U		V
	911-250		U		V
	911-255		U		V
	911-260		U		V
	911-265		U		V
	911-270		U		V
	911-275		U		V
	911-280		U		V
	911-285		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-28MM	Old Rev.	U	New Rev.	V
	911-290		U		V
	911-295		U		V
	911-2MM		U		V
	911-300		U		V
	911-305		U		V
	911-310		U		V
	911-315		U		V
	911-320		U		V
	911-325		U		V
	911-330		U		V
	911-335		U		V
	911-340		U		V
	911-345		U		V
	911-350		U		V
	911-355		U		V
	911-360		U		V
	911-365		U		V
	911-370		U		V
	911-375		U		V
	911-380		U		V
	911-385		U		V
	911-390		U		V
	911-395		U		V
	911-3MM		U		V
	911-400		U		V
	911-405		U		V
	911-40MM		U		V
	911-410		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-415	Old Rev.	U	New Rev.	V
	911-420		U		V
	911-425		U		V
	911-430		U		V
	911-435		U		V
	911-437		U		V
	911-440		U		V
	911-445		U		V
	911-450		U		V
	911-455		U		V
	911-460		U		V
	911-465		U		V
	911-470		U		V
	911-475		U		V
	911-480		U		V
	911-485		U		V
	911-490		U		V
	911-495		U		V
	911-4MM		U		V
	911-500		U		V
	911-505		U		V
	911-510		U		V
	911-515		U		V
	911-520		U		V
	911-525		U		V
	911-530		U		V
	911-535		U		V
	911-540		U		V
	911-545		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-550	Old Rev.	U	New Rev.	V
	911-555		U		V
	911-560		U		V
	911-565		U		V
	911-570		U		V
	911-575		U		V
	911-580		U		V
	911-585		U		V
	911-590		U		V
	911-595		U		V
	911-5MM		U		V
	911-600		U		V
	911-605		U		V
	911-610		U		V
	911-615		U		V
	911-620		U		V
	911-625		U		V
	911-630		U		V
	911-635		U		V
	911-640		U		V
	911-645		U		V
	911-650		U		V
	911-655		U		V
	911-660		U		V
	911-665		U		V
	911-670		U		V
	911-675		U		V
	911-680		U		V
	911-685		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-690	Old Rev.	U	New Rev.	V
	911-695		U		V
	911-6MM		U		V
	911-700		U		V
	911-705		U		V
	911-710		U		V
	911-715		U		V
	911-720		U		V
	911-725		U		V
	911-730		U		V
	911-735		U		V
	911-740		U		V
	911-745		U		V
	911-750		U		V
	911-755		U		V
	911-760		U		V
	911-765		U		V
	911-770		U		V
	911-775		U		V
	911-780		U		V
	911-785		U		V
	911-790		U		V
	911-795		U		V
	911-7MM		U		V
	911-800		U		V
	911-805		U		V
	911-810		U		V
	911-815		U		V
	911-820		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-825	Old Rev.	U	New Rev.	V
	911-830		U		V
	911-835		U		V
	911-840		U		V
	911-845		U		V
	911-850		U		V
	911-855		U		V
	911-860		U		V
	911-865		U		V
	911-870		U		V
	911-875		U		V
	911-880		U		V
	911-885		U		V
	911-890		U		V
	911-895		U		V
	911-8MM		U		V
	911-900		U		V
	911-905		U		V
	911-910		U		V
	911-915		U		V
	911-920		U		V
	911-925		U		V
	911-930		U		V
	911-935		U		V
	911-940		U		V
	911-945		U		V
	911-950		U		V
	911-955		U		V
	911-960		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	911-965	Old Rev.	U	New Rev.	V
	911-970		U		V
	911-975		U		V
	911-980		U		V
	911-985		U		V
	911-990		U		V
	911-995		U		V
	911-9MM		U		V
	912-030		U		V
	912-035		U		V
	912-040		U		V
	912-045		U		V
	912-050		U		V
	912-055		U		V
	912-060		U		V
	912-065		U		V
	912-070		U		V
	912-075		U		V
	912-080		U		V
	912-085		U		V
	912-090		U		V
	912-095		U		V
	912-1.000		U		V
	912-1.040		U		V
	912-1.065		U		V
	912-1.080		U		V
	912-1.100		U		V
	912-1.125		U		V
	912-1.180		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-1.190	Old Rev.	U	New Rev.	V
	912-1.200		U		V
	912-1.250		U		V
	912-10.000		U		V
	912-100		U		V
	912-105		U		V
	912-10MM		U		V
	912-110		U		V
	912-115		U		V
	912-120		U		V
	912-125		U		V
	912-12MM		U		V
	912-130		U		V
	912-135		U		V
	912-13MM		U		V
	912-140		U		V
	912-145		U		V
	912-150		U		V
	912-155		U		V
	912-15MM		U		V
	912-160		U		V
	912-165		U		V
	912-16MM		U		V
	912-170		U		V
	912-175		U		V
	912-17MM		U		V
	912-180		U		V
	912-185		U		V
	912-190		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-195	Old Rev.	U	New Rev.	V
	912-19MM		U		V
	912-1MM		U		V
	912-200		U		V
	912-205		U		V
	912-20MM		U		V
	912-210		U		V
	912-215		U		V
	912-21MM		U		V
	912-220		U		V
	912-225		U		V
	912-22MM		U		V
	912-230		U		V
	912-235		U		V
	912-240		U		V
	912-245		U		V
	912-250		U		V
	912-255		U		V
	912-260		U		V
	912-265		U		V
	912-26MM		U		V
	912-270		U		V
	912-275		U		V
	912-280		U		V
	912-285		U		V
	912-28MM		U		V
	912-290		U		V
	912-295		U		V
	912-2MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-300	Old Rev.	U	New Rev.	V
	912-305		U		V
	912-310		U		V
	912-315		U		V
	912-320		U		V
	912-325		U		V
	912-32MM		U		V
	912-330		U		V
	912-335		U		V
	912-340		U		V
	912-345		U		V
	912-350		U		V
	912-355		U		V
	912-360		U		V
	912-365		U		V
	912-370		U		V
	912-375		U		V
	912-380		U		V
	912-385		U		V
	912-390		U		V
	912-395		U		V
	912-3MM		U		V
	912-400		U		V
	912-405		U		V
	912-410		U		V
	912-412		U		V
	912-415		U		V
	912-420		U		V
	912-425		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-430	Old Rev.	U	New Rev.	V
	912-430 BE		U		V
	912-435		U		V
	912-435 BE		U		V
	912-435 BN		U		V
	912-435 GN		U		V
	912-435 OE		U		V
	912-435 PE		U		V
	912-435 RD		U		V
	912-435 VT		U		V
	912-440		U		V
	912-445		U		V
	912-450		U		V
	912-450 BK		U		V
	912-455		U		V
	912-460		U		V
	912-465		U		V
	912-470		U		V
	912-475		U		V
	912-480		U		V
	912-485		U		V
	912-490		U		V
	912-495		U		V
	912-4MM		U		V
	912-500		U		V
	912-505		U		V
	912-510		U		V
	912-515		U		V
	912-520		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-525	Old Rev.	U	New Rev.	V
	912-530		U		V
	912-535		U		V
	912-540		U		V
	912-545		U		V
	912-550		U		V
	912-555		U		V
	912-560		U		V
	912-565		U		V
	912-570		U		V
	912-575		U		V
	912-580		U		V
	912-585		U		V
	912-590		U		V
	912-595		U		V
	912-5MM		U		V
	912-600		U		V
	912-605		U		V
	912-610		U		V
	912-615		U		V
	912-620		U		V
	912-625		U		V
	912-630		U		V
	912-635		U		V
	912-640		U		V
	912-645		U		V
	912-650		U		V
	912-655		U		V
	912-660		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-660 BK	Old Rev.	U	New Rev.	V
	912-665		U		V
	912-670		U		V
	912-675		U		V
	912-680		U		V
	912-685		U		V
	912-690		U		V
	912-695		U		V
	912-6MM		U		V
	912-700		U		V
	912-705		U		V
	912-710		U		V
	912-715		U		V
	912-720		U		V
	912-725		U		V
	912-730		U		V
	912-735		U		V
	912-740		U		V
	912-745		U		V
	912-750		U		V
	912-755		U		V
	912-760		U		V
	912-765		U		V
	912-770		U		V
	912-775		U		V
	912-780		U		V
	912-785		U		V
	912-790		U		V
	912-795		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-7MM	Old Rev.	U	New Rev.	V
	912-8.000		U		V
	912-800		U		V
	912-805		U		V
	912-810		U		V
	912-815		U		V
	912-820		U		V
	912-825		U		V
	912-830		U		V
	912-835		U		V
	912-840		U		V
	912-845		U		V
	912-850		U		V
	912-855		U		V
	912-860		U		V
	912-865		U		V
	912-870		U		V
	912-875		U		V
	912-880		U		V
	912-885		U		V
	912-890		U		V
	912-895		U		V
	912-8MM		U		V
	912-900		U		V
	912-905		U		V
	912-910		U		V
	912-915		U		V
	912-920		U		V
	912-925		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	912-930	Old Rev.	U	New Rev.	V
	912-935		U		V
	912-940		U		V
	912-945		U		V
	912-950		U		V
	912-955		U		V
	912-960		U		V
	912-965		U		V
	912-970		U		V
	912-975		U		V
	912-980		U		V
	912-985		U		V
	912-990		U		V
	912-995		U		V
	912-9MM		U		V
	913-025		U		V
	913-030		U		V
	913-035		U		V
	913-040		U		V
	913-045		U		V
	913-050		U		V
	913-055		U		V
	913-060		U		V
	913-065		U		V
	913-070		U		V
	913-070 BE		U		V
	913-075		U		V
	913-080		U		V
	913-085		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-090	Old Rev.	U	New Rev.	V
	913-095		U		V
	913-1.000		U		V
	913-1.125		U		V
	913-1.250		U		V
	913-100		U		V
	913-105		U		V
	913-10MM		U		V
	913-110		U		V
	913-115		U		V
	913-11MM		U		V
	913-120		U		V
	913-125		U		V
	913-12MM		U		V
	913-130		U		V
	913-135		U		V
	913-13MM		U		V
	913-140		U		V
	913-145		U		V
	913-14MM		U		V
	913-150		U		V
	913-155		U		V
	913-15MM		U		V
	913-160		U		V
	913-165		U		V
	913-16MM		U		V
	913-170		U		V
	913-175		U		V
	913-17MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-180	Old Rev.	U	New Rev.	V
	913-185		U		V
	913-18MM		U		V
	913-190		U		V
	913-195		U		V
	913-19MM		U		V
	913-1MM		U		V
	913-200		U		V
	913-205		U		V
	913-20MM		U		V
	913-210		U		V
	913-215		U		V
	913-220		U		V
	913-225		U		V
	913-230		U		V
	913-235		U		V
	913-240		U		V
	913-245		U		V
	913-250		U		V
	913-255		U		V
	913-260		U		V
	913-265		U		V
	913-270		U		V
	913-275		U		V
	913-280		U		V
	913-285		U		V
	913-290		U		V
	913-295		U		V
	913-2MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-300	Old Rev.	U	New Rev.	V
	913-305		U		V
	913-310		U		V
	913-315		U		V
	913-320		U		V
	913-325		U		V
	913-330		U		V
	913-335		U		V
	913-340		U		V
	913-345		U		V
	913-350		U		V
	913-355		U		V
	913-360		U		V
	913-365		U		V
	913-370		U		V
	913-375		U		V
	913-380		U		V
	913-385		U		V
	913-390		U		V
	913-395		U		V
	913-3MM		U		V
	913-400		U		V
	913-405		U		V
	913-410		U		V
	913-415		U		V
	913-420		U		V
	913-425		U		V
	913-430		U		V
	913-435		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-437	Old Rev.	U	New Rev.	V
	913-440		U		V
	913-445		U		V
	913-450		U		V
	913-455		U		V
	913-460		U		V
	913-465		U		V
	913-470		U		V
	913-475		U		V
	913-480		U		V
	913-485		U		V
	913-490		U		V
	913-495		U		V
	913-4MM		U		V
	913-500		U		V
	913-505		U		V
	913-510		U		V
	913-515		U		V
	913-520		U		V
	913-525		U		V
	913-530		U		V
	913-535		U		V
	913-540		U		V
	913-545		U		V
	913-550		U		V
	913-555		U		V
	913-560		U		V
	913-565		U		V
	913-570		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-575	Old Rev.	U	New Rev.	V
	913-580		U		V
	913-585		U		V
	913-590		U		V
	913-595		U		V
	913-5MM		U		V
	913-600		U		V
	913-605		U		V
	913-610		U		V
	913-615		U		V
	913-620		U		V
	913-625		U		V
	913-630		U		V
	913-635		U		V
	913-640		U		V
	913-645		U		V
	913-650		U		V
	913-655		U		V
	913-660		U		V
	913-665		U		V
	913-670		U		V
	913-675		U		V
	913-680		U		V
	913-685		U		V
	913-690		U		V
	913-695		U		V
	913-6MM		U		V
	913-700		U		V
	913-705		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-710	Old Rev.	U	New Rev.	V
	913-715		U		V
	913-720		U		V
	913-725		U		V
	913-730		U		V
	913-735		U		V
	913-740		U		V
	913-745		U		V
	913-750		U		V
	913-755		U		V
	913-760		U		V
	913-765		U		V
	913-770		U		V
	913-775		U		V
	913-780		U		V
	913-785		U		V
	913-790		U		V
	913-795		U		V
	913-7MM		U		V
	913-800		U		V
	913-805		U		V
	913-810		U		V
	913-815		U		V
	913-820		U		V
	913-825		U		V
	913-830		U		V
	913-835		U		V
	913-840		U		V
	913-845		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-850	Old Rev.	U	New Rev.	V
	913-855		U		V
	913-860		U		V
	913-865		U		V
	913-870		U		V
	913-875		U		V
	913-880		U		V
	913-885		U		V
	913-890		U		V
	913-895		U		V
	913-8MM		U		V
	913-900		U		V
	913-905		U		V
	913-910		U		V
	913-915		U		V
	913-920		U		V
	913-925		U		V
	913-930		U		V
	913-935		U		V
	913-940		U		V
	913-945		U		V
	913-950		U		V
	913-955		U		V
	913-960		U		V
	913-965		U		V
	913-970		U		V
	913-975		U		V
	913-980		U		V
	913-985		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	913-990	Old Rev.	U	New Rev.	V
	913-995		U		V
	913-9MM		U		V
	938-020		U		V
	938-030		U		V
	938-035		U		V
	938-040		U		V
	938-045		U		V
	938-050		U		V
	938-055		U		V
	938-060		U		V
	938-065		U		V
	938-070		U		V
	938-075		U		V
	938-080		U		V
	938-085		U		V
	938-090		U		V
	938-095		U		V
	938-1.000		U		V
	938-1.100		U		V
	938-1.125		U		V
	938-1.180		U		V
	938-1.250		U		V
	938-100		U		V
	938-105		U		V
	938-10MM		U		V
	938-110		U		V
	938-115		U		V
	938-11MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-120	Old Rev.	U	New Rev.	V
	938-125		U		V
	938-130		U		V
	938-135		U		V
	938-13MM		U		V
	938-140		U		V
	938-145		U		V
	938-14MM		U		V
	938-150		U		V
	938-155		U		V
	938-160		U		V
	938-165		U		V
	938-16MM		U		V
	938-170		U		V
	938-175		U		V
	938-180		U		V
	938-185		U		V
	938-18MM		U		V
	938-190		U		V
	938-195		U		V
	938-19MM		U		V
	938-1MM		U		V
	938-200		U		V
	938-205		U		V
	938-20MM		U		V
	938-210		U		V
	938-215		U		V
	938-220		U		V
	938-220 BK		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-225	Old Rev.	U	New Rev.	V
	938-230		U		V
	938-235		U		V
	938-240		U		V
	938-245		U		V
	938-24MM		U		V
	938-250		U		V
	938-255		U		V
	938-260		U		V
	938-265		U		V
	938-270		U		V
	938-275		U		V
	938-280		U		V
	938-285		U		V
	938-290		U		V
	938-295		U		V
	938-2MM		U		V
	938-300		U		V
	938-305		U		V
	938-310		U		V
	938-315		U		V
	938-320		U		V
	938-325		U		V
	938-32MM		U		V
	938-330		U		V
	938-335		U		V
	938-340		U		V
	938-345		U		V
	938-350		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-355	Old Rev.	U	New Rev.	V
	938-360		U		V
	938-365		U		V
	938-370		U		V
	938-375		U		V
	938-380		U		V
	938-385		U		V
	938-390		U		V
	938-395		U		V
	938-3MM		U		V
	938-400		U		V
	938-405		U		V
	938-410		U		V
	938-415		U		V
	938-420		U		V
	938-425		U		V
	938-430		U		V
	938-435		U		V
	938-440		U		V
	938-450		U		V
	938-455		U		V
	938-460		U		V
	938-465		U		V
	938-470		U		V
	938-475		U		V
	938-480		U		V
	938-485		U		V
	938-490		U		V
	938-495		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-4MM	Old Rev.	U	New Rev.	V
	938-500		U		V
	938-505		U		V
	938-510		U		V
	938-515		U		V
	938-520		U		V
	938-525		U		V
	938-530		U		V
	938-535		U		V
	938-540		U		V
	938-545		U		V
	938-550		U		V
	938-555		U		V
	938-560		U		V
	938-565		U		V
	938-570		U		V
	938-575		U		V
	938-580		U		V
	938-585		U		V
	938-590		U		V
	938-595		U		V
	938-5MM		U		V
	938-600		U		V
	938-605		U		V
	938-610		U		V
	938-615		U		V
	938-620		U		V
	938-625		U		V
	938-630		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-635	Old Rev.	U	New Rev.	V
	938-640		U		V
	938-645		U		V
	938-650		U		V
	938-655		U		V
	938-660		U		V
	938-665		U		V
	938-670		U		V
	938-675		U		V
	938-680		U		V
	938-685		U		V
	938-690		U		V
	938-695		U		V
	938-6MM		U		V
	938-700		U		V
	938-705		U		V
	938-710		U		V
	938-715		U		V
	938-720		U		V
	938-725		U		V
	938-730		U		V
	938-735		U		V
	938-740		U		V
	938-745		U		V
	938-750		U		V
	938-755		U		V
	938-760		U		V
	938-765		U		V
	938-770		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-775	Old Rev.	U	New Rev.	V
	938-780		U		V
	938-785		U		V
	938-790		U		V
	938-795		U		V
	938-7MM		U		V
	938-800		U		V
	938-805		U		V
	938-810		U		V
	938-815		U		V
	938-820		U		V
	938-825		U		V
	938-830		U		V
	938-835		U		V
	938-840		U		V
	938-845		U		V
	938-850		U		V
	938-855		U		V
	938-860		U		V
	938-865		U		V
	938-870		U		V
	938-875		U		V
	938-880		U		V
	938-885		U		V
	938-890		U		V
	938-895		U		V
	938-8MM		U		V
	938-900		U		V
	938-905		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	938-910	Old Rev.	U	New Rev.	V
	938-915		U		V
	938-920		U		V
	938-925		U		V
	938-930		U		V
	938-935		U		V
	938-940		U		V
	938-945		U		V
	938-950		U		V
	938-955		U		V
	938-960		U		V
	938-965		U		V
	938-970		U		V
	938-975		U		V
	938-980		U		V
	938-985		U		V
	938-990		U		V
	938-995		U		V
	938-9MM		U		V
	940-030		U		V
	940-035		U		V
	940-040		U		V
	940-045		U		V
	940-050		U		V
	940-055		U		V
	940-060		U		V
	940-065		U		V
	940-070		U		V
	940-075		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-080	Old Rev.	U	New Rev.	V
	940-085		U		V
	940-090		U		V
	940-095		U		V
	940-1.000		U		V
	940-1.005		U		V
	940-1.010		U		V
	940-1.015		U		V
	940-1.020		U		V
	940-1.025		U		V
	940-1.030		U		V
	940-1.035		U		V
	940-1.040		U		V
	940-1.045		U		V
	940-1.050		U		V
	940-1.055		U		V
	940-1.060		U		V
	940-1.065		U		V
	940-1.070		U		V
	940-1.075		U		V
	940-1.080		U		V
	940-1.085		U		V
	940-1.090		U		V
	940-1.095		U		V
	940-1.100		U		V
	940-1.105		U		V
	940-1.110		U		V
	940-1.115		U		V
	940-1.120		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-1.125	Old Rev.	U	New Rev.	V
	940-1.130		U		V
	940-1.135		U		V
	940-1.140		U		V
	940-1.145		U		V
	940-1.150		U		V
	940-1.155		U		V
	940-1.160		U		V
	940-1.165		U		V
	940-1.170		U		V
	940-1.175		U		V
	940-1.180		U		V
	940-1.185		U		V
	940-1.190		U		V
	940-1.195		U		V
	940-1.200		U		V
	940-1.205		U		V
	940-1.210		U		V
	940-1.215		U		V
	940-1.220		U		V
	940-1.225		U		V
	940-1.230		U		V
	940-1.235		U		V
	940-1.240		U		V
	940-1.245		U		V
	940-1.250		U		V
	940-100		U		V
	940-105		U		V
	940-10MM		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-110	Old Rev.	U	New Rev.	V
	940-115		U		V
	940-11MM		U		V
	940-120		U		V
	940-125		U		V
	940-12MM		U		V
	940-130		U		V
	940-135		U		V
	940-13MM		U		V
	940-140		U		V
	940-145		U		V
	940-150		U		V
	940-155		U		V
	940-15MM		U		V
	940-160		U		V
	940-165		U		V
	940-170		U		V
	940-175		U		V
	940-180		U		V
	940-185		U		V
	940-18MM		U		V
	940-190		U		V
	940-195		U		V
	940-19MM		U		V
	940-1MM		U		V
	940-200		U		V
	940-205		U		V
	940-20MM		U		V
	940-210		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-215	Old Rev.	U	New Rev.	V
	940-21MM		U		V
	940-220		U		V
	940-225		U		V
	940-22MM		U		V
	940-230		U		V
	940-235		U		V
	940-23MM		U		V
	940-240		U		V
	940-245		U		V
	940-24MM		U		V
	940-250		U		V
	940-255		U		V
	940-25MM		U		V
	940-260		U		V
	940-265		U		V
	940-270		U		V
	940-275		U		V
	940-280		U		V
	940-285		U		V
	940-290		U		V
	940-295		U		V
	940-2MM		U		V
	940-300		U		V
	940-305		U		V
	940-310		U		V
	940-315		U		V
	940-320		U		V
	940-325		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-330	Old Rev.	U	New Rev.	V
	940-335		U		V
	940-340		U		V
	940-345		U		V
	940-350		U		V
	940-355		U		V
	940-360		U		V
	940-365		U		V
	940-370		U		V
	940-375		U		V
	940-380		U		V
	940-385		U		V
	940-390		U		V
	940-395		U		V
	940-3MM		U		V
	940-400		U		V
	940-405		U		V
	940-410		U		V
	940-415		U		V
	940-420		U		V
	940-425		U		V
	940-430		U		V
	940-435		U		V
	940-440		U		V
	940-445		U		V
	940-450		U		V
	940-455		U		V
	940-460		U		V
	940-465		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-470	Old Rev.	U	New Rev.	V
	940-475		U		V
	940-480		U		V
	940-485		U		V
	940-490		U		V
	940-495		U		V
	940-4MM		U		V
	940-500		U		V
	940-505		U		V
	940-510		U		V
	940-515		U		V
	940-520		U		V
	940-525		U		V
	940-530		U		V
	940-535		U		V
	940-540		U		V
	940-545		U		V
	940-550		U		V
	940-555		U		V
	940-560		U		V
	940-565		U		V
	940-570		U		V
	940-575		U		V
	940-580		U		V
	940-585		U		V
	940-590		U		V
	940-595		U		V
	940-5MM		U		V
	940-600		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-605	Old Rev.	U	New Rev.	V
	940-610		U		V
	940-615		U		V
	940-620		U		V
	940-625		U		V
	940-630		U		V
	940-635		U		V
	940-640		U		V
	940-645		U		V
	940-650		U		V
	940-655		U		V
	940-660		U		V
	940-665		U		V
	940-670		U		V
	940-675		U		V
	940-680		U		V
	940-685		U		V
	940-690		U		V
	940-695		U		V
	940-6MM		U		V
	940-700		U		V
	940-705		U		V
	940-710		U		V
	940-715		U		V
	940-720		U		V
	940-725		U		V
	940-730		U		V
	940-735		U		V
	940-740		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-745	Old Rev.	U	New Rev.	V
	940-750		U		V
	940-755		U		V
	940-760		U		V
	940-765		U		V
	940-770		U		V
	940-775		U		V
	940-780		U		V
	940-785		U		V
	940-790		U		V
	940-795		U		V
	940-7MM		U		V
	940-800		U		V
	940-805		U		V
	940-810		U		V
	940-815		U		V
	940-820		U		V
	940-825		U		V
	940-830		U		V
	940-835		U		V
	940-840		U		V
	940-845		U		V
	940-850		U		V
	940-855		U		V
	940-860		U		V
	940-865		U		V
	940-870		U		V
	940-875		U		V
	940-880		U		V

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Parts Affected	940-885	Old Rev.	U	New Rev.	V
	940-890		U		V
	940-895		U		V
	940-8MM		U		V
	940-900		U		V
	940-905		U		V
	940-910		U		V
	940-915		U		V
	940-920		U		V
	940-925		U		V
	940-930		U		V
	940-935		U		V
	940-940		U		V
	940-945		U		V
	940-950		U		V
	940-955		U		V
	940-960		U		V
	940-965		U		V
	940-970		U		V
	940-975		U		V
	940-980		U		V
	940-985		U		V
	940-990		U		V
	940-995		U		V
	940-9MM		U		V

Change Will Affect:

This change will affect the product specifications.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1112

Issue Date: 1/16/2026

Description of Change:

Product series 939-XXX was inadvertently removed from the drawing in a previous revision and has now been added back.

Effective Date of Change: January 16, 2026

Reason for Change: Inaccuracy in the datasheet.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122