

Product Advisory

Issue Date: May 22, 2023

Change Type:

Packaging update for specific DCSG NIC adapters.

Parts Affected:

BRM Part Number	Family	Channel	New Revision Number
BCM957508-N2100G	Thor	Channel	29
BCM957504-N1100G	N1100G	Channel	29
BCM957416N4160C	N210GBT	Channel	18
BCM957414A4141DDLT	Thomson3 LP	Dell	5
BCM957414A4141DDT	Thomson3	Dell	5
BCM957416A4160DLPC	Davy LP	Dell	15
BCM957416A4160DC	Davy	Dell	14
BCM957412A4120DLPC	Hopkins LP	Dell	20
BCM957412A4120DC	Hopkins	Dell	19
BCM95719N1905HC	Bubbles	HPE	20
BCM957416N4160HC	Beehive	HPE	20
BCM957412N4120HC	Blackberry	HPE	18
BCM957414A4142HC	Blockbuster	HPE	11
BCM957416A4162HC	Bishop	HPE	10
BCM957412A4121HC	Blaze	HPE	10

Description and Extent of Change:

The bulk pack count is increasing from ten to twenty per outer carton. The Minimum Order Quantity (MOQ) will change from ten to twenty.

Reasons for Change:

The change is being implemented to further enhance supply continuity.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The part number revision will be incremented to track this update. Product shipments will start after June 30, 2023.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.