

Product Change Notice

Issue Date: 27-April-2023

Change Description:

Addition of TSMC Fab16 Foundry source

Parts Affected:

BCM6710A1KFFBG

BCM6705A1KFFBG

BCM6705A1KFFBG-X

Description and Extent of Change:

Addition of TSMC Fab16 Foundry source

Reasons for Change:

Adding second source option for supply chain resiliency

Effect of Change on Fit, Form, Function, Quality, or Reliability:

All electrical specifications and physical characteristics remain within the datasheet limits. Appropriate electrical characterization and reliability qualifications have been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:

Product shipments using this change will begin January 2024

Qualification Data:

Qualification data will be available after 09/15/2023

Samples will be available upon request from 07/15/2023

Software / Firmware Update:

As with all changes please check with your Broadcom FAE to determine if any software or firmware updates are required as a result of this change.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.