

PCN-265115

Product Change Notice

Issue Date: 30-July-2023

Change Description:

Introduction of new LED die

Parts Affected:

| |
|-----------------|
| ASM6-SL91-NST0H |
| ASM6-SLD1-NST0H |
| ASM6-SW91-NMQBH |
| ASM6-SW91-NMQCH |
| ASM6-SW91-NNRDH |
| ASM6-SW91-NNRKH |
| ASM6-SW91-NPREH |
| ASM6-SW91-NPRFH |
| ASM6-SW91-NPRHH |
| ASM6-SWD1-NPSBH |
| ASM6-SWD1-NPSCH |
| ASM6-SWD1-NQTDH |
| ASM6-SWD1-NQTEH |
| ASM6-SWD1-NQTFH |
| ASM6-SWD1-NQTHH |
| ASM6-SWD1-NQTKH |

Description and Extent of Change:

New die has been qualified as a replacement to existing LED die.

Reasons for Change:

Discontinuation of current LED die supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change in fit, form, function, quality or reliability of the final product.

Effective Date of Change:

Part with the above change will commence 90 days after the issuance date above.

1. Broadcom will continue to ship parts from both LED die sources after the implementation date until the inventory of the existing LED die source is fully depleted.
2. The shipment may contain parts with either the existing or new die source after the implementation date.

Qualification Data:

Qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements.

Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.