



PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015
PCN: PCN LEDIL 109 a, b, c, d

Subject: PCN 109.b – Change of assembly instructions

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has updated C13806_MIRELLA-XW-PF assembly instructions to include glue for fastening.

Time line: This change is valid immediately

Affected products: C13806_MIRELLA-XW-PF

Included in assemblies: CN14209_MIRELLA-XW-PF-VER013
CN14211_MIRELLA-XW-CL-PF-VER013
CN14212_MIRELLA-XW-DL-PF-VER013
CN14568_MIRELLA-XW-DL-PF
CN14572_MIRELLA-XW-CL-PF
CN14576_MIRELLA-XW-RZL-PF
CN14755_MIRELLA-XW-PF-XTM

Changes: C13806_MIRELLA-XW-PF assembly instructions has been updated to include glue for fastening. This change does not have effect on optical performance of the products.

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com