

NO: REL-120	PRODUCT: Multiple Low Signal Relay Families
DATE: December 2009	TYPE: Product Discontinuation

Multiple Low Signal Relay Series to be DISCONTINUED

Due to low order volumes and new sales strategies, Omron is **discontinuing** the following series of Low Signal Relays.

G6H-2F (SMD type) series Low Signal relays made by OER

- Discontinuation Notice of Surface Mount-Relay
- Reason for Product Discontinuation: Decreasing Orders
- Discontinuation date: The end of September, 2010
- Date of the Last Order 06/29/2010
- Recommended Replacement: G6K Series or G6S Series (Conditional Replacement)

G6H series Low Signal relays made by OER

- Discontinuation Notice of G6H Relay
- Reason for Product Discontinuation: Decreasing Orders
- Discontinuation date: The end of September, 2010
- Date of the Last Order 06/29/2010
- Recommended Replacement: G6K Series or G6S Series (Conditional Replacement)

G6A-4 series Low Signal relays made by OER

- Discontinuation Notice of G6A-4 Relay
- Reason for Product Discontinuation: Decreasing Orders
- Discontinuation date: The end of September, 2010
- Date of the Last Order 06/29/2010
- Recommended Replacement: G6A-2 Series (2 pieces) (Conditional Replacement)

G5A series Low Signal relays made by OER

- Discontinuation Notice of G5A Relay
- Reason for Product Discontinuation: Decreasing Orders
- Discontinuation date: The end of September, 2010
- Date of the Last Order 06/29/2010
- Recommended Replacement: G6S Series (Conditional Replacement)

Please contact the [Product Manager](#) for questions and technical support pertaining to these discontinuations.