



CUSTOMER SERVICE
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000753

DATE: 1-NOV-12

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX9110ESA	MAX9110ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9110ESA-T	MAX9110ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9112EKA-T	MAX9112EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9112ESA	MAX9112ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9112ESA-T	MAX9112ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113ASA+	MAX9113ASA/V+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113EKA	MAX9113EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113EKA/GH8-T	MAX9113EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113EKA-T	MAX9113EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113ESA	MAX9113ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113ESA+B4D	MAX9113ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9113ESA-T	MAX9113ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9121EUE	MAX9121EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9121EUE-T	MAX9121EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9122EUE	MAX9122EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9122EUE-T	MAX9122EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9122EUE-TG077	MAX9122EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9123EUE	MAX9123EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9123EUE+G60	MAX9123EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9123EUE+TG60	MAX9123EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9123EUE-T	MAX9123EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9124ESE	MAX9124ESE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9124ESE-T	MAX9124ESE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9125ESE	MAX9125ESE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9125ESE-T	MAX9125ESE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 3-DEC-2012

Discontinuance	MAX9129EUE	MAX9129EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9129EUE-T	MAX9129EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9130EXT	MAX9130EXT+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9130EXT-T	MAX9130EXT+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9150EUI	MAX9150EUI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9152ESE	MAX9152ESE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9152ESE-T	MAX9152ESE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9152EUE	MAX9152EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9152EUE-T	MAX9152EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9153EUI	MAX9153EUI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9153EUI-T	MAX9153EUI+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9154EUI	MAX9154EUI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9154EUI-T	MAX9154EUI+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9155EXT	MAX9155EXT+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9155EXT-T	MAX9155EXT+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9157EHJ	MAX9157EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9157EHJ-T	MAX9157EHJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9160EUI	MAX9160EUI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9160EUI-T	MAX9160EUI+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9169EUE	MAX9169EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9169EUE-T	MAX9169EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9171EKA-T	MAX9171EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9171ESA	MAX9171ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9172EKA	MAX9172EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9172EKA-T	MAX9172EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9172ESA	MAX9172ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9172ESA-T	MAX9172ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9173ESE	MAX9173ESE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9173ESE-T	MAX9173ESE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9173EUE	MAX9173EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9173EUE-T	MAX9173EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9174EUB	MAX9174EUB+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9174EUB-T	MAX9174EUB+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9175ETB	MAX9175EUB+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9175EUB	MAX9175EUB+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9175EUB-T	MAX9175EUB+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9176EUB	MAX9176EUB+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX9176EUB-T	MAX9176EUB+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9179EUE	MAX9179EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9179EUE-T	MAX9179EUE+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9180EXT	MAX9180EXT+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9180EXT-T	MAX9180EXT+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9310AEUP	MAX9310AEUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9310AEUP-T	MAX9310AEUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9310EUP	MAX9310EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9310EUP-T	MAX9310EUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9313EGJ-G068	MAX9313EGJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9315EUP	MAX9315EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9315EUP-T	MAX9315EUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320AEKA	MAX9320AEKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320BESA	MAX9320BESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320BEUA	MAX9320BEUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320BEUA-T	MAX9320BEUA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320EKA	MAX9320EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320EKA-T	MAX9320EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320ESA/GG8	MAX9320ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320EUA	MAX9320EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9320EUA-T	MAX9320EUA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9321AEKA	MAX9321AEKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9321BESA	MAX9321BESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9321BESA-	MAX9321BESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9321EKA	MAX9321EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9321EKA-T	MAX9321EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9323EUP	MAX9323EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9323EUP-G05	MAX9323EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9323EUP-TG05	MAX9323EUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9323EUP-TG077	MAX9323EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9324EUP	MAX9324EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9324EUP-T	MAX9324EUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9325EQI	MAX9325EQI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9325EQI-C01026	MAX9325EQI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9360EKA	MAX9360EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9360EKA-T	MAX9360EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9370ESA	MAX9370ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX9370ESA-T	MAX9370ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9371EKA	MAX9371EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9371EKA-T	MAX9371EKA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9371ESA	MAX9371ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9371ESA-T	MAX9371ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9372EKA	MAX9372EKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9372EUA	MAX9372EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9372EUA+TG48	MAX9372EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9372EUA-G48	MAX9372EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9372EUA-T	MAX9372EUA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9374AEKA	MAX9374AEKA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9378EUA	MAX9378EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9378EUA-T	MAX9378EUA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9381ESA	MAX9381ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9381ESA-T	MAX9381ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9381EUA	MAX9381EUA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9381EUA-T	MAX9381EUA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9382ESA	MAX9382ESA+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9382ESA-T	MAX9382ESA+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9384EWP	MAX9384EWP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9384EWP/GG8	MAX9384EWP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9384EWP/GH9	MAX9384EWP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9384EWP/GH9-T	MAX9384EWP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9386EUP	MAX9386EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9387EUG	MAX9387EUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9387EUG-T	MAX9387EUG+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9388EUP	MAX9388EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9388EUP-T	MAX9388EUP+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9389EHJ	MAX9389EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9389EHJ-T	MAX9389EHJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9390EHJ	MAX9390EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9390EHJ-T	MAX9390EHJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9392EHJ	MAX9392EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9392EHJ+TG52	MAX9392EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9392EHJ-T	MAX9392EHJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9393EHJ	MAX9393EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9393EHJ-T	MAX9393EHJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX9393ETJ	MAX9393ETJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9393ETJ-T	MAX9393ETJ+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9394EHJ	MAX9394EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9395EHJ	MAX9395EHJ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX9406ETM	MAX9406ETM+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211AIPL	ICM7211AIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211AIQH	ICM7211AIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211AIQH-G0034	ICM7211AIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211AMIPL	ICM7211AMIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211IQH	ICM7211IQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7211MIQH	ICM7211MIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7212AIPL	ICM7212AIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7212AMIPL	ICM7212AMIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7212AMIQH	ICM7212AMIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7212AMIQH-D	ICM7212AMIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218AIP	ICM7218AIP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218AIQ	ICM7218AIQ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218BIP	ICM7218BIP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218BIQ	ICM7218BIQ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218CIQ	ICM7218CIQ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218DIP	ICM7218DIP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7218DIQ	ICM7218DIQ+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7224IPL	ICM7224IPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7224IQH-D	ICM7224IQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7224IQH-T	ICM7224IQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	ICM7225IQH	ICM7225IQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1452AAE	MAX1452AAE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1452ATG	MAX1452ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1452CAE	MAX1452CAE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1452EAE	MAX1452EAE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1455AUE	MAX1455AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX1464AAI	MAX1464AAI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6920AWP	MAX6920AWP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6921AQI	MAX6921AQI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6921AUI	MAX6921AUI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6921AWI	MAX6921AWI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6922AQH	MAX6922AQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX6934AQH	MAX6934AQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6950CEE	MAX6950CEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6950EEE	MAX6950EEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6951CEE	MAX6951CEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6951EEE	MAX6951EEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6952EAX	MAX6952EAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6952EPL	MAX6952EPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6953EAX	MAX6953EAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6953EPL	MAX6953EPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6954AAX	MAX6954AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6955AAX	MAX6955AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6956AAI	MAX6956AAI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6956AAX	MAX6956AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6957AAI	MAX6957AAI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6957AAX	MAX6957AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6957ANI	MAX6957ANI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6957ATL	MAX6957ATL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6958AAEE	MAX6958AAEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6958AAPE	MAX6958AAPE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6958BAEE	MAX6958BAEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6959AAEE	MAX6959AAEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6959AAPE	MAX6959AAPE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6959BAEE	MAX6959BAEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6960AMH	MAX6960AMH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6960ATH	MAX6960ATH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6964AEG	MAX6964AEG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6964ATG	MAX6964ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6965AEE	MAX6965AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6965ATE	MAX6965ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6966AEE	MAX6966AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6966ATE	MAX6966ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6967AEE	MAX6967AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6968AAE	MAX6968AAE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6968APE	MAX6968APE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6968AUE	MAX6968AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6969ANG	MAX6969ANG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6969AUG	MAX6969AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX6969AWG	MAX6969AWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6970AAE	MAX6970AAE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6970AUE	MAX6970AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6971AUG	MAX6971AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6977AUE	MAX6977AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6978AUE	MAX6978AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX6979AUG	MAX6979AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7219CNG	MAX7219CNG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7219CWG	MAX7219CWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7219ENG	MAX7219ENG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7219EWG	MAX7219EWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7221CNG	MAX7221CNG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7221CWG	MAX7221CWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7221ENG	MAX7221ENG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7221EWG	MAX7221EWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7231BFIPL	MAX7231BFIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7231BFIQH	MAX7231BFIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7231CFIPL	MAX7231CFIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7232CFIQH	MAX7232CFIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7233BFIPL	MAX7233BFIPL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7233BFIQH	MAX7233BFIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7234BFIQH	MAX7234BFIQH+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7300AAI	MAX7300AAI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7300AAX	MAX7300AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7300ANI	MAX7300ANI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7300ATL	MAX7300ATL+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7301AAI	MAX7301AAI+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7301AAX	MAX7301AAX+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7310AEE	MAX7310AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7310ATE	MAX7310ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7310AUE	MAX7310AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7311AAG	MAX7311AAG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7311ATG	MAX7311ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7311AUG	MAX7311AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7311AWG	MAX7311AWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7312AAG	MAX7312AAG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7312ATG	MAX7312ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX7312AUG	MAX7312AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7312AWG	MAX7312AWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7313AEG	MAX7313AEG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7313ATG	MAX7313ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7315AEE	MAX7315AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7315ATE	MAX7315ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7315AUE	MAX7315AUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7316AEE	MAX7316AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7316ATE	MAX7316ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7317AEE	MAX7317AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7317ATE	MAX7317ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7318AAG	MAX7318AAG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7318ATG	MAX7318ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7318AUG	MAX7318AUG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7318AWG	MAX7318AWG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7319AEE	MAX7319AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7319ATE	MAX7319ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7320AEE	MAX7320AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7320ATE	MAX7320ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7321AEE	MAX7321AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7321ATE	MAX7321ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7322AEE	MAX7322AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7322ATE	MAX7322ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7323AEE	MAX7323AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7323ATE	MAX7323ATE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7324AEG	MAX7324AEG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7324ATG	MAX7324ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7325AEG	MAX7325AEG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7325ATG	MAX7325ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7326ATG	MAX7326ATG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7328AAP	MAX7328AAP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7329AWE	MAX7329AWE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7347AEE	MAX7347AEE+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7348AEP	MAX7348AEP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7349AEG	MAX7349AEG+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7367EUP	MAX7367EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7368EUE	MAX7368EUE+	4-May-2013	1-Nov-2014	Part has lead-free replacement

Discontinuance	MAX7369EUP	MAX7369EUP+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR105	MAX7375AXR105+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR105-T	MAX7375AXR105+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR185	MAX7375AXR185+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR365	MAX7375AXR365+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR405	MAX7375AXR405+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR405-T	MAX7375AXR405+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR425	MAX7375AXR425+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR805	MAX7375AXR805+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7375AXR805-T	MAX7375AXR805+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7377AXRD	MAX7377AXRD+	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX7377AXRD-T	MAX7377AXRD+T	4-May-2013	1-Nov-2014	Part has lead-free replacement
Discontinuance	MAX2091EVKIT	MAX2091EVKIT#	4-May-2013	1-Nov-2014	Evaluation kit is no longer supported
Discontinuance	MAX2092DEVBRD	MAX2092EVKIT#	4-May-2013	1-Nov-2014	Evaluation kit is no longer supported
Discontinuance	806-0489-21+	806-0489-22+	4-May-2013	1-Nov-2014	Part can no longer be manufactured
Discontinuance	806-0489-21+T	806-0489-22+T	4-May-2013	1-Nov-2014	Part can no longer be manufactured
Discontinuance	MAX19793DEVBRD	MAX19793EVKIT#	4-May-2013	1-Nov-2014	Evaluation kit is no longer supported
Discontinuance	MAX17512ATP+	NONE	4-May-2013	1-Nov-2014	Part can no longer be manufactured
Discontinuance	MAX17512ATP+T	NONE	4-May-2013	1-Nov-2014	Part can no longer be manufactured
Discontinuance	MAX17512EVKIT#	NONE	4-May-2013	1-Nov-2014	Evaluation kit is no longer supported
Discontinuance	MAX17806EVKIT+	MAX17806EVKIT#	4-May-2013	1-Nov-2014	Evaluation kit is no longer supported