



## Product Change Notification: DSNO-22UTRQ751

---

**Date:**

11-Mar-2026

**Product Category:**

32-Bit Microcontrollers

**Notification Subject:**

eSign # EOL0000639: End of Life (EOL) of ATSAMC21J18A-MZ, ATSAMC21J17A-MZ, ATSAMC20J16A-MZ, ATSAMC21J18A-MZ-SL3, ATSAMC21J18A-MZT, ATSAMC21J16A-MZT, ATSAMC21J18A-MZTVAO, ATSAMC20J17A-MZVAO, ATSAMC21J17A-MZTVAO, ATSAMC21J16A-MZTVAO, ATSAMC21J15A-MZTVAO, ATSAMC20J16A-MZTVAO and ATSAMC20J17A-MZTVAO catalog part numbers (CPN).

**Affected CPNs:**

[DSNO-22UTRQ751\\_Affected\\_CPN\\_03112026.pdf](#)

[DSNO-22UTRQ751\\_Affected\\_CPN\\_03112026.csv](#)

**PCN Status:** End of Life (EOL) Notification

**Microchip Parts Affected:**

Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**EOL Description:** The ATSAMC21J18A-MZ, ATSAMC21J17A-MZ, ATSAMC20J16A-MZ, ATSAMC21J18A-MZ-SL3, ATSAMC21J18A-MZT, ATSAMC21J16A-MZT, ATSAMC21J18A-MZTVAO, ATSAMC20J17A-MZVAO, ATSAMC21J17A-MZTVAO, ATSAMC21J16A-MZTVAO, ATSAMC21J15A-MZTVAO, ATSAMC20J16A-MZTVAO and ATSAMC20J17A-MZTVAO catalog part numbers (CPN) will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after January 31, 2027. Please review the attached parts affected list below for the details about replacement parts if applicable.

**Note:** If replacement parts are not listed in the attached list please contact your [Local Sales Representative](#)

**Reason for EOL:** No longer have manufacturing support for the CPN listed in the attachment.

**Estimated Effective Dates:** Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

**Last Date for Bookings (LTB):** 31 July 2026

**Last Date for Shipments LTS:** 31 January 2027

**Revision History:** February 26, 2026: Issued EOL notification.

March 11, 2026: Re-issued EOL notification to update "EOL Description" of the EOL letter.

**Note:** The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable product.

### **Attachments:**

[PCN\\_DSNO-22UTRQ751\\_Suggested Replacement.pdf](#)

[PCN\\_DSNO-22UTRQ751\\_Suggested Replacement.xlsx](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.