



## Product Change Notification: MAAN-02HMPG886

---

### Date:

08-Jul-2025

### Product Category:

Clock And Timing - Clock And Data Distribution, Clock And Timing - Clock Generation, Clock And Timing - Oscillators

### Notification Subject:

eSign #EOL0000534: End of Life (EOL) of selected MX55/57, MX575ABC, PL102-10, PL123-02N, PL123-09, PL135-67, PL500-17, PL560-47, PL565-37, PL610C2, PL611, PL611-01, PL613, PL663-18, PL671, PL671-25, PL902 and SM803 device families.

### Affected CPNs:

[MAAN-02HMPG886\\_Affected\\_CPN\\_07082025.pdf](#)

[MAAN-02HMPG886\\_Affected\\_CPN\\_07082025.csv](#)

### Notification Text:

#### PCN Status:

End of Life (EOL) Notification

#### Microchip Parts Affected:

Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN\_#\_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

#### EOL Description:

The MX55/57, MX575ABC, PL102-10, PL123-02N, PL123-09, PL135-67, PL500-17, PL560-47, PL565-37, PL610C2, PL611, PL611-01, PL613, PL663-18, PL671, PL671-25, PL902 and SM803 device families will be moving to End of Life (EOL) status effective today. These products will no longer be offered after the date listed in the attached Affected CPN. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your Local Sales Representative

**Reason for EOL:**

No longer have manufacturing support for the CPN listed in the attachment.

**Estimated Effective Dates:**

Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): Please refer to PCN\_#\_Suggested\_Replacements (excel file) for the list of LTB dates identified per catalog part number.

Last date for shipments (LTS): Please refer to PCN\_#\_Suggested\_Replacements (excel file) for the list of LTS dates identified per catalog part number.

**Revision History:**

July 08, 2025: Issued EOL notification.

**Attachments:**

**[PCN MAAN-02HMPG886 Suggested Replacements.pdf](#)**  
**[PCN MAAN-02HMPG886 Suggested Replacements.xlsx](#)**

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.