



Product Change Notification: SYST-06MESY573

Date:

08-Sep-2026

Product Category:

32-Bit Microcontrollers

Notification Subject:

PIC32CM MC00 Family Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-06MESY573_Affected_CPN_09082026.pdf](#)

[SYST-06MESY573_Affected_CPN_09082026.csv](#)

Notification Text:

SYST-06MESY573

Microchip has released a new Document for the PIC32CM MC00 Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC32CM MC00 Family Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change:

Added a note to the OSC48M Start-Up errata.

Impacts to Data Sheet: None

Reason for Change: To improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 07 Sep 2026

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

PIC32CM MC00 Family Silicon Errata and Data Sheet Clarifications

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from