



## Product Change Notification: SYST-15DSMJ238

### Date:

19-Nov-2024

### Product Category:

Clock and Timing - Clock and Data Distribution

### Notification Subject:

Data Sheet - ZL40294 - 20-Output DB2000QL Buffer with Ultra-Low Additive Jitter

### Affected CPNs:

**SYST-15DSMJ238\_Affected\_CPN\_11192024.pdf**

**SYST-15DSMJ238\_Affected\_CPN\_11192024.csv**

### Notification Text:

SYST-15DSMJ238

Microchip has released a new Datasheet for the ZL40294 - 20-Output DB2000QL Buffer with Ultra-Low Additive Jitter of devices. If you are using one of these devices please read the document located at **ZL40294 - 20-Output DB2000QL Buffer with Ultra-Low Additive Jitter**.

**Notification Status:** Final

### Description of Change:

Updated Media Type options and Examples in the Product Identification System section.

**Reason for Change:** To Improve Productivity.

**Impacts to Data Sheet:** See above details.

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 19 Nov 2024

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## Attachments:

### **ZL40294 - 20-Output DB2000QL Buffer with Ultra-Low Additive Jitter**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from