



Product Change Notification / SYST-18YIFQ586

Date:

20-Apr-2023

Product Category:

General Purpose FPGAs, System On Chip FPGAs

PCN Type:

Document Change

Notification Subject:

ERRATA - SmartFusion®2 Device Errata

Affected CPNs:

[SYST-18YIFQ586_Affected_CPN_04202023.pdf](#)
[SYST-18YIFQ586_Affected_CPN_04202023.csv](#)

Notification Text:

SYST-18YIFQ586

Microchip has released a new Errata for the SmartFusion®2 Device Errata of devices. If you are using one of these devices please read the document located at [SmartFusion®2 Device Errata](#).

Notification Status: Final

Description of Change: Added 1.25. Avoid eNVM Page Lock and Unlock if Code is Being Executed from eNVM both in Release and Debug Mode

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 20 Apr 2023

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

SmartFusion®2 Device Errata

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.