



Product Change Notification - SYST-23DUUM411

Date:

25 Oct 2019

Product Category:

8-bit Microcontrollers

Affected CPNs:**Notification subject:**

ERRATA - ATtiny1614 Silicon Errata and Data Sheet Clarification

Notification text:

SYST-23DUUM411

Microchip has released a new Product Documents for the ATtiny1614 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [ATtiny1614 Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Updated document template. 2) The ADC errata, ADC Functionality Cannot be Ensured with ADCCLK Above 1.5 MHz for All Conditions, has been split into two separate erratas and rewritten. 3) Added clarifications to ADC and PTC electrical characteristics.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 25 Oct 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[ATtiny1614 Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.